

**Douglas County Surveyor's Record of  
Government Corners Renewed**

28 T.S. 3

R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

For: Seneca Jones Timber Co.  
M 138-46 and C.S. File 65/37-14 A thru E  
Greg Lang - July 2001

Cor. Secs. 7, 8, 17, & 18

178

Found - Byron Brass Cap properly marked. (ren. #7)  
Fd. accessories according to the 1975 renewal by  
Langlitz (Ren. #132)

Set - Aluminum post by the corner.  
I set spikes in the following trees:  
29" Cedar bears N.35½°E., 29.5 ft. (placed new tag)  
21½" D.Fir bears S.11½°E., 5.4 ft.  
18" D.Fir bears S.33½°W., 10.4 ft.  
14" W.Fir bears N.84¾°W., 12.4 ft. (placed new tag)

Note - Less than 100' N'ly of North Myrtle Rd. just before  
the current end of pavement. C.S. File 65/37-14D

1/4 Cor. Secs. 7 & 8

179

Found - Orig. Hemlock BT (now 29"), good face, we cut in & fd  
scribing approx. 6" from the core of the tree.  
Orig. Cedar not found.

Set - 5/8"x36" iron rod with a 2½" alum. cap. This monument  
was set N.21°W., 12.54 ft. or 19 lks. (the orig.  
rec. bearing & dist.) from the 1910 Hemlock  
described above. Also set an alum. post  
alongside the corner.  
15½" Hemlock bears N.35½°E., 51.0 ft. scribed "¼ S8"  
"BT"  
15½" Hemlock bears S.48¾°E., 46.4 ft. scribed "¼ S8"  
"BT"  
9½" D.Fir bears S.60¾°W. 33.5 ft. scribed "¼ S7" "BT"  
9½" D.Fir bears N.17°W., 44.5 ft. scribed "¼ S7" "BT"  
Set spike in the base of the trees & placed new tags.

Note - Corner is on an easterly slope. C.S. File 65/37-14C

Cor. Secs. 5, 6, 7, 8

\* corrected  
8-1-01 DCSO SC

180

Found - Brass cap set by Byron (Ren. #102)  
Also found down Maple N.23°E., 18.8'

Set - Alum. post by corner monument. ✓  
12" W.Fir bears N.81¼°E., ~~24.0~~ ft. scribed "T28S R3W  
S5" "BT" 124.0  
8" D.Fir bears S.15¾°E., 75.2 ft. scribed "T28S R3W  
S8" "BT"  
10" D.Fir bears S.0¾°W., 132.9 ft. scribed "T28S R3W  
S8" "BT"  
6" Yew bears N.74¾°W., 83.2 ft. scribed "T28S R3W S6"  
"BT"

Set spike in the base of the trees & placed new tag.

Note - In open unit; approx. 950' N'ly of main gravel road  
on North side of small ridge. C.S. File 65/37-14B

1/4 Cor. Secs. 8 & 17

181

Found - Brass cap set by Byron (Ren. #52), loose & leaning,  
but still firmly in the ground at the base. We  
straighten & tighten; build rock mound.  
Orig. NE BT (now 14" Hemlock) bears N.13¾°E., 5.6 ft.  
Set spike in the base of the tree & placed new tag  
Also fd. Byron's SE BT down, root hole matches cap  
position.

Set - Also set an alum. post alongside the corner.  
11" W.Fir bears S.81¼°E. 14.8 ft. scribed "¼ S17" "BT"  
8" Hemlock bears S.76°W. 32.2 ft. scribed "¼ S17" "BT"  
15" Hemlock bears N.58°W. 24.8 ft. scribed "¼ S8" "BT"  
Set spike in the base of the trees & placed new tag.

Note - Corner lies @ the foot of a NW'ly slope & approx. 30'  
West of a small creek. C.S. File 65/37-14E

continued next page