

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 4 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Corner of Sec. 36, T28-4W. & Secs. 1 & 6, T29S-R's. 3 & 4W. 99

Found - Both Original Bearing Trees:

Orig. 18", now 30" Fir, now down, shows good scar, S.35°W.22.4 ft.

Orig. 20", now 38" Fir, S.30°W. 40.2 ft. I open & find good scribng.

Set - Brass Cap at Cor. Mkd: $\frac{S36}{S1/S6}$ T28S County Surveyor's
T29S Office, 1958
R4W R3W

New BT's: 20" Cedar bears S.71°W. 55.2 ft. scribed S1 T29S R4W CS BT.

18" Cedar bears S.30°E. 29.5 ft. scribed S6 T29S R3W CS BT.

James W. Byron, Dep.
M. Godfrey
S. Billow
C.S. 49/47
June 1958

Sec. Cor. to Secs. 32 & 33, T28-4W. & Sec. 5-4, T29-4W. 100

Found - Angle Iron Fence Post.

20" Fir N.70°E. 52.8 ft., now 28", Good Scar. REN#98

20" Fir N.82°E. 36.2 ft., dead, found scribng.

42" Fir S.72°E. 82.5 ft., cut down, shows scribng.

New BT's: 8" Laurel S.41°W. 47.7 ft. Scribed T29S R4W S5 CS BT.

10" Laurel S.20°E. 31.9 ft. Scribed S4 CS BT.

29" Fir N.42°W. 31.2 ft. scribed T28S R4W S32 CS BT.

Note - Corner 1 foot East of North-South Fence.

*Find ok 5/91
M 113-14*

James W. Byron, Deputy
Mike Darby & Wm. Stoffel
C. S. File No. 52/126
April 1963

$\frac{1}{2}$ Section Corner to Sections 17 & 16. 101

Set by Proportionate Measurement, See C.S. File No. 53/32.

Do not find Original Bearing Trees.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963

$\frac{1}{2}$ S17/S16 T28S R4W

New BT's: 10" Cedar bears S.46°W. 43.0 ft. scribed $\frac{1}{2}$ S17 CS BT.

26" Cedar bears N.28°W. 32.0 ft. scribed $\frac{1}{2}$ S17 CS BT.

10" Cedar bears S.61°E. 40.8 ft. scribed $\frac{1}{2}$ S16 CS BT.

21" Laurel bears N.14°E. 73.8 ft. scribed $\frac{1}{2}$ S16 CS BT.

James W. Byron
For J. Markham
July 30, 1963
C.S. 53/32

Sec. Cor. To Secs. 31 & 32 only, T27-4W. 102

(on North Line T28S R4W)

Found - Iron Wagon Boxing set by Frear in 1921. REN#91 (See Ren.#5, T27-4W)

27" I. Cedar S.28°E. 112.2 ft., shows plain axe scar. Tree
alive and in good condition.

24" Cedar S.82°W. 28.3 ft. is uprooted & dead, shows
very plain axe scar. Tree marked by Frear.

New BT's: 10" I. Cedar N.76°E. 57.5 ft. Mkd: T27S-R4W S32 CS BT.

10" I. Cedar N.38°W. 85.6 ft. Mkd: T27S R4W S31 CS BT.,

Scribed high to get over fence wires.

Nov. 1, 1963

Milo E.
Godfrey &
Crew
C. S. File
No. 53/33

Sec. Cor. to Secs. 4 & 5, T28-4W. & Secs. 32 & 33, T27-4W. 103

Found - Brass Cap set in 1959, also $\frac{1}{2}$ " Iron Pipe - See Ren. #63.

3 BT's. marked in 1959 still in good condition:

12" E. Cedar S.53 $\frac{1}{2}$ °W. 99.9 ft. - 34" D. Fir N.79°W. 37.0 ft.

8" D. Fir S.56 $\frac{1}{2}$ °E. 75.4 ft. - N.E. BT. is now broken off.

New BT: 8" Doug. Fir N.58°E. 100.4 ft. Mkd: T27S R4W S33 CS BT.

Milo E.
Godfrey & Crew
April 22,
1964
C.S. File
No. 53/33

Sec. Cor. to Sections 2 - 3 - 10 - 11. 104

Found - At Corner found G. L. O. Brass Cap set in 1958 Survey.

24" Fir Snag N.40°W. 5.6 ft., bark scribed.

13" Cedar Snag N.20 3/4°E 95.4 ft., all scribng visible.

All other BT's. are blown down, logged or gone.

New BT's: 12" D. Fir S.41°E. 57.6 ft. Mkd: T28S R4W S11 CS BT.

5" D. Fir S.24°W. 47.0 ft. Mkd: S10 CS BT.

9" D. Fir N.38°E. 111.2 ft. Mkd: T28S R4W S2 CS BT.

11" D. Fir N.70°W. 87.0 ft. Mkd: T28S R4W S3 CS BT.

M. E.
Godfrey and
Crew
June 5,
1964
C. S. File
No. 49/67