

Douglas County Surveyor's Record of  
Government Corners Renewed

T28

T. S.

R 4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

C O N T - - - (Sec. cor. for 24 & 25 only)

121

trees cut to short tipped out stumps. The stumpholes match the bearings and distances of the orig. bearing trees reasonably well but the nature of the uproots disallows accurate measurement. No blaze or scribe marks are visible because these trees have tipped over on their faces.

Set - Because of the plumb and firm set of the brass cap monument and the reasonable fit of the above mentioned found stump holes, the monument position is accepted as good.

New BT's- A 9" DBH white fir bears S.09°W., 64.4 ft. and is scribed T28S R4W S25 CS BT on a double blaze.

A 10" DBH D. fir bears S.39°W., 70.6 ft. and is scribed T28S R4W S25 CS BT on a double blaze.

Because of future logging in area, no other suitable trees are available. Lower blazes of new BTs are carefully aimed at corner. New Bts are tagged with DCSO BT tags.

Stephen Flause  
Deputy, Doug.  
Co. Surveyors  
T. Plouff  
March 26, 1981  
C.S. 61/19

3/26/81

Center 1/4 corner for Sec. 10.

Set - 5/8" x 30" I.R., 26" in ground from which BT's bear:

New BT's- 6" D. Fir bears N.39°E., 9.0-ft., marked C1/4 S10 BT

6" Laurel bears S.38°W., 10.0-ft., marked C1/4 S10 BT

Note - Corner lies on South slope, 130-ft. East of a draw & 75-ft. West of a cat in heavy brush & reproduction.

10/81

Burton Holt  
for: Sun Studs  
October, 1981  
M 90 - 5

122

Sec. Corner common to Secs. 34, & 35, and Secs. 3, & 2 of T.29-4.

Found - Brass Cap, properly mkd. (set in 1958 Resurvey).

BTs. - 20" W. fir w/healed over face, bears N.30°E., 7.9-ft.

20" cedar BT, down, scribes vis., bears S.35°E., 62.7-ft.

24" cedar BT w/healed over face bears S.80-1/2°E., 37.3-ft.

(Rec. 36.3-ft.).

18" D. fir BT w/healed over face bears N.66-1/2°W., 42.9-ft.

18" cedar, now down, no marks vis., bears S.80°E., 16.5-ft. Orig.

22" fir snag w/scribes vis., bears S.60°W., 27.7-ft. Orig.

\* Note: The N.E. original BT rotted & scattered in general area.

New BTs.- 8" cedar BT, I scribed "T29S R4W S2 BT" bears S.27°E., 52.0-ft.  
12/81

Bruce Shaner  
For: Longview Fibre Co.  
Oct., 1981 thru Jan., 1982  
RM 3-54

124

1/4 Corner common to Sec. 35, and Sec. 2 of T.29-4.

BTs. - 48" cedar stump w/remains of old face, bears S.12°W., 27.7-ft.

Root hole of Madrona bears N.12°W., 27.7-ft. (young Madrona about it), (Rec. N.22°W.)

U.S.G.L.O. Corner tag faces into corner, signed by H. Langdon & H. Carlson, others, Oct.28, 1945.

U.S.G.L.O. Witness tag faces corner, signed by Burt Holt (circa 1940).

Cruiser blaze "K" faces corner (Al Keatley, Stomar Lumber Co.) (circa 1955).

New BTs.- 10" D. fir BT I scribed "1/4 S2 BT" bears S.49°E., 12.0-ft.

10" D. fir BT I scribed "1/4 S35 BT" bears N.45°E., 11.2-ft.  
12/81

125

1/4 Corner common to Sec. 31, and Sec. 36 of T.28-5.

Set - 1" x 30" galv. I.P. w/ 2 1/2" B.C. mkd.: T28S R5W R4W 1/4 S36 S31 LS 866 1983.

New BTs - 10" white oak bears N.41°11'W., 74.5-ft., scribed: 1/4 S36 BT

7" madrone bears N.6°30'E., 35.1-ft., scribed: 1/4 S31 BT.

Note - Pending an answer from the B.L.M. regarding this 1/4 Cor., the monument was in place N.0°8'23"E., 33.96-ft. from its present location, from Feb.8, 1983 to Mar.18, 1983. Bearing tree faces are toward the first position,

Fnd. - 33" black oal bears N.1°47'E., 71.6-ft. The tree had been previously opened. I re-opened the tree in the area of a lower blaze but found no face or scribing.  
1-3/83

William Ruppert  
LS#866  
For: Deam, Richard  
Jan.-Mar., 1983  
M 93 - 68  
C.S. 58/270

SEE C.S.  
58/270 FOR  
LETTER