

Douglas County Surveyor's Record of
Government Corners Renewed

T 28

T. S.

R 4

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

126

Section corner for Secs. 26, 25, 35 and 36.

Found - 3/4" iron rod flush with ground. Ren. #58
5" fir, now 8" hemlock with well healed blaze bears N.30°W., 2.0ft
18" cedar, now 23" with illegible scribing visible in partially
healed blaze, bears S.36°E., 39.7 ft. (Rec. S.84°E., 40.0 ft.)
Probable orig. 10" fir, now 34" high cut stump with scribing
"S 36" in bark per Ren. #58, bears S.69°E., 16.5 ft.
(Rec. S.73°E., 15.2 ft.) No sign of orig. scribing.
Probable orig. 10" fir, now 36" with rescribing per Ren. #58
visible (S 35) bears S.9°W., 24.2 ft. (Rec. S.5°W., 25.7 ft.)
Probable Orig. 48" fir now 52" stump, no scribing or face
visible (however, the bark has been disturbed during logging)
bears N.66°W., 22.9 ft. (Rec. N.70°W., 223.7 ft.) Note: Orig.
distance appears to be in error.

Note: bearings to orig. BTs do not fit, however they are all off 4° in the
same direction making the relationship between trees fit well.

Set - Since this area is to be logged soon, I DO NOT SET new monument
but do leave found 3/4" iron rod per Ren. #58 in place.

New Accessory:

Set spike in center of orig. 48" now 52" fir stump, marked
"BO 1" bears N.66°W., 22.9 ft.

Bearing trees are outside of clear cut boundary signs therefore most
accessories should be untouched by logging. I double tagged all BTs for
better visibility.

5/18/83

Section corner for Secs. 9, 10, 15 and 16.

Found - 1958 BLM brass cap.
14" fir bears S.22°E., 52.5 ft. (Rec. 52.8 ft.) Closed face.
19" fir stump, 3 ft. tall, bears N.36°W., 48.5 ft., Closed face.
15" fir bears N.17°E., 62.4 ft. Closed face.
SW cedar BT not found.

New BTs - 5" fir bears S.71°W., 34.9 ft. scribed "X BT".
12" fir bears N.20°W., 18.1 ft. scribed "T28S R4W S9 BT".

May 1985

127

1/4 Section Corner for Sections 29 and 30

REN #107

Found - 5/8" Iron Rod (1964)
BT's - 30" Pine, bears S.34°E., 30.2 ft. dist. Now Stump.
- 20" Cedar Stump, bears S.15 1/2°W., 43.0 ft. dist.
24" Fir, bears N.64°W., 109.0 ft. dist., healed blaze.
17" Fir, bears N.65°E., 49.7 ft. dist., healed blaze.

SET - Aluminum cap on existing iron rod, marked "LS 498"

Center 1/4 Section Corner for Section 29

REN #109

WITNESS CORNER - CORNER FALLS CN BRIDGE.

Set - 5/8" x 36" Iron rod and Aluminum cap Mkd. "LS 498". Witness
Corner lies 22.0 ft. South of true corner position.

New BTs- 11" Cedar bears N.61°W., 20.8 ft. dist., scribed.
26" Fir, bears S.5°E., 31.5 ft. dist., scribed.

NOTE: Tagged fence corner bears S.25°14'W., 53.0 ft. dist., FOUND NO
Evidence of 1922 Corner Information.

Center 1/4 Corner for Section 22

Set - 5/8" x 36" Iron rod with alum. cap mkd. "LS 498"

New BTs- 12" Cedar bears N.42°E., 10.1 ft.
14" Fir bears S.70°E., 27.8 ft.

Section corner for Secs. 22, 23, 27 and 26

Found - 2" Iron Pipe. Ren. No. 29

26" Fir bears N.32 1/2°W., 56.8 ft. Healed
34" Fir bears S.65 3/4°W., 48.8 ft. Healed

Set - 5/8" x 36" Iron Rod and Alum. Cap in Iron pipe.

New BTs - 6" Fir S.26°E., 8.1 ft.
11" Fir bears N.61°E., 27.1 ft.

131

Gregory Quibell,
Deputy, Doug. Co.
Surveyors Office
John Powell
May 18, 1983
L.S. 62/7

Rondald G. Geisler
LS #1988
For: Champion
International Corp.
May 1985
M 98 - 72

Howard W. Johnstone
"LS 498"
For: Roseburg Resources
Company
February 1986
M 100 - 36

Howard Johnstone
L.S. No. 498
For: Roseburg Resources
March 1986
M 100 - 47

RE-RENEWED SECTION CORNER NO. #134