

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28

T. S. R 4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97501

Burton W. Holt  
L.S. 418  
April 8, 1986  
C.S. 62/30

1/4 Corner for SECTIONS 3 and 10 132  
Found - BLM brass cap in place but both bearing trees have been  
uprooted. This area has been logged recently and no standing  
trees are left.  
New BTs - A 40" fir stump bears S.64°E., 21.1 ft. marked 1/4 S10 BT.  
An 18" cedar stump bears N.33°E., 75.6 ft. marked 1/4 S3 BT.  
This corner lies on an east slope, 100 ft. south of a rocked road.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Sept. 15, 1989  
C.S. 64/1

Section Corner for Sec. 36; and Sec. 31 of T28-3 133  
Found - A 3 1/4" 1964 BLM brass cap on a 2 1/2" dia. iron pipe, protruding  
7" above ground. (from 1964 BLM D. resurvey.  
Orig. 34" dia. Cedar now depression with burnt roots bears  
N.32°W., 25.7 ft. (agrees with 1964 BLM record)  
Orig. 24" dia. D. fir bearing N.10°E., 130.7 ft. in 1964  
BLM resurvey is gone.  
42" now 49" dia. D. fir with a fully healed single blaze bears  
N.48°E., 56.1 ft. (agrees with rec.) from 1964 BLM resurvey.  
16" now 18" dia. 7 ft. tall tipped D. fir stump with illegible  
scribe marks in a partially healed single blaze bears  
N.50 3/4°W., 44.2 ft. (agrees with rec.) from 1964 BLM resurvey.  
8" now 12" dia. I. Cedar with a partially healed single blaze,  
bears N.70°W., 15.8 ft. (agrees with rec.) from 1980 BLM  
resurvey. Note: Tree not likely to live long, recently girdled  
with a chain saw.  
New BTs - 8" dia. I. Cedar double blazed and scribed "T28S R3W S31 CS BT"  
bears N.69 1/2°E., 45.0 ft.  
14" dia. D. fir double blazed and scribed "T28S R4W S36 CS BT"  
bears N.17 1/2°W., 52.7 ft.  
Corner lies at the intersection of a north and east cutting lines. Old  
growth in northeast quadrant.

9/15/89

Center 1/4 Corner for Section 22 134  
Set - 5/8" x 36" iron rod and alum. cap (See Ren. #130)  
BTs - 12" Cedar, N.82°E., 6.9 ft.  
14" Fir, S.59°E., 30.7 ft.

Howard Johnstone  
For: Roseburg  
Resources, Inc.  
March, 1990  
M 101 - 75  
(Revises M100-47)

1/4 Corner for Secs. 27 and 28 135  
Found - 1958 Cad. Brass cap/iron pipe  
12" Cedar S.78°E., 40.6 ft. healed.  
8" Fir, N.54 1/4°W., 27.1 ft. Part healed. (No record)  
16" Fir stump, S.20 1/2°W., 28.4 ft. (27.7) See Ren. #51  
30" Fir stump, N.78°E., 11.9 ft.

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
May 17, 1990  
C.S. 64/9

1/4 Corner for Sections 31 and 32 136  
Found - A 2" I.D. iron pipe flush with ground. From M 53 - 61  
1" dia. iron rod protrudes 6" above ground (Rec. 3/4" in  
M53-51) bears S.58 1/2°E., 9.55 ft. (agrees w/rec) Source  
unknown.  
Bearing and distance taken from 2" iron pipe:  
A double trunked B. oak with a fully healed single blaze found  
on 19" dia. southwest trunk, we open blaze and find scribe  
marks "BT". Center of root crown bears N.48°E., 88.4 ft.  
(source unknown, ring count dates back approx. to M53-61)  
16" dia. I. cedar with a fully healed single blaze, we open  
illegible scribe marks visible, bears N.10°W., 15.1 ft.  
(source unknown, ring count dates back approx. to M53-61)  
New BT - 10" dia. D. fir double blazed and scribed "1/4 S31 CS BT" bears  
S.32 1/2°W., 43.5 ft.  
Note: 2" dia. iron pipe bears N.65°W., 10.0 ft. from a north-south and east  
running fence corner.

5/17/90