

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5 R. W. W. M.

CORNER TO SECTIONS 17, 18, 19 and 20.

I renewed this corner from one original B.T. which was
alive and in which the scribe marks were visible. Set an
Oak post 4" x 4" x 30" and marked trees as follows 2" pipe
White Oak 24" dia. bears N. 19° E., 17 lks.
Black Oak 20" dia. bears S. 72° E., 50 ft.
White Oak 16" dia. bears S. 56° 45' W., 49.8 ft.
Black Oak 10" dia. bears N. 59° 30' W., 89.2 ft. **87**

1/4 SECTION TO SECTIONS 2 and 3.

Pointed rock set in ground. Original B.T.s rotted away.
I checked to holes where they stood and remark new B.T.s as
follows

A Black Oak 9" dia. bears 121.5 lks. - N. 17° W. - *reported by Miller 12-18-57*
A White Oak 4" dia. bears S. 34° 15' E., 31 lks.

1/4 CORNER BETWEEN SECTIONS 5 and 38 South Boundary

I set corner from old oak tree which was still in good
shape. Old Ash B.T. in evidence but down. I marked
a 15" Alder for the B.T. which bears S. 28° W., 559 lks. **144**

1/4 CORNER BETWEEN 15 and 16.

Old Bearing Trees good. Set new stake. **97**

1/4 CORNER BETWEEN 10 and 15.

Old Bearing Trees good. Set new stake. **96**

CORNER SECTION 9, 10, 15, and 16.

Find old B.T.s stump N. 56 1/2° W., 5.20 scars visible
Oak S. 40 3/4° E., 4.00
Oak S. 30 1/2° E., 1.96 given as 4.90
Marked Oak 12" dia. bears N. 69° 30' W., 51 lks. B. P. S. C.S. **93**

CORNER TO SECTION 4, 5 T. 29 R. 5, and 32, 33 T. 28 S. R. 5 W.

I renewed this corner from 3 old B.T.s. Other tree was
gone. Set Oak Post. Fence post at corner. Old B.T.s are
badly rotted. Marked new B.T.s as follows

Black Oak 20" dia. bears S. 66° W., 170.7 ft.
Black Oak 14" dia. bears N. 28° 30' W., 68.8 ft. **81**
White Oak 10" dia. bears N. 78° E., 148.8 ft.
Black Oak 10" dia. bears S. 24° E., 120.0 ft.

1/4 CORNER BETWEEN SECTION 23 and 22

Set with 10" x 14" x 20" Sandstone from original B.T.
Laurel 24" dia. bears N. 50° E., 32.1 lks.
Fir 38" dia. bears S. 60° W., 35.0 lks. **67**

Chisled 1/4 S. C.S. on S. face of sandstone. The laurel was
32 links distance, instead of 23 links. Remark old bearing
trees.

CORNER OF SECTION 14, 15, 22 and 23.

Location determined from 12" Black Oak. Original bearing
tree N. 35° W., 45 lks. which we chopped out. Scribe marks
plain and legible. Tree fell due to its weight being all on
one side. A Black oak rotten stump N. 17° E., 34 lks. with
hole where B.T. original blazes were, was another original
B.T. Other B.T. destroyed but evidences of stump and roots
checked location for bearing and distance. Set a Sandstone
8" x 10" x 16", 12" in ground for corner from which

Fir 12" dia. bears N. 12° E., 44. lks.
Fir 12" dia. bears S. 86° W., 23. lks.
Fir 10" dia. bears S. 41° E., 24 lks.
Fir 14" dia. bears N. 36° W., 60 lks. **55**

NORTH 1/4 CORNER OF SECTION 6 ONLY.

Corner was set from old B.T.s by driving 3/4" x 36"
round iron Bolt in ground. Marked new bearing trees as
follows

Fir 14" dia. bears S. 22° 15' E., 120.3 ft.
White Oak 8" dia. bears S. 46° 45' W., 17.3 ft.

Fd. ok.
H. Pieske
June, 1922
M 90-22

FD. OK 12190
M 111-23

See Corner No. 11-A (out of place)

G. A. McHenry
Dep. Co. Sur.
Nov. 1922
Witnesses
P. D. Wolford
S. K. Bowden
O. W. Sprinzer
D. C. S.
Bergh chain
Sam Whitsett
Wit.
Oiley Barn
Oliver Patterson
Feb. 1923

Nov. 16, 1925
W. H. Woods
Wit.
W. S. Crear
A. B. Hatfield
L. S. Patterson

H. L. Eppstein
Wit.
Bill Dolan
S. D. Whitsett
May 10, 1926

Ben B. Irving
Jan. 6, 1938
Wit.
N. E. Richardson
Blinn Cooper
Wesley French
Frank Bohme

Ben B. Irving
D. C. S.