

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 21 - 22 - 28 - 27. 73
 Found - $\frac{3}{4}$ " I. P. under N.S. Fence at corner & 18" Maple S.11°E.
 183.5 ft., not S. 9°E. 183.5 ft., shows good scribing. *Ren #41*
 Orig. N. E., N.W. & S. W. Bearing Trees.
 New BT's: 15" Maple bears N.53°E. 51.3 ft. scribed S22 T28S R5W
 CS BT.
 16" Db $\frac{1}{2}$ " Maple bears N.10 $\frac{1}{2}$ °W. 74.7 ft. scribed S21 T28S
 R5W CS BT.
 Rescribed O.B.T., now 36" Maple S.8 $\frac{1}{2}$ °W. 158.4 ft.,
 "S28 CS BT" (scribed high above fence.)

Section Corner to Sections 29 - 28 - 32 - 33. 74
 Found - 2" I. P. at Corner & both BT's. as recorded by Cole. *Ren #37*
 We open N. W. BT. & find good scribing. W. BT. *#53*
 shows good scar but may die, result of 1961 Fire.
 Rescribe N. W. BT. S29 CS BT T28S R5W.
 New BT's: 11" W.O. bears N.67°E. 139.3 ft. scribed T28S R5W
 S28 CS BT. - No other BT's. near.
 Note - Corner is under E. W. Fence.

75
 $\frac{1}{4}$ Corner to Sections 21 and 22.
 Found - Orig. 20", now 36" B.Oak Snag, center rotted., S.39°W.
 16.5 ft. *See Ren #28*
 Orig. S. E. BT. not found. Brigg's N.E. BT. standing
 & shows good scribing.
 Auto Spring at Corner.
 Set Brass Cap alongside Auto Spring Mkd: County Surveyor's Office,
 1961 $\frac{1}{4}$ S21/S22 T28S R5W.
 New BT's: 15" R.Fir N.69°E. 13.0 ft. scribed $\frac{1}{4}$ S22 CS BT.
 16" R.Fir S.57°W. 15.2 ft. scribed $\frac{1}{4}$ S21 CS BT.
 Note - Corner at four way fence intersection.

76
 $\frac{1}{4}$ Corner to Section 29 and 32.
 Found - Orig. 12", now 20" B.Oak N.17°W. 39.6 ft., we open &
 find good scribing " $\frac{1}{4}$ ". Also find a Stump Hole
 that checks for S. E. BT.
 Note - East West Fence is 35 ft. South.
 Set Brass Cap at Corner Mkd: County Surveyor's $\frac{1}{4}$ S29 T28S R5W
 Office, 1961 S32
 New BT's: O.B.T., now 20" B.Oak N.17°W. 39.6 ft. scribed $\frac{1}{4}$ S29 CS BT.
 18" B.Oak bears S.24°E. 23.3 ft. scribed $\frac{1}{4}$ S32 CS BT.

77
 $\frac{1}{4}$ Corner to Sec. 30, T28-5W. & Sec. 25, T28-6W.
 Found - Orig. 17", now 24" W.O. N.62°W. 23.8 ft., We open near
 base & find good scribing "T".
 Orig. 14", now 24" W.O. N.64°E. 17.2 ft. Do not open.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
 R6W $\frac{1}{4}$ S25/S30 R5W T28S
 New BT's: 15" W.O. bears S.63°W. 50.2 ft. scribed $\frac{1}{4}$ S25 CS BT.
 Orig. 24" W.O. N.64°E. 17.7 ft. scribed $\frac{1}{4}$ S30 CS BT.

78
 Section Corner to Secs. 30-31, T28-5W. & Secs. 25-36, T28-6W.
 Found - Orig. 20", now 28" W. Oak, shows good scribing on old
 face, "BT", S.65°W. 27.1 ft.
 Orig. 28", now 32", W. Oak N.25°W. 66.7 ft., shows
 good scar, we do not open. Orig. S.E. BT. not found.
 Note - Corner at 4 way fence intersection.
 Set - Brass Cap at Cor. Mkd: County Surveyor's S25 | S30 T28S
 Note - Cap set 2.0 ft. above Office, 1961 R6W S36 | S31 R5W
 ground. Solid Rock at Bottom.
 New BT's: O.B.T. 28" W.Oak S.65°W. 27.5 ft. S36 T28S R6W CS BT.
 22" W.Oak bears S.41 $\frac{1}{2}$ °E. 43.0 ft. sc. S31 T28S R5W CS BT.
 13" W.Oak bears N.43°E. 45.7 ft. scribed S30 T28S R5W CS BT.
 8" W.Oak bears N.31°W. 37.0 ft. scribed S25 T28S R6W CS BT.

RE-RENEWED CORNER NO.

FD 11/27
M 105-13A-8
D. BENTZ

FD OK 11/76
M 105-13A-8
D. BENTZ

FD 4/91
D. BAKER
M 105-13A-8

James W. Byron, Deputy County Surveyor
 Dale McFarland
 Jim Powell
 September - October 1961
 C. S. File No. 49/64