

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 S T. S. R 5 W R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 97401

150

William Ruppert
LS#866
For: Deam, Richard
Jan.-Mar., 1983
M 93 - 68

Center 1/4 Sec. Cor. of Sec. 36.
Set - 1" x 30" galv. I.P. w/ 2 1/2" B.C. mkd: T28S R5W C 1/4 S36
LS 866 1983.
New BTs- 5" madrone N.16°30'E., 11.5-ft.
7" oak bears N.29°30'W., 55.4-ft. (Both trees scribed: C 1/4
S36 BT)
Note - Pending an answer from the B.L.M. regarding proportioning of
the east 1/4 Cor., the center 1/4 cor. monument was in place
N.0°04'E., 16.93-ft. from the present position, from Feb. 8,
1983 to Mar. 18, 1983. Bearing tree faces are toward the
first position. 1-3/83

151

Larry E. Monrean
Deputy, Doug. Co.
Surveyors Office
October 7, 1983
C.S. 62/9

FD 5/91
D. BAKER
M 113-32

Section corner for Secs. 30, 29, 31, 32.
Found- 1" dia. iron pipe set by Markham. Ren. #60
Orig. W. oak, 8" now 13" dia. bears N.16°W., 49.9 ft. (Orig. Rec.
N.14 1/2°W., 51.5 ft.) reblazed by Markham, well healed. This
tree is in a fence running west, fence wire grown in.
11" now 15" madrone bark scribed and blazed bears N.57°E., 17.1 ft.
(Rec. 17.7 ft.) Ren. #60
6" now 12" madrone, bark scribed & blazed bears S.61°E., 17.0 ft.
The top is broken out of this tree, still growing. Ren. #60
26" now 30" madrone, scribing visible in partially healed blaze,
bears S.51°W., 46.0 ft. Ren. #60
Set - 1" x 30" iron pipe and brass cap at position of found Markham mon-
ument. Monument protrudes about 12" above ground. Cap is marked:
"Douglas Co Surveyors Office T 28 S S30 S29 S31 S32 R 5 W
1983". Place 1" iron pipe along southerly edge of new monument.
No new accessories.

10/7/83

152

Larry E. Monrean,
Deputy, Doug. Co.
Surveyors Office
R.W. Smith & P. Bair
Nov. 9, 1983
C.S. 62/9

1/4 Corner for Sections 11 and 12.
Found - Iron pipe and 1977 brass cap, properly mkd, per Ren. #143
firmly set 12" below ground level.
12" now 15" east fork of double forked white oak bears S.75°W.,
163.5 ft. (Rec. 162.0 ft. per Ren. #59 is to face of BT) BT
has well healed double blaze.
28" now 29" white oak bears S.16°W., 342.3 ft. per Ren. #128. BT
is tipped out and down, BT will be cut in near future.
3/4" I.R. bears S.75°W., 41.6 ft. (Rec. 41.3 ft. per Ren. #128)
protruding 4" above ground in N-S fence line.
New Accessories:
13" multiple topped black oak double blazed & scribed 1/4 S11
CS BT" bears N.69°W., 329.6 ft.
A 5/8" I.R. with alum. cap stamped "BO" set 2" below ground bears
S.9°E., 254.8 ft. I. rod is 1 ft. east of NE concrete footing
block of barn.
Note: Monument lies in open pasture 41 ft. east of N-S fence and 252 ft.
north of a barn. Metal detector may be helpful in locating buried
corner. Sketch in CS file.

11/9/83

153

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
August 8, 1989
C.S. 64/1

Section Corner for Sections 28, 29, 32 and 33
Found - A 1 1/4" I.S. iron pipe (Rec. 2") protruding 5" above ground.
Ren. No. 37
12" now rotted Oak of indeterminable size. no scribing, blazes
or axe marks seen, bears N.36 3/4°E., 75.2 ft. (agrees with
record) Possible Orig. BT.
15" now 30" dia. 2 1/2 ft. high Oak stump with possible blaze seen
from top, bears N.40°E., 74.7 ft. (Rec. N.40°E., 74. ft.,
possible face measurement). Ren. No. 37
12" now 15" dia. W. oak with a fully healed double blaze bears
N.28°W., 185.0 ft. (agrees with record) Ren. No. 37
11" now 18" dia. W. oak with a fully healed single blaze bears
N.67°E., 139.3 ft. (agrees with rec) Ren. No. 74 (This tree
to be cut in near future.)
Set - A 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. x 32" long I.P.
is set in ground at referenced position of Ren. No. 37 1 1/4"
I.D. iron pipe. DCSO BC/IP protrudes 6" above ground, 1 1/4" I.P.
is set along North edge of DCSO BC/IP and protrudes 5" above
ground. BC stamped "Douglas County Surveyors T28S S29 S28
S32 S33 R5W 1989 Office" 1 1/4" I.D. iron pipe from
Ren. No. 37 measured 23 1/2" long.)