

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 6 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

S. E. Corner of D. L. C. # 40. 63
 Found - Orig. 14" now 26" B.O. BT. N.67°W. 93.7 ft. This BT. recently
 opened, shows good scribing "T28 CL 40 R6 BT"
 Stone Set for Corner not found.
 Set Brass Cap at Corner Marked S. E. DLC 40 T28S R6W,
 County Surveyor's Office, 1958
 New BT's: 26" Cedar N.29°W. 20.4 ft. scribed T28S R6W SE CL 40 CS BT.
 22" R.Fir S. 7°W. 33.2 ft. scribed T28S R6W SE CL 40 CS BT.
 Fence Corner bears N.61°W. 22 ft.

James W. Byron, Deputy
 Milo Godfrey
 S. Blom
 March 31, 1958
 C. S. File No. 49/73

$\frac{1}{4}$ Section Corner to Sections 5 & 8. 64
 Found - Orig. 7" now 18" B.O. N.20°E. 36.3 ft. This BT. recently
 opened, good scribing visible " $\frac{1}{4}$ S". I do not find Original
 S. E. BT.
 Set Brass Cap at Corner marked: $\frac{1}{4}$ $\frac{S5}{S8}$ T28S R6W County Surveyor's
 Office, 1958
 Note - Corner at Wire Fence Corner.
 New BT's: 13" R.Fir bears S.7°W. 26.4 ft. scribed $\frac{1}{4}$ S8 CS BT.
 6" W. O. bears N.29°W. 11.6 ft. scribed $\frac{1}{4}$ S5 CS BT.

James W. Byron, Deputy
 Milo Godfrey
 S. A. Blom
 May 21, 1958
 C. S. File No. 49/73

FD-5/BK
 R. WARE
 M 96-71

Section Corner to Sections 4, 5, 8, & 9. 65
 Found - $\frac{3}{4}$ " Iron Pipe at Section Corner & 4 Way Fence Corner. REN #6
 Find 14", now 28" W. O. N.48°W. 75.9 ft., I open & find
 good scribing.
 The S. E. BT. gone.
 I reblaze & rescribe 28" W. O. N.48°W. 75.9 ft. S5 T28S R6W CS BT.
 Blaze & Scribe 20" B. O. N.45°E. 1.8 ft. S4 T28S R6W CS BT.
 Blaze & Scribe 8" B. O. S.25 $\frac{1}{2}$ °E. 105.2 ft. S9 T28S R6W CS BT.

RE-RENEWED, SEE COLLIER NO. #186

Section Corner to Sections 5, 6, 7, & 8. 66
 Found - Both BT's. as renewed by Boyer, check for bearing & REN #39
 distance., Show good faces, I do not open.
 Boyer's Rock at Corner & a 1" Steel Shaft at Corner.
 Set Brass Cap at Corner alongside Rock & Shaft Mkd:
 $\frac{S6}{S5}$ T28S R6W County Surveyor's Office, 1958
 $\frac{S7}{S8}$
 Elazed & Scribed 6" B. O. S.0°30'W. 12.9 ft. S7 T28S R6W CS BT.

S. E. Corner of D.L.C. No. 53 in T.28/R.6 W. 67
 Rock Corner in place, but no trees.
 I marked a 5" Prune Tree N.41°W., 27.0 ft.

RE-RENEWED, SEE COLLIER NO. #68

H.L. Eppstein
 Feb., 1935

S. E. Corner D. L. C. No. 53. 68
 Found - Corner Stone with 1" + chisled on top at fence corner thus:
 B.T. scribed by Eppstein, REN #67 1935 removed by Zeller after tree died.
 New BT's: 19" B.Oak bears N.80 $\frac{1}{2}$ °W. 19.9 ft. scribed S. E. DLC 53 CS BT.
 8" B.Oak bears N. 6°E. 33.7 ft. scribed S.E. DLC 53 CS BT.

James W. Byron
 M. Godfrey
 S.A. Blom
 Aug. 14, 1958
 C.S. File #49/73

$\frac{1}{4}$ Section Corner to Sections 30 & 31. 69
 Found - Both Original BT's.:
 Orig. 24", now 40" Oak, down, shows old face, rotted, no
 scribing found.
 Orig. 24", now 44" W. Oak. I open & find good scribing,
 " $\frac{1}{4}$ S BT" S.53 $\frac{1}{2}$ °W. 483.8 ft.
 Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958 $\frac{1}{4}$ $\frac{S30}{S31}$ T28S
 R6W
 New BT's: 18" Pine bears S.43°E. 316.3 ft. scribed $\frac{1}{4}$ S31 CS BT.
 16" W.Oak bears N.34 $\frac{1}{2}$ °E. 225.5 ft. scribed $\frac{1}{4}$ S30 CS BT.

James W. Byron, Deputy
 Milo Godfrey
 S. A. Blom
 Nov. 17, 1958
 C. S. File No. 49/50