

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881


$\frac{1}{4}$ Corner to Sections 10 and 15.
Found - Both Rocks as recorded, in Original Survey.
12" x 6" x 24" Stone, 6" out of ground at fourway fence,
corner and at true corner.
Set - Brass Cap alongside West Edge of Corner Stone and Mkd:
County Surveyor's $\frac{1}{4}$ S10 T28S R6W
Office, 1962 S15
No trees near for Bearing Trees:

126

Fd. BRASS CAP
7/85 E. BLISS
M 99-3
7/87 M 104-62
FD. OK 1991-0001
DEC. 90
1992-0008
GENZ

$\frac{1}{4}$ Corner to Sections 20 and 29.
Found - 1" I. Pipe at Corner & along East Edge of Roadway. *Rev. #28*
Now 22" Cedar bears N.46°E. 146.7 ft. We open & find good
scribing.
Boyer's N.W. BT. gone, in excavation area.
Set - Brass Cap alongside Corner Pipe & Mkd: County Surveyor's
 $\frac{1}{4}$ S20 T28S R6W Office, 1962
No new BT's. scribed. S29

127

N. W. Corner D. L. C. No. 46.
Found - Wedge-shaped Stone, 8" x 4" at ground & 8" above ground
at fence cor. thus:

We do not find Original Bearing Tree.
Corner Stone was used for Initial Point of Yocum Acres.
New BT: 19" B.Oak bears N.50°E. 12.1 ft. scribed N.W. Cl 46 CS BT.

128

$\frac{1}{4}$ Corner to Sections 20 and 29.
Found - 1" I. Pipe at Corner & along East edge of Roadway.
Now 22" Cedar bears N.46°E. 146.7 ft. We open & find
good scribing.
Boyer's N.W. BT. gone, in excavation area. *Same as above*
Set - Brass Cap alongside Corner Pipe & Mkd: County Surveyor's
Office, 1962 $\frac{1}{4}$ S20 T28S R6W. *#127*
S29 No new BT's. scribed.

129

S. W. Corner D. L. C: No. 43.
Found - 6" x 6" x 8" High Stone. We mark 2" + on top.
Note: D.L.C. Corner is 1.0 ft. North of Fence Corner.
See C. S. File No. 52/108 M 23-18
New BT: 11" Pear N.40½°E. 47.3 ft. scribed SW Cl 43 CS BT. *146*

RE-RENEWED, SEE CORNER NO. #164

Section Corner to Sections 11 - 12 - 13 - 14.
Found - High Pointed Rock Bearing Object per GLO notes of 1853.
Set - 3" I. R. Flush
P.K. 10 ft. East of edge White Line
P.K. 9 ft. West of edge White Line
3" I.R. on East R/W Line State Highway.

129-A

$\frac{1}{4}$ Corner to Sec. 35, T28-6 & Sec. 2, T29-6W.
Conglomerate Rock Set from Original "Y" Oak Stump hole which
is S.72½°E. 396 lks. and from fallen dead "Y" Oak N.13½°E. 306 lks.
New Trees properly blazed and scribed.
10" Wh. Oak N. 8°E. 57.5 ft. marked CS BT.
12" Wh. Oak S.34°45'E. 66 ft. mkd: CS BT.
Dec. 21, 1937, Drove 1½" Pipe beside Rock, 46" in ground and
6" above ground near foot of hill at wedge of Oak Thicket.

130

Fd. OK 7/20/64
R. SMITH, Deut. Co
Surveyors OFF.
C.S. 62/18

James W. Byron, Deputy County Surveyor
Dale McFarland and John Powell
January & February 1962
C. S. File No. 49/139

Byron & Crew
Feb. 20, 1962
C.S. 52/108
M 23 -18

Arthur Boyer
N.E. Richardson
V. Phipps.
March 10, 1937

Fd. OK 5/16/64
C.S. 63/19