

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

G.R. Lecklider
For-C.M. McDermott
March, 1959
Map File
M 14 - 18

1/4 Section Corner to Sections 15 & 22.
Set 1/2" Rod in Mound of Stone from which:
11" Fir - S.79°W - 28.9 ft.
11" Fir - N.06°W - 14.0 ft.
Original Corner Not Found.

118

James W. Byron, Deputy
S. A. Bilow
May 29, 1959
C. S. File No. 49/50

N. E. Corner of D. L. C. No. 56.
Found - 18", now 36" Fir S.54°W. 68.5 ft., previously opened,
shows good scribing "DLC 56". See Ren. #37.
Bridge over Creek rebuilt. I do not check Tie to Pier.
Note - Corner in Creek. I set Wit. Cor. 50' West of True Corner;
Set Brass Cap Mkd: County Surveyor's Office, 1959, N.E. Cor. DLC 56
T28S R7W.
New BT's: 20" R. Fir bears S. 7° W. 41.3 ft. scribed Wit. NE CL 56 CS BT.
Rescribe now 36" Fir S.33°W. 12.0 ft. Wit. NE CL 56 CS BT.

FD OK PER BEUTZ
NOV. 1988 M107-34
FD OK 12/89 1990-0073

119

N. E. Corner D. L. C. No. 59.
Found - 36", now 40" B. O. N. 2°W. 11.9 ft., shows good reverse
scribing "59 CS". See Ren. #40.
Also Find 1" Iron Pipe under E.W. Wire Fence at Corner.
I do not set Brass Cap at Corner.
New BT's: 28" B. Oak bears N.29°E. 49.3 ft. scribed NE CL 59 CS BT.
38" B. Oak bears S.49°E. 135.5 ft. scribed NE CL 59 CS BT.

120

FD OK
7/06
H. P. OSK
M102-23

James W. Byron
Milo Godfrey
Clete Putnam
Oct. 12, 1959
C. S. File No. 49/50

Section Corner to Sections 17, 18, 19 and 20.
Found - Orig. 20", now 40" Fir S.73°E. 79.2 ft., shows parts of
good bank scribing.
Orig. 40", now down 50" R. Fir N.23°E. 10.6 ft. Old
axe marks found, no scribing.
Orig. S.W. & N.W. BT's, not found.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
S18 | S17 T28S R7W
S19 | S20
New BT's: 6" Cedar bears N.56°W. 15.8 ft. scribed S18 CS BT.
14" Maple bears S.26°W. 19.2 ft. scribed S19 T28S R7W CS BT.
10" Maple bears S.29 1/2°E. 30.8 ft. scribed T28S R7W S20 CS BT.
5" Cedar bears N.43°E. 42.6 ft. scribed S17 CS BT.
Note - Ravine is approx. 50 feet East of Corner.

121

RE-RENEWED, SEE CORNER NO. #246

James W. Byron
Milo Godfrey
Clete Putnam
Feb. 1961
C.S. File No. 49/79

Renew S4/S3 T28S R7W.
Found - Brass Cap at Corner & S.W. BT.
New BT's: 17" R. Fir bears S.36°W. 36.8 ft. scribed S4 T28S R7W CS BT.
15" R. Fir bears South 51.0 ft. scribed S3 T28S R7W CS BT.
----- (SEE ALSO) -----
Ren. #53
Renew Angle Point S.34°53'W. 74.6 ft. from S4/S3
Found - Brass Cap and N. E. Bearing Tree.
New BT: 11" R. Fir bears N.85°E. 29.2 ft. scribed AP CS BT.
15" R. Fir bears S.72°W. 56.7 ft. scribed AP CS BT.

122

122A

James W. Byron, Deputy
Done For: Douglas County
April 24, 1956
C. S. File No. 47/176
RM 1 - 15

1/4 Corner to Section 28 & 29.
Set 3/4" Iron Rod 16" Below Ground for Corner. - SEE Ren. #88 (DUPLICATE) (RENEWAL)
Blaze & Scribe: 28" Fir S.81°30'W. 31.8 ft. 1/4 S29 CS BT.
30" B. Oak S.86°30'E. 151.5 ft. 1/4 S28 CS BT.
----- (SEE #20) -----
Section Corner to Section 29 - 30 - 31 - 32. (FD OK 3/93) (J. ARTMAN) 1993-002A
Found - 3/4" Iron Rod for Corner. BT's. no good, stumps only. REN #18
44" B. Oak N.76°W. 18.8 ft. Rescribe S30 CS BT. REN #87
36" W. Oak N. 6°E. 27.6 ft. Rescribe S29 CS BT.
Rock bears S.58°30'E. 9.85 ft; 1/2" I. Pipe in Fence Line bears S.85°E. 19.8'.
N. W. Corner of Concrete Steps bears S.3°30'E. 25.05 ft.

123

FD. I.R. OK & FIR
2/10/84
M. HAVIG
C.S. 50/164

124