

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21861

Center 1/4 Cor. Sec. 6 (Ren. # 107)
Found: 14" now 20" W. Fir, alive and in good condition, marked by Boyer in 1958, bears N 75 1/2° W., 64.0 ft. with scribe marks "6" visible on partially healed blaze.
an 18" W. Fir, alive, also marked by Boyer bears N 42° E., 35° ft., (Rec. N 38° E., 35.0 ft.) with scribing "Cen S6 1/16" and other illegible markings on an unhealed blaze.
Note: Record markings for the NE bearing tree are "Cen S6 1581 BT"
We also find an unrecorded 1" I. Pipe bearing N69 1/2° W., 4.8 ft. from the true corner point. At the true corner point determined by the above shown measurements, we set a 1:x30: I. pipe with brass cap attached marked:

DOUGLAS CO. SURVEYOR
1975

T28S
C 1/4 o Sec. 6
R. 7. W

Compass Declination setting: 20° East

1/4 Corner for Secs. 6 and 7. (See Ren. #182)
Found: 24" now 25" fir that bears N 19 1/2° W.; 33.5 ft. distance, alive and well; good scar.
9" now 11" fir that bears S 74° E.; 18.4 ft. distance, healthy, shows good double blaze; grown over.
1" X 24" Iron Pipe at corner point.
Steel fence post set by Boyer in 1965.

Set: 1" X 30" Iron Pipe with brass cap at corner point Mkd.:
County Surveyor
1976

T28S R7W
S6
S7

Set: Line crossing tag east side of BLM road #28-8-12.
Compass Declination setting: 20° East.

Section Corner for Secs. 6, 5, 7 and 8. Ren. #149
Found - A 2" Brass cap, 1924 GLO properly stamped. Cap in good condition but bent toward south. Se straighten & secure in ground.
A 12" Fir, stump, bears N. 47° E., 15.8 ft. scribed "R7W S5 BT" visible. This is a 1928 BT.
A 14" now 16" yewwood bears N. 12 1/2° E., 29.5 ft. scribing visible on partly healed blaze. Ren. #149
A "PK" nail embedded in a snadstone outcrop bears N. 50° E., 28.3 ft. We found no other evidence.
New BT's - A 9" D. Fir bears due South, 33.4 ft. mkd. "T28S R7W X (4"x4") CS BT" in a double blaze.
A 6" D. Fir bears S. 48° W., 70.6 ft. mkd. "T28S R7W S7 CS BT" in a double blaze.

Northwest Corner for Section 5.
Found - 1924 GLO Brass cap properly marked.
A 20" now 18" rotted snag bears S. 41° E., 33.0 ft. Snag scribed "W S5 BT" Ren. #137
A 7" now 18" Fir, bears S. 9° E., 24.3 ft. Tree has well healed blaze.
A 24" now 26" W. Fir, now a windfall bears S. 49° E., 45.0 ft. Tree has well healed blaze.
New BT - A 23" D. Fir, bears S. 83 1/2° E., 55.6 ft. Tree double blazed and scribed "T 28 S R 7 W S 5 CS BT".

SE Corner DLC #54
Found - 3/4" x 29" Iron pipe Ren. #'s 125 and 29
From Which:
An orig. 10" D. Fir, now 23" snag, bears N. 20° W., 24.4 ft. Tree shows large deep healed scar.
A 16" Maple, bears S. 46° E., 12.4 ft. Face is rotted out and tree is dying.
A 24" now 34" W. Fir, bears N. 76° W., 9.3 ft. Tree is alive & shows good scar.

Set - A 1"x30" Brass cap stamped Douglas Co. Surveyor DLC 54
1976 SE Cor. |
T 28 S R 7 W

Replaced found iron pipe on east side of brass cap.

CONT. NEXT PAGE

227

Gary L Langlitz
Greg E. Quibell
Danna L Ingram
C.S. 57/36
10/1/75

228

A. Victor Cangie
James H. Cook
County Surveyors
C.S. 59/8
4-1-76

229

A. Victor Cangie
Jim H. Cook
Co. Surveyors Office
April 27, 1976
C.S. 59/8

230

L.E. Monrean
P. Earle
A. Cangie
Do. Co. Surveyor
Office
July 8, 1976
C.S. 59/18

231

A. Victor Cangie
Karen Cheney
Doug. Co. Surveyors Office
Aug. 26, 1976
C.S. 59/18

P.D. 2/84
O.S. H.D.
C.S. 58/164