

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

231

A. Vic Cangie
Karen Cheney
Doug. Co. Surveyor's
Office
Aug. 26, 1976
C.S. 59/18

SE Cor. DLC #54 CONT. From last page
New BT's - A 6" D. Fir, bears N.2 1/2°E., 15.1 ft. mkd. "SE DLC
54 CS BT" in a double blaze.
A 9" D. Fir, bears S.35 1/2°E., 33.5 ft. mkd. "SE DLC 54
CS BT" in a double blaze.
8/26/76

232

Section Corner for Secs. 4, 5, 8 and 9.
Found - No trace of brass cap set in 1924. Did not find any orig.
or 1924 resurvey bearing trees. Ren. #144
Three BT's from 1961 renewal still standing from which I
set a brass cap after opening a white oak & finding scribing
"T28S R7W S4 CS" on the upper blaze.
Set - Brass cap at section corner stamped:
"Douglas County Surveyor's Office"

T 28 S	R 7 W
S 5	S 4
S 8	S 9
1976	

From which:

A W. Oak 6" now 8" bears N.41°E., 27.3 ft. Tree double blazed &
scribed "T28S R7W S4 CS" on upper blaze. The lower blaze is well
healed.
A W. Oak 5" now 7" bears N.19°E., 23.5 ft. Tree has well healed
double blaze.
An 18" R. Fir, now 24" bears S.2 1/2°E., 56.0 ft. (Rec. S.5 1/2°E.)
Tree has well healed double blaze.
An 18" Cedar, now a windfall, bears S.61 1/2°W., 49.5 ft. Tree
laying with blaze down.
New BT - A 7" I. Cedar, bears N.65 1/2°W., 26.1 ft. Tree double blazed &
scribed "T28S R7W S5 CS BT".

10/4/76

233

Corner for Secs. 6 and 7 only, West boundary.
Found - 1924 GLO brass cap, properly marked and firmly set.
A 12" now 16" Fir, bears S.71°E., 11.0 ft. (Rec. 10.6 ft.)
Tree has well healed blaze.
A 14" Fir now a windfall, bears N.28°E., 14.5 ft.
An. orig. 20" now 26" Fir stump bears S.30°E., 11.2 ft. Stump
has old blaze.
An Orig. 18" now 28" Fir bears N.72°W., 7.9 ft. Tree has poorly
healed blaze.
All other BT's are gone.
New BT - A 14" D. Fir bears N.80 1/2°E., 48.3 ft. Tree double blazed and
scribed "T28S R7W S6 CS BT".

12/6/76

234

West 1/4 Corner for Sec. 7 only.
Found - 1924 GLO brass cap properly marked and firmly set.
A 7" Cedar now 13" bears N.19°E., 27.7 ft. Tree has well healed
blaze.
A 14" Cedar now 18" bears S.73°E., 34.3 ft. Tree has well healed
blaze.

NO RENEWAL.

12/6/76

235

1/4 Corner for Secs. 14 and 23.
Found - Sandstone set by Frear in 1917 Ren. #70 NOT FOUND.
Brass cap set by Byron in 1961 Ren. #163 found lying on the ground.
The only remaining orig. BT, an orig. 15" now 25" W. Oak, previously
opened by Byron, pieces of wood with illegible reverse scribing
found near base of BT. Bears S.77°E., 153.8 ft. (Rec. S.77°E., 158.4)
A 20" now 23" I. Cedar with scribing "1/4 S14 CS BT" visible on
an unhealed single blaze. Ren. #163 bears N.31 1/2°E., 85.8 ft.
A 10" now 12" B. Oak, alive and well healed. bears N.31°W., 34.7 ft.
Set - We add the markings "Reset 1977" to the brass cap previously marked
and set the monument 22" in the ground at the position determined
by Frear as being the best position to resolve the conflicts he not
in the distances to the orig. bearing trees.

2/24/77

L. E. Monrean, Doug. Co. Surveyor's Office
P. L. Earle
Oct. 4, 1976
C.S. 59/24

Larry E. Monrean, Doug. Co. Surveyors
P. L. Earle
K. Cheney
Dec. 6, 1976
C.S. 59/26

Gary L. Langlitz
Doug. Co. Surveyors
Office
Stephen J. Flause
Gorda Taylor
Feb. 24, 1977
C.S. 59/29

3-77