

Douglas County Surveyor's Record of
Government Corners Renewed

T 28

T. S.

R 7

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE., 21881

245

1/4 Corner for Sec. 33; and Sec. 4 of T.29-7

Found - No original post found.

A 6" x 12" quartz rock (origin unknown) now 13" x 8" x 6" quartz rock as used in 1957 survey by A. Boyer and 1973 survey by G. Baughman, M 12 - 72 and RM 2 - 46 respectively, Douglas Co. records. No marks on stone.

A 40" diam. B. Oak with previously cut out blaze, rotted center bears S.25°E., 106.3 ft. dist. (Rec. brg. & dist.) This tree was referred to as the orig. 6" B. oak in the above mentioned surveys. No visible scribe found.

Set - A 1" x 30" iron pipe with brass cap stamped "Douglas County Surveyor T28S 1/4 S33 R7W S4 T29S 1982", at record bearing & distance from 40" oak, which is the position of found stone, protruding 10" above the ground with quartz rock along south side of cap. Set this corner to perpetuate a used corner position.

New Accessories:

A 13" diam. B. Oak scribed "1/4 S4 CS BT" in a double blaze bears S.11 3/4°W., 128.1 ft. dist.

A 5/8" x 30" iron rod with alum. cap stamped "BO 1" and Douglas Co Surveyor, bears N.43°W., 32.95 ft. dist. Set flush with ground.

A 5/8" x 30" iron rod with alum. cap stamped "BO 2" and Douglas Co Surveyor, bears N.62°E., 35.60 ft. dist. Set flush with ground.

No other trees within reasonable range.

Corner falls on a west slope 0.9 ft. west of a N-S fence.

8/24/82

Section corner for Secs. 17, 18, 19 and 20.

Found - 1959 County brass cap, properly marked, on 1" iron pipe, **246**

bent over to the east, nearly out of the ground. Ren. #121

Orig. 20" now 32" fir with faint bark scribing, bears S.73°E., 79.2 ft. This tree is across ravine from corner.

14" now 15" double trunk maple bears S.26°W., 18.7 ft. (Rec. 19.2 ft. checks center of blazed trunk). Has well healed blaze.

10" now 12" maple bears S.29 1/2°E., 30.8 ft. Tree has well healed blaze. Ren. #121

5" now 8" cedar bears N.43°E., 41.1 ft. (Rec. 42.6 ft.) Has a well healed blaze. Ren. #121.

NW cedar BT is down.

Set - Reset monument at corner position.

New BT - 6" I. cedar double blazed & scribed "S18 CS BT" bears N.10°W., 44.9 ft.

Note - This corner lies on a steep easterly slope about 50 ft. west of ravine bottom.

10/7/83

1/4 Corner for Secs. 25 and 36. **247**

Found - 1958 County brass cap on 1 1/2" iron pipe protruding 13 1/2" above ground. Cap properly marked. Ren. #105

Orig. 20" W. oak, now 30" diam. hollowed out tree still alive No scribing visible, bears N.10°W., 26.4 ft.

Orig. 18" B. oak now a depression in the ground, no remains of BT, bears S.42°W., 57.4 ft.

16" now 22" diam. fir stump, 4 1/2 ft. high, with well healed double blaze, bears N.82°E., 38.1 ft. (Rec. 37.6 ft.) Ren. #105

8" W. oak, now 9" dia. with well healed double blaze bears S.21°W., 6.0 ft. Ren. #105

New BTs - 10" B. oak double blazed and scribed "1/4 S36 CS BT" bears S.59°E 44.5 ft.

10" D. fir double blazed and scribed "1/4 S36 CS BT" bears S.75°W., 19.5 ft.

This corner lies 5 ft. south of a east, west fenceline on a small knoll approx. 1000 ft. south of State Hwy. #42.

12/5/83

Karen Reed, Deputy
Doug. Co. Surveyors
Office
Terrie Plouff
Aug. 24, 1982
C.S. 62/1

Larry E. Monrean
Deputy, Doug. Co.
Surveyors Office
J. M. Powell
Oct. 7, 1983
C.S. 62/9

Randall Smith
P.L. Bair
Dougl. Co. Surveyors
Office
Dec. 5, 1983
C.S. 62/9