

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28

T. S.

R 7

R. W. W. M.

ROXE-CHAPMAN CO., EUGENE, ORE. 97501

261

Witness corner for Sections 35 and 36 only of T.27-7

Found - 1924 GLO disk on a 2" I.P. protruding 6 ins. above ground and properly marked.

(No original evidence found.)

5" now a 29" W. Oak with a well healed single blaze bears N.5°W., 27.1 ft. (Per 1924 Mensch survey)

NW corner of house bears S.35 1/2°E., 196.7 ft. (Rec. 195.4 ft.) Per 1924 Mensch resurvey.)

A 5/8" Iron rod protrudes 16" above ground bears East, 60 ft. (Rec. S.89°53'W.) (Per M43-38) Top of I.R. bent East.

(No evidence found of barn per Mensch 1924 resurvey)

New Accessory:

The NE corner of brick chimney at 7925 Lookingglass Road bears S.51 3/4°W., 77.7 ft.

Corner is approx. 0.5 miles south of Lookingglass on the west side of Lookingglass Road. (Co. Rd. #47) (Sketch in C.S. file.)

4/18/85

Section Corner to Sections 19 and 30 only. REN. #173

262

Found - 1924 GLO survey disk on an iron pipe, protruding 5 ins. above ground, and leaning 5 ins. west, properly marked.

Monument returned to plumb, firmly set and protruding 8 ins. above ground.

10" now tipped out and down badly rotted oak, no marks found, a depression in ground bears N.33°E., 29 ft. Agrees with rec. (Original)

12" now a 17" diam. Doug. Fir, with a fully healed double blaze, bears S.61°E., 11.2 ft. Agrees with record. (1924 resurvey)

27" now a 27" diam., 4 ft. high Doug. Fir stump, with a fully healed lower blaze and a partially healed upper blaze with scribing visible "W S19 CS". Bears N.35°E., 5.0 ft. Agrees with record. (Ren. #173)

New BT"s - 16" D. Fir, double blazed and scribed "T28S R7W S30 CS BT", bears S.29 3/4°E., 26.9 ft.

7" madrone, bark scribed "T28S R7W S19 CS BT", bears N.29°E., 29.6 ft.

Corner lies on steep NW slope.

Northwest corner DLC #56 (AP 5 - Tr. 63)

263

Found - A 1924 GLO 1" I.P. with brass cap, properly mkd., protruding 12" above ground. Top of BC/IP is bent 3" south of plumb position.

A 5" wide x 3/8" thick iron bar 1" below ground found along north east edge of BC/IP (possible iron bar set per Ren. #38)

1" iron pipe found by GLO in 1924 was looked for but not found.

30" now 38" dia. B. oak with a fully healed double blaze bears S.1 1/2°E., 85.1 ft. (Rec. S.1 1/2°E., 84.2 ft. is a possible face measurement) Ren. No. 38

30" now 27" dia. 5 ft. high rotted pine stump, no blazes or scribing found, bears N.42 1/2°W., 96.0 ft. (Rec. N.42 1/2°W., 94.8 ft. is a possible face measurement) Ren. No. 38

10" now 14" dia. W. oak with a fully healed single blaze, bears N.22 1/2°E., 20.5 ft. (agrees with rec.) 1924 retracement

10" now 15" dia. W. oak with a fully healed single blaze bears S.40 1/2°E., 77.8 ft. (Rec. S.40 1/2°E., 76.6 ft. is a possible face measurement) 1924 retracement

(Bearings and distances taken to plumb position of 1924 GLO BC/IP.)

Corner lies 1 1/2 ft. north of corner post to an east and south running fence lines.

6/15/87

Larry Monrean, Deputy  
Doug. Co. Surveyors  
Office  
Randall Smith  
Stephen J. Flause  
April 18, 1985  
C.S. 62/25

Doug. Co. Surveyor's  
Office  
Randall W. Smith, &  
Stephen J. Flause  
June 26, 1985  
C.S. 62/28

Douglas County  
Surveyors Office  
R. Smith - S. Flause  
June 15, 1987  
C. S. 62/45