

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

1/4 Section Corner to Section 29 & 28.

Found - 28 inch Fir Stump, bark scribed "BT" near top of cut n $83\frac{1}{2}^{\circ}E$ 13.5 ft.
This Corner renewed by Frear, 1936, See Road Survey Notes.

Set Brass Cap at Corner marked 1/4 S 29|28 T 28S, R 8W, County Surveyor's Office, 1957

New Bearing Trees: 12 inch W. Fir bears N $10^{\circ}E$ 20.5 ft scribed 1/4 S 28 CS BT.
17 inch R. Fir bears N $77^{\circ}W$ 45.5 ft. scribed 1/4 S 29 CS BT.

Note: (Concerning above 1/4 Corner and 1/4 Corner 29 and 32.)

I can find no evidence of original BTs or Eppstein's BTs to support either of these corners. I do find BLM tags on trees at each corner indicating they have been used as true corners.

59
Fol. ok 2/1/69
1/6/69
1/13/69
1/19/69
J. Fee
July & August, 1957
C.S. File No. 49/5

James W. Byron, Dep. Co. Surveyor
M. Godfrey

Section Corner to Section 20, 21, 29, & 28.

Found - 20 inch now 40 inch R. Fir S $30^{\circ}E$ 25.1 ft. I open old face & fine good scribing "BT". Also find 50 inch R. Fir N $10^{\circ}E$ 17.8 ft. which is record bearing & distance for original N.E. BT. I open & find old face but no scribe markings found.

Set Brass Cap at corner marked County Surveyor's Office, 1957 Sec 20|21 T28S, R 8W 29|28

New Bearing Trees:
10 inch R. Fir bears S $46\frac{1}{2}^{\circ}E$ 41.6 ft. scribed S28 T 28S, R8W CS BT.
50 inch R. Fir bears N $10^{\circ}E$ 17.8 ft. rescribed old face S 21 T 28S, R 8W, CS BT.
8 inch Maple bears N $16^{\circ}W$ 13.6 ft. scribed S 20 CS BT.
6 inch Chinquapin bears S $34\frac{1}{2}^{\circ}W$ 26.0 ft scribed S 29 CS BT.

60

Renew Section Corner to Sections 14, 13, 23, & 24. See Rev. # 8

Found - All four BTs. as renewed by Boyer, 1939. N. W. BT partly open, scribing visible. All other BTs have closed faces. I do not open. All BTs alive & in good condition & all check for bearings & distance.

Set Brass Cap at corner marked County Surveyor's Office, 1957.s. 14|13 T.28S, R.8W. 119 23|24

Note - No new BTs.

Aug. 29, 1957

61

1/4 Section Corner to Sections 2 and 11.

Found - Scribed Yew Wood post 4x4"X20" long - scribed "1/4 S., 11, CS, 2". Cedar tree, now 48 inch diameter, N. $18^{\circ}E$ 10.7 feet - face not completely grown over showing scribe "1/4 S. 2 CS". Does not appear old enough for original, probably refaced & rescribed by Eppstein in 1930.
10 inch W. Fir N. $55^{\circ}W$, 13.8 feet showing 2 good scars.
22 inch Douglas Fir S. $77^{\circ}E$, 19.2 feet showing 2 good scars. I did not chop out scar on either of these trees. All trees are alive & apparently in good condition except that White Fir is partly uprooted & leaning badly.

Corner Post is in a fairly new E. & W. Fence Line.

Set an iron pipe at corner, with brass cap stamped County Surveyors Office, 1957 1/4 S. 2 T. 28S., R. 8W.

Aug. 27, 1957

62

1/4 Section Corner to Section 11 & 12.

Found - Steel axle set by Eppstein in 1930. - Rev. # 37
White Fir, (now 30 inches in diameter, N. $35^{\circ}E$, 121.4 feet, showing good scars.

White Fir stump, now 32 inches in diameter, N. $44^{\circ}W$, 96.6 feet, chopped out blaze & found BT scribe in good condition. Old rotted Fir stump bears N. $86^{\circ}W$, 15.6 feet. A clump of small Chinquapins bears S. $20^{\circ}E$, 13 feet.

Mark one new tree: A 8 inch Douglas Fir bears S. $88^{\circ}W$, 19.4 feet scribe 1/4 S. 11 CS. BT.

Aug. 28, 1957

63

Renew Section Corner to Sections 11|12 SEE BLM Resurvey

14|13 VOL. 48 PG 1825A

Found - 1 1/2 inch steel axle at corner.

Douglas Fir, now 7" diam., N. $39^{\circ}W$, 51.2 ft., chopped out lower blaze and found scribe "B:T." very plain. Rev. # 2

Rotted Remnants of Oak Stump, N. $52^{\circ}E$, 25.5 ft. (to center). No scribing found. Stump was too far gone.

No evidence found of other original bearing trees.

Mark New Trees: 7" Madrone S. $49^{\circ}W$. 22.2 ft. scribe, T. 28S, R8W. S14 CS. BT. (7" Madrone S. $70^{\circ}E$. 7.5 Ft. scribe T28S. R8W. S. 13) CS. BT.
6" Madrone N. $73^{\circ}E$. 11.1 ft. scribe T. 28S, R8W. S12 CS. BT.

64

James W. Byron, Deputy Co. Surveyor
M. Godfrey
J. Fee
August 28, 1957 - C.S. File No. 49/12