

Douglas County Surveyor's Record of
Government Corners Renewed

28 T. S. 8 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

92

$\frac{1}{4}$ Section Corner to Sections 5 and 8.
Found - $\frac{1}{2}$ " Gal. Iron Pipe on west R/W of Reston Co. Rd. &
2 old "X's" which I counted the rings to determine
the age of said "X's" to be 24 yrs. (or about 1936). I accepted
this as the location of the Orig. corner because it fit the call
on top of the ridge as per original field notes & on the strength
of a penciled notation in Vol. 14, Pg. 5829, G.L.O. Field notes
filed in the office of the County Surveyor of Doug. Co., Oreg. &
I quote: "16" Hem. N.35°E. 30 lks. This is only tree standing
and it is in decay. August, 1936. CCC truck trail locator reports:
A truck trail might destroy this tree but he will put in a pipe at the
corner if it does and will mark some other trees. A Chestnut
8" S.43°W. 78 lks." End of quote.
I found very old blazes running west from this pipe. The timber
to the east is small 2nd growth now and no blazes could be found.
From this pipe a point N.35°E. 30 lks. (The location of the BT.
at that time would fall in the existing road. 149
Set - Steel tube with survey cap alongside pipe in mound of
Stone. Scribed: 16" Fir N.30°E. 17.4 ft.
16" Fir S.21°E. 6.7 ft.
Note - This corner falls 24 ft. west of the center of Reston
Ridge County Road.

G. Robert Lecklider
Witness: Dale McFarland
January 1961
C. S. File No. 51/162

93

Section Corner to Section 3 and 4 only. 713
Found - 14" Cedar At corner; scribe visible but decaying.
26" Cedar S.80°E. 17.8 ft., overgrown. Rescribe Same.
S. W. BT. gone; No other tree in SW quad. within limits.
Set - Drove steel tube with survey cap in base of 14" Cedar
Corner Tree.
Notes - This corner falls on steep rocky south slope about 2 chns.
south of main E-W ridge. The SW quadrant has been
logged. There is a yellow tag at the corner & cruisers marks.

94

North Line of T28-8W. - South $\frac{1}{4}$ Sec. 36, T27-8W.
Found - Both BT's. as recorded by Johnson, but do not find
 $\frac{1}{2}$ " I. R. set at Corner. -SEE REN. #2, T.27-8
Orig. 10", now 18" down B.Oak N.42 $\frac{1}{2}$ °W. 72.6 ft., previously
opened, shows good scribing " $\frac{1}{4}$ ". Also find Stump Section
in place.
Orig. N.E. BT. not found. Recorded by Johnson as found.
Johnson's BT's, now Snags thus: B.Oak N.74°W. 102.0 ft.;
B.Oak N.10°E. 70.5 ft. (Johnson N.11 $\frac{1}{2}$ °E. 67.0 ft.)
(Johnson N.82°W. 90.0 ft.)
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
South $\frac{1}{4}$ S36 T27SR8W.
New BT's: 17" R.Fir bears N.6 $\frac{1}{2}$ °E. 33.9 ft. scribed S $\frac{1}{4}$ S36 CS BT.
18" R.Fir bears N.80°W. 39.6 ft. scribed $\frac{1}{4}$ S36 CS BT.
Note - The North $\frac{1}{4}$ Corner Section 1 T28-8W bears N.86°E. 594.9 ft.,
Record East 594.0 ft.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
March 1961
C.S. File No. 49/12

95

Section Corner to Sections 1 and 2 only.
Found - Both BT's. as recorded by Ramsey, 1960. S.E. BT., now
stump, scribing visible. SW. BT., now down, felled by
loggers. Iron Pipe at Corner not found. -REN. #88
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961
T27S R8W
S2/S 1 T28S
New BT's: 32" Laurel bears N.14°E. 114.6 ft. scribed S 1 & 2 T28SR8W CS BT.
12" R.Fir bears S. 2 $\frac{1}{2}$ °W. 73.2 ft. scribed S2 T28S R8W CS BT.

- E.O. OR. 3/15 - V. HILLING M. 55-57

RE-RENEWED
CORNER NO. #184