

Douglas County Surveyor's Record of  
Government Corners Renewed

28 T. S. 8 R. W. W. M.

WAKE-CHAPMAN CO., EUGENE, ORE. 97196

Erroneously put in T28/R7.

Corner to Secs. 3, 4, 9, 10.

NOT IN T28SR8W

96

Renew Corner, Set Oak Post from original trees which bear as follows:

Deputy  
Floyd Cole  
July 5, 1913

- Fir 15" in Diam. bears N. 62° E. dist. 47 lks.
- Fir 8" in Diam. bears S. 38° E. dist. 75 lks.
- Fir 36" in Diam. bears S. 70° W. dist. 85 lks.
- Fir 16" in Diam. bears N. 60° W. dist. 96 lks.

Renew AP 3  
Tract 62 S 36 T28S R8W  
AP 2 Tract 63

97

Found - Brass Cap & N. E. BT., good condition.  
Stump of S. E. BT.

New BT: 18" R. Fir bears S. 6° E. 17.0 ft. scribed AP 2 Tr. 63 CS BT.

Renew E 1/4 Corner Section 36, T28 - 8W.

98

Found - 1" I. P. at Corner & Orig. 24", now 36" Fir Stump N. 87° W. 21.1 ft.

We open near base and find good scribing "BT" - Ren # 30A

Brass Cap not found & no other BT's, of record found. # 194

Set - Brass Cap at Corner & under 4' Log Mkd: County Surveyor's Office, 1961

New BT: 12" R. Fir bears S. 41° E. 54.8 ft. scribed 1/4 S36 CS BT.  
No other trees near.

Corner to Sec. 36, T28 8W. & Sec. 1, T29 8W.

Found - Brass Cap in E. W. Fence line. BT's still alive.

N. E. BT., center rotted, shows good reverse scribing "W 28".

New BT: 6" W. Oak bears N. 9° E. 26.4 ft. scribed T28S R8W CS BT.

99

1/4 Corner Sec. 1, T28-8W. & Sec. 6 T28-7 1/2 W.

100

Found Brass Cap. N.W. BT. now stump. S.E. BT. is O.K.

New BT: 17" R. Fir bears N. 70° W. 37.0 ft., recently scribed 1/4 S1 and other scribing.

FOOK  
R. GEISLER  
11/25-1/26  
M 90-79

Section Corner to Secs. 12 & 13, T28-8W. & Secs. 7 & 18, T28-7 1/2 W.

101

Found - Brass Cap at Corner.

36" Fir S. 80° W. 6.6 ft., alive & in good condition.

Dogwood, down & dead, S. 74° E. 12.5 ft., showing old scribing.

30" Fir, dead snag, N. 17° E. 38.9 ft.

36" Fir, uprooted & dead, N. 26° W. 34.3 ft.

New BT: 18" D. Fir N. 54 1/2° W. 77.0 ft. scribed T28S R8W S12 CS BT.

1/4 Corner to Sec. 12, T28-8W. & Sec. 7, T28-7 1/2 W.

102

Found - Brass Cap at Corner. S.E. BT. is O.K. S.W. BT. now stump.

New BT: 12" R. Fir bears N. 5° W. 14.2 ft. scribed 1/4 S12 CS BT.

1/4 Corner Sec. 13, T28-8W. & Sec. 18, T28-7 1/2 W.

103

Found - Brass Cap at Corner. N.E. BT., now snag. N.W. BT. O.R.

New BT: 12" W. Fir bears S. 5° E. 13.5 ft. scribed 1/4 S18 6S BT.

1/4 Section Corner to Sec. 24, T28-8W. & Sec. 19, T28-7 1/2 W.

104

Found - Both BT's., each shows good scars but have rotted centers.

Find Stone at Corner but do not find "+" nor any marks.

We drill Hole in Rock & Set 1/2" x 12" I. R. at Corner & 3/4" x 30" I. R. alongside, rods set in concrete.

New BT's: 6" W. Oak bears S. 22° W. 20.5 ft. scribed 1/4 S24 CS BT.

7" W. Oak bears S. 58° E. 22.0 ft. scribed 1/4 S19 CS BT.

Note - Bearing & Distance to East 1/4 Corner Section 19, T28-7 1/2 W. checks OK.

105

Section Corner to Sections 24 & 25, T28-8W. & Secs. 19 & 30, T28-7 1/2 W.

Found - Brass Cap at Corner & Stump of S.E. BT., shows good scribing.  
No trace of other BT's.

Also Sec # 30A

(over)

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
April 1961  
C.S. File No. 49/50

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
May 5 - 6 1961  
C.S. File No. 52/79

May 1961  
C. S. File No. 52/79