

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Marvin C. Ramsey, RS404  
For Southern Oregon Plywood, Grants Pass, Oregon  
July 17, 1962 - August 10, 1962  
C. S. File No. 51/242

$\frac{1}{4}$  Section Corner to Sections 5 and 4. 108  
38.99 chains - Point for the  $\frac{1}{4}$  sec. cor. at proportionate distance.  
Find no evidence of the Original Corner.  
Set - Iron Pipe 3 ft. long  $1\frac{1}{2}$  ins. diam., 28 ins in the ground,  
mkd. RS404 from which:  
D. Fir 24" diam., bears S.11°E. 16 lks. dist. mkd.  $\frac{1}{4}$  S4 RS404 BT.  
D. Fir 12" diam., bears N. 82°W., 12 lks. dist. mkd.  $\frac{1}{4}$  S5 RS404 BT.

See 1975  
Re-survey

78.83 Chains - Point for the sec. cor. of Secs. 4 - 5 - 8 and 9. 109  
Determined by double proportion. Find no evidence of Orig. Sec. Cor.  
Set - Iron Pipe 3 ft. long, 2 ins. diam., 28 ins. in the ground,  
mkd. RS404 from which new bearing trees:  
8" D. Fir bears N.18°E., 10 lks. dist., mkd. T28S R8W S4 RS404 BT.  
8" D. Fir bears S.44°E. 18 lks. dist., mkd. T28S R8W S9 RS404 BT.  
10" D. Fir bears S.26°W. 3 lks. dist., mkd. T28S R8W S8 RS404 BT.  
18" D. Fir bears N.31°W. 56 lks. dist., mkd. T28S R8W S5 RS404 BT.

See 1975  
Re-survey

$\frac{1}{4}$  Section Corner to Sections 8 and 9. 110  
39.84 ch. point for the  $\frac{1}{4}$  cor. at proportionate distance.  
Find no evidence of the original corner  
Set - an iron pipe 3 ft. long  $1\frac{1}{2}$  ins. diam., 28 ins. in the  
ground, from which:  
12" D. Fir bears S.84°E. 19 lks. mkd.  $\frac{1}{4}$  S9 RS404 BT.  
8" D. Fir bears S.9 $\frac{1}{2}$ °W. 16 lks. mkd.  $\frac{1}{4}$  S8 RS404 BT.

$\frac{1}{4}$  Section Corner to Sections 4 and 9. 111  
40.84 ch.-Point for the  $\frac{1}{4}$  sec. cor. at proportionate dist.  
Find no evidence of the original corner.  
Set - Iron Pipe 3 ft. long  $1\frac{1}{2}$ " diam., 28" in the ground, mkd. RS404, from wh:  
18" D. Fir bears N.57°E. 8 lks. mkd.  $\frac{1}{4}$  S4 RS404 BT.  
10" D. Fir bears S.53°W. 9 lks. mkd.  $\frac{1}{4}$  S9 RS404 BT.

See 1975  
Re-survey  
SEE 1987  
Corrective  
Survey

Center  $\frac{1}{4}$  Corner to Section 4. 112  
Point for the center  $\frac{1}{4}$  sec. cor. at the intersection of  
North and South center line.  
Set - Iron Pipe 3 ft. long,  $1\frac{1}{2}$ " diam., 28" in ground, mkd. RS404 from which:  
8" Madrona bears N.42°E. 108 lks. dist., mkd. C  $\frac{1}{4}$  S4 RS 404 BT.  
30" D. Fir bears S.70 $\frac{1}{2}$ °E. 89 lks. mkd. C  $\frac{1}{4}$  S4 RS 404 BT.  
48" D. Fir bears S.52 $\frac{1}{2}$ °W. 85 lks. mkd. C  $\frac{1}{4}$  S4 RS 404 BT.

$\frac{1}{4}$  Section corner of Sections 3 and 4. 113  
Established by A. Boyer, July 16, 1953.  
Find - Fir Post from which: *REN. # 21*  
12" Hemlock bears S.71°E. 30 lks. mkd.  $\frac{1}{4}$  S3 BT.  
17" Hemlock bears N.24 $\frac{1}{2}$ °W. 35 lks. mkd.  $\frac{1}{4}$  S4 BT.  
Set - In place of the Fir Post an Iron Pipe 3 ft. long  $1\frac{1}{2}$ " diam.,  
28" in the ground, mkd. RS404.

RE-RENEWED CORNER NO. # 192

$\frac{1}{4}$  Corner for Sections 27 and 28. 114  
Found - 18" Cedar S. 1°E. 24 lks. (now 36")  
24" Fir S.60°W. 19 lks. (now a stump)  
Set - 4" x 4" x 4ft. Post & Scribed a 4" Fir S.48°W. 10.0 ft. 125

$\frac{1}{4}$  Corner for Sections 2 and 3. 114-A  
Found - 36" Fir N.39 $\frac{1}{2}$ °E. 18 lks. (snag - bark scribe)  
30" Fir S.37°W. 21 lks. (snag - bark scribe)  
Set - 4" x 4" x 4 ft. Yew Post.  
Scribed: 12" Yew N.45°W. 26.0 ft.  
8" Yew N.25°E. 64.7 ft. 126

RE-RENEWED CORNER NO. 126

Howard W. Johnstone  
For Roseburg Lumber Co.  
Wit. J. Clark & R.  
Hendrickson  
August 24, 1962  
C.S. File No. 51/163