

Douglas County Surveyor's Record of
Government Corners Renewed

28

T. S.

8

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

115

Corner to Sections 32 and 33 only, T27-8W.
North Boundary of T28S R8W.

Found - Brass Cap at Corner. N. E. BT. has been cut.
26" Hemlock N.11°W. 21.1 ft. O.K., shows good scribing.

New BT: 36" Cedar bears N. 2° E. 39.9 ft. scribed S33 T27S R8W CS

James W. Byron
& Crew
June 1963
C.S. File
BT. 49/79

116

1/4 Section Corner to Sections 20 and 29.

Found - Orig. 20", now 36" Fir Stump S.60°E. 18.5 ft., shows reverse scribing.

Orig. 18", now 30" Fir Stump North 18.5 ft., not N.10°W.
18.5 ft., shows burned area that may have been old face.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 1/4 S20 T28S R8W S29

New BT's: 23" Cedar bears S.29°E. 32.2 ft. scribed 1/4 S29 CS BT.

15" R.Fir bears N.35°W. 66.0 ft. scribed 1/4 S20 CS BT.

Byron &
Crew
10/25/63
C.S. File
No. 52/79

Section Corner to Sections 19 - 20 - 29 - 30.

Found - Orig. BT's., except S.E. BT. N.E. BT. shows bark scribing
on old stump. S.W. BT., now snag with large log against
face. N.W. BT. low cut stump.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 S19 | S20 T28-8W S30 | S29

New BT's: 5" R. Fir bears N.35°E. 29.3 ft. scribed S20 CS BT.

10" Hemlock bears S.77°W. 55.6 ft. scribed S30 CS BT. T28S R8W.

12" Hemlock bears N.69°W. 30.3 ft. scribed S19 T28S R8W CS BT.

10" Cedar bears S. 2°E. 38.8 ft. scribed S29 T28S R8W CS BT.

Byron &
Crew
11/22/63
C. S. File
No. 52/79

118

1/4 Corner to Sections 23 and 24.

Found - 1" I.Rod in N.-S. Fence & both BT's. (See Ren. #5 & 65).
W.Oak to SE down, W.Oak to S.W. is a snag.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964 T28S R8W S23/S24 -Set I.R. alongside.

New BT: 10" Northern B. 8 1/2° E. 11.3 ft. Mkd: 1/4 S23 CS BT.

No other trees available to N.W.

This corner lies approx. 175.0 ft. N. of Reston-Tenmile Road.

Nov. 1962 - 64/77
B.C. REMOVED
REF. WITH I. RODS
SEE M 49-10
WILL BE C.S.
REPLACED
SMP
5/1/30

119

Section Corner to Sections 13 - 14 - 23 - 24.

Found - No trace of Brass Cap (See Ren. # 8 & #61)

Two of the Four BT's are dead. Other BT's are turned
out & slid down hill. Dead BT's. as below:

8" Fir S.40°W.? 22.5 ft., recorded as S.30°W., shows
scribe marks & is a snag.

15" Fir N.85°E. 17.0 ft. is a stump & has a healed over face,
visible on top.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964 T28S R8W S14 | S13 S23 | S24

New BT's: 9" D.Fir S.53°W. 59.5 ft. Mkd: T28S R8W S23 CS BT.

14" D.Fir N.55°E. 14.4 ft. Mkd: T28S R8W S13 CS BT.

10" D.Fir S.8°E. 56.6 ft. Mkd: T28S R8W S24 CS BT.

No tree available to N.W.

Vernon R. Tracy
Mike Darby & J. Barnett
Sept. 1964
C. S. File No. 52/79

120

Exterior "L" D.L.C. #41. 22 - 23 - 24 - 25.

Found - 2" Iron Pipe at DLC Corner, See Ren. #17. #30
30" D. Fir, now 34", S. 40° E. 49.0 ft., bark scribing visible.

Set - Brass Cap at DLC Cor. Mkd: County Surveyor's Office, 1966 T28S R8W Ext. L DLC 41/

Reblazed & Rescribed: 34" D.Fir S. 40° E. 49.0 ft. scribed Ext. E DLC 41 CS BT.

Note - This corner lies in fence corner, fences running North & West.

RE-RENEWED, SEE CORNER NO. #183
RE-RENEWED, SEE CORNER NO. #168

FD OK
B.C. 1/3/75
BY BENNY 2/4/75
M117-30