

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell and Vernon R. Tracy  
W. Penley V. Perron  
C. S. File No. 54/113

145

Standard  $\frac{1}{4}$  Corner to Section 4 only, T28-8W.  
Found - 1961 Cadastral Brass Cap, properly set and marked.  
Orig. 25" Fir, alive, S.25°E. 13.2 ft., Rescribe vis. on unhealed blaze.  
10" Hemlock, N.67°W. 13.2 ft., blazes nearly healed. We Tag(Boyer's BT)  
6" Hemlock, broken off 15' high, dying, S.38°W. 23.1 ft., scribe vis.  
New BT: 7" Hemlock S.44°W. 20.8 ft. mkd: " $\frac{1}{4}$  S 4 SC CS BT".  
This cor. lies on top of spur, sloping W. The  $\frac{1}{4}$  cor. of Sec.33, T27-8W.  
bears N.89 $\frac{1}{2}$ °E. 27.1 ft.

5/18/70

146

Section Corner to Sections 32 & 33 only, T27 $\frac{1}{2}$ -8W.  
Found - Only shattered remains of one BT, as follows:  
18" Hemlock N.22 $\frac{1}{2}$ °W. 66.7 ft., dead, shattered stump, frag. scribe  
on portion of blaze.  
No trace of N. E. BT. or 1961 Brass Cap at corner point.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T27 $\frac{1}{2}$  R8W S 32 | S 33  
Office, 1970 T28  
New BT: 30" Hemlock N. 4° W. 112.4 ft. mkd: "T27 $\frac{1}{2}$ S R8W S32 CS BT"  
(This is only suitable tree close)  
Corner was destroyed by large rocks rolling down from new Burnt Mt.  
access road construction & lies on very steep, N.E. slope.  
The Stand. corner of Secs. 4 & 5, T28-8W. is 42.9 ft. S.88°E.

5/15/70

FD OK PER HINTZ  
DEC. 86 - M103-B

147

Standard Corner to Sections 4 and 5, T28-8W.  
Found - 1961 Cadastral Brass Cap, in pipe, with 2" I.P. alongside.  
Orig. 32" Hemlock S.81°E. 7.3 ft., alive & tagged.  
12" Hemlock, alive, S.36°E. 50.2 ft., tagged, blaze nearly healed.  
All other BT's. gone, due to large rocks & logs in fill of new  
Burnt Mt. access road.  
New BT: 32" Hemlock S.1 $\frac{1}{2}$ °W. 63.5 ft. mkd: "T28S R8W S5 SC CS BT".  
This cor. lies on very steep, easterly slope about 125 ft. W. of  
Wilson Creek, course NW.

5/15/70

148

$\frac{1}{4}$  Corner to Section 31 only, T27-8W.  
Found - 10", now 12" Yew, N.10°E. (RecN4OE) 16.5 ft., scribe visible,  
scribe partly done with knife.  
36", now 38" D.Fir, N.50°W. 11.2 ft., shows faint bark scribe "SC" done  
with scribe, definitely old enough. Other bark scribe with  
knife, " $\frac{1}{4}$ S BT".  
Set - Brass Cap at Cor. Mkd: County Surveyor's T27S R8W  $\frac{1}{4}$  S 31  
Office, 1970 T28S  
Reblzd. & Resbd: 38" B.Fir N.50°W. 11.2 ft. mkd: " $\frac{1}{4}$  S31 CS BT".  
New BT: 16" Hemlock N.55° E. 23.7 ft. mkd: " $\frac{1}{4}$  S31 CS BT".

4/23/70

149

$\frac{1}{4}$  Corner to Sections 5 and 8.  
Found -  $\frac{1}{2}$ " Steel Tube with alumn. cap & BT's. called for in Ren. #92.  
16", now 18" Fir, alive, N.30°E. 17.4 ft., blaze healed, we tag. #179  
16", now 18" Fir, alive, S.21°E. 6.7 ft., blaze healed, tagged on road side  
Decayed remnants of Hemlock Stump N.45°E. 19.8 ft. with possible  
portion of old blaze on piece laying on ground, buried. Mr. Lecklider  
was quoting wrong bearing for this tree in his renewal.  
We do not find  $\frac{1}{2}$ " Galv. Iron Pipe, monument used is rusting badly.  
Set - Brass Cap at Cor. mkd: County Surveyor's T 28 S R 8 W  
(Dep. old monument alongside) Office S 5  
1970 S 8  
This corner lies 15 ft. west of the west edge of old Burnt Mt. truck  
trail, See C.S. File 51/242.

4/15/70

150

Section Corner to Secs. 6 & 7, T28-8 and Secs. 12 & 1, T28-9W.  
Found - 36" D.Fir, now stump, S.45°W. 30.4 ft., faint bark scribe.  
30" D.Fir, now stump, S.25°E. 16.5 ft.  
20" D.Fir, now stump N.40°W. 29.0 ft., opened for scribe "T".  
40" D.Fir, now down, N.40°E. 9.2 ft., tree covered with log.

(continued over)