

Douglas County Surveyor's Record of  
Government Corners Renewed

T 28

T. S. R 8

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas Co. Surveyors  
Office  
R.W. Smith  
S. J. Flause  
Aug. 9, 1984  
C.S. 62/21

1/4 Corner for Sections 8 and 17  
Found - 1972 BLM disk on a I.P. protruding 6" above ground properly mkd.  
A 17" now 21" D. fir, 7 ft. high stump with a single well healed  
blaze bears N.13°E., 48.2 ft.  
A 10" D. fir with a single well healed blaze bears S.17°W.,  
9.7 ft. (Rec. S.14°W., is to center of trunk.)  
New BTs - 29" D. Fir double blazed and scribed "1/4 S8 CS BT" bears  
N.49°W., 33.3 ft.  
10" Hemlock double blazed and scribed "1/4 S17 CS BT" bears  
S.28°E., 16.0 ft.

Corner lies on a east slope.

8/9/84

181

James W. Byron  
M. Godfrey  
S. Bilow  
Sept. 19, 1957  
S. C. File No. 49/5

1/4 Corner for Sections 35 and 36.  
(NOTE: THIS IS A 1957 COUNTY RENEWAL BY BYRON THAT WAS ERRONEOUSLY  
MARKED T.27-3 AND RECORDED IN THAT TOWNSHIP CORNER BOOK.) (SEE REN. #3  
for Boyer visit and Ren. #130 for Tracy 1969 visit)

Found - Both of Boyer's renewed BTs. The 36 inch Black Oak now stump  
S.57°W., 42.0 ft. shows rotted face, no scribing found.  
The 18 inch now 22 inch white Oak S.23°30'E., 108.0 ft. has  
rotted face with faint scribe, marks "B 4". Also find what I  
believe to be the original S.55°E., 93.1 feet BT. Checks bearing  
& distance and shows old face, rotted, no scribing found.  
Boyers BTs check bearings & Distances. I can not find Boyers 1/2 inch iron  
pipe.  
Set - Brass cap at corner marked 1/4 S35/36 T.27S, R.3W., County Surveyor  
Office, 1957.  
I blaze & scribe 36" Black Oak stump S.57°W., 42.0 ft. 1/4 S35 CS BT.  
10" forked cedar S.26 1/2°E., 61.4 ft. scribed 1/4S 36CSBT  
11" Fir S.87°E., 96.7 ft. scribed 1/4 S36 CS BT.  
Brass cap is near fence corner, (See sketch in file.)

182

9/19/57

Section corner for Sections 19, 20, 30 and 29

Found - 1963 County disk on a I.P. protruding 15" above ground marked  
County Surveyors Office T28S S19 S20 S30 S29 R 5 W 1963".  
Ren. #117  
Orig. BT, 40" now a 43" dia. 5 ft. high D. fir stump with a flat  
bark blaze and axe marks "X" that do not appear to be orig. bears  
N.65°E., 24.0 ft. (Rec. N.65°E., 21.1 ft.)  
36" now a 42" dia. 4 ft. high D. fir stump, no marks visible bears  
N.20°W., 11.4 ft. (Rec. N.30°W., 10.6 ft.) (Orig.)  
28" now a 30" dia. 25 ft. high D. fir snag, previously opened  
no marks visible, bears S.60°W., 11.9 ft. (agrees with rec.) (orig.)  
SE BT gone.  
5" now a 10" dia. D. fir with a fully healed single blaze bears  
N.32°E., 29.3 ft. (Rec. N.35°E., 29.3 ft.) Ren. #117  
10" now a 20" dia. hemlock with a fully healed single blaze  
bears S.77°W., 55.6 ft. (agrees with rec.)  
12" now a 15" dia. hemlock with a fully healed double blaze  
bears N.69°W., 28.8 ft. to center of root crown (Rec.  
N.69°W., 30.3 ft. to center of trunk) Ren. #117  
10" now a 21" dia. I. cedar with a fully healed double blaze  
bears S.2°E., 38.8 ft. (agrees with record. Ren. #117)

Set - "5" in R 5 W stamped out and remarked with an "8" to correct  
range on brass disk.

No new accessories. Corner lies on a west slope. Using orig. dist. as  
face measurements would move Ren. #117 corner position approx 15 inches  
NE of present location. I don't believe the possible position difference  
is significant enough to set another monument.

10/8/85

Larry E. Monrean,  
Deputy, Douglas Co.  
Surveyors Office  
Randall W. Smith,  
Party Chief;  
Stephen J. Flause,  
Notekeeper, witness.  
Oct. 8, 1985  
C.S. 62/29

183