

Douglas County Surveyor's Record of
Government Corners Renewed

T 28 T.S. R 8 R.W.W.M.

KONE-CHAPMAN CO., EUGENE, ORE. 21881

Ronald Geisler
For: Champion
International Cor.
Nov. 1985/Jan. 1986
M 90 - 79

Section corner for Secs. 1 and 12; and Secs. 6 & 7 of T.28-7½
Found - 1924 GLO 2½" brass cap on a 2" I.P. See also Ren. No. 45
14" fir, uprooted and down, bears S.19°W., 12.5 ft. No scribing.
(Original)
18" fir, now badly spintered stump and downed tree, bears N.37°E.,
23.8 ft. Scribed T28S R7½W. (1924)
13" incense cedar bears S.49°E., 28.5 ft. Closed face. (1957)
New BTs - 10" cedar bears N.42°W., 16.4 ft. scribed T28S R8W S1 BT.
4" fir bears N.17°E., 10.3 ft. scribed X BT.
8" fir bears S.26°W., 27.4 ft. scribed T28S R8W S12 BT.

191

Richard Hintz
For: International
Paper Co.
Dec. 1986 M103 - 8

1/4 Corner Sections 3 & 4.
Found - A 1 1/2" Iron Pipe. See Renewal #113.
BT'S - 14" Hemlock bears S 71°E, 19.8'. Tree down with healed blaze.
18" Hemlock stump bears N 24°30' W, 23.1'. (Cut below blaze).
New Bt's 24" Hemlock bears S36°E, 14.9 '. Scribed "1/4 S 3 BT".
14" Hemlock bears N 23°30' W, 17.5'. Scribed "1/4 S 4 BT".

192

Howard Johnstone
For: Roseburg Lumber
March 19, 1987
C.S. 63/26

1/4 Corner for Sections 8 and 17
Found - 1972 BLM resurvey brass cap in good condition.
22" Fir, N.15° E., 48.2 ft. now a high stump, face overgrown.
10" Fir, S.14° W., 9.9 ft. Low stump 1/2 face remains, overgrown.
29" Fir, N.49° W., 33.3 ft. blaze open. REN.#181
New BT - 7" Hemlock, S.21°W., 40.7 ft. scribed "1/4 S17 BT"
Placed brass tag on face "LS 498. In new clear-cut unit.
Timber is now cut on South and East sides of corner.

193

Douglas County
Surveyors Office
S. J. Flause
R. J. Smith
June 10, 1987
C. S. 62/45

1/4 Corner for Section 36 only. (East)
Found - A 1961 County 2½" Dia. brass cap properly mkd. on a 1" I.D. iron pipe firmly set and protruding 16" above ground. Ren. #98
A 1" Dia. iron pipe from Ren. #30A not evident.
From orig. 1855 Hathorn survey, A 24" Dia. now a 36" Dia. 3 ft. tall fir stump with the scribing "BT" visible in an opened blaze bears N.87°W., 21.2 ft. as per record.
From Ren. #98, a 12" R. fir now a 12" Dia. 2 ft. tall fir stump with rotted blaze on fallen trunk, no scribing found, bears S.41°E., 54.8 ft. as per record.
Not found - 24" B. oak searched for and not found. Ren. #30A.
Southeast 16" fir BT not searched for. Ren. #30A
From 1924 resurvey, no evidence of SW BT found.
Monument position is perpetuated as found.
New BTs - An 11" D.B.H. D. fir scribed "1/4 S36 CS BT" on a double blaze bears N.74½°W., 40.2 ft.
A 10" D.B.H. W. fir scribed "1/4 S36 CS BT" on a double blaze bears S.49½°W., 22.9 ft. distant.
Monument lies in break of steep easterly slope approx. 100± ft. S.09°W. from north-south switch-back in private road.

3/19/87

194

Douglas County
Surveyors office
R. W. Smith
S. J. Flause
June 16, 1987
C. S. 62/45

Southeast corner for Section 36. (CORNER REPORT ONLY)
Found - A 1924 GLO 3½" brass cap properly mkd. on a 3" dia. iron pipe protruding 1 ft. above ground.
10" now 22" dia. W. Oak with a fully healed blaze, reverse scribing is seen through hole in backside of tree "T28S R7W S31" bears N.0½°E., 169.0 ft. Orig. BT, agrees with rec.
12" B. oak now stump hole bears N.5°W., 219.8ft. (N.5°W., 221.10 ft. per 1924 GLO agrees well with rec.). Orig. BT. (Another tree has in the past been mistaken as this BT. We opened it and found no scribing. This is a 21" W. oak which bears N.7½°W., 241.7 ft. with a 1961 BT tag having orig. NW BT bearings and distances marked on tag.)
7" now 11" Dia. W. oak with a single fully healed blaze bears N.21 3/4°W., 109.6 ft. agrees with record. 1924 BT.
No other orig. or 1924 BTs found.
6" now 13" Dia. W. oak with a fully healed double blaze bears N.9°E., 26.4 ft. agrees with record. Ren. No. 99
Corner lies in a west running fence line approx. 100 ft. west from the intersection of a north-south fence and west running fence.

6/10/87

195

6/16/87