

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 28 T. S. R 8 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 91881

Witness Corner for Sections 25 and 36 only.

REFERENCED OUT FOR NEW FIELD BEING ESTABLISHED

Found - 1 1/2" O.D. x 21" long I.P. laying horizontal 2" below ground near position of TRUE corner (Rec. 1" I.P. source unknown).

A 1969 County brass cap on an iron pipe protruding 1 ft. above ground per Ren. #132. 1" iron pipe set by J.W. Cole (County Surveyor, S.C. 5/37) at W.C. not found.

No original BTs found.

14" now 27" dia. Maple with a fully healed single blaze bears N.18 1/2°E., 11.9 ft. (Rec. N.22°E., 11.9 ft.) Per CS 5/37

12" now 24" dia. mult. trunked alder bearings and dists. taken center of trunk to an 18 ft. high snag, with a partially healed blaze, scribe visible "88" bears S.35°W., 26.5 ft. (Rec. S.35°W., 24.4 ft.) Per CS 5/37.

30" now 33" dia. Ash with a partially healed blaze, scribing visible "8W 25 0 T" bears N.30°W., 29.6 ft. (Rec. N.27°W., 29.0 ft.) Per. CS 5/37

SW cor. DLC #39 (DCSO BC/IP) bears west, 470 ft. Agrees with record.

Note: Discrepancies are noted between field notes (C.S. 5/37; Survey map M 1-2; and old renewal records Vol. 1 Pg. 13 #39.) Three BTs scribed in field notes, only two shown on survey map and old renewal records. A distance error on survey map, Maple BT shown as being 14.0 ft. from W.C. corner should be 11.4 ft. according to field notes and old renewal records.

Set - DCSO BC/IP lies in area property owner Donald Standley will develop a new field. Position of BC/IP referenced (see new accessories) then monument removed.

New Accessories:

18" alder with PK nail in blaze, approx. 30" up trunk, bears S.87°W., 60.49 ft.

24" Alder (SW BT) with PK nail in new blaze, approx. 18" up trunk, bears S.42°W., 25.33 ft.

17" Alder with PK nail in blaze, approx. 12" up trunk, bears S.01°W., 45.89 ft.

Witness corner brass cap/iron pipe saved, should be reset below ground when field is finished.

3/25/88

1/4 Corner for Sections 35 and 36

Found - 1957 County 2 1/2" brass cap on a 1 3/8" O.D. Iron pipe protruding 14" above ground. Ren. #182 and #130. Ren. #182 erroneously indicates brass cap mkd. "1/4 S35/36 T.27S R3W County Surveyor Office 1957".

18" now 36" dia. W. Oak with a previously opened blaze no scribing found, bears S.55°E., 93.1 ft. (agrees with rec.) Orig. BT. No evidence of orig. southwest BT found.

18" now 15" dia. W. Oak with a fully healed double blaze bears S.75 1/4°E., 11.0 ft. (Rec. S.73 1/2°E., 110.0 ft.) Ren. #3 Unsure how this tree's dia. determined in past renewals.

36" now 36" dia. 2 ft. high oak stump with illegible scibe marks and axe mark visible bears S.54 3/4°W., 42 ft. (Rec. S.57°W., 42 ft.) Per Ren. #3 and 182

10" cedar now stump hole, bears S.26 1/2°E., 61.4 ft. (agrees with record) Ren. No. 182

11" now 20" dia. D. fir with a fully healed double blaze bears S.87°E., 96.7 ft. (agrees with rec.) Ren. #182

New BT - A double trunked madrone bark scribed "1/4 S35 CS BT" on 7" southeast trunk. Center of root crown bears N.44°W., 29.1 ft.

4/20/89

Section Corner for Sections 34 and 35: and Secs. 2 & 3 of Sec. T29-8

Found - 1 1/4" iron post found loosely set projecting 24" above ground. W/cap. BT by Boyer, a fir snag 17" bears S.70°W., 77 lks. Ren. #57

BTs by Byron:

A fir 11" bears N.21 1/2°E., 25 lks. healed double blaze.

A fir, 14" bears S.8°E., 46 lks. healed double blaze.

A fir, 19" bears N.4 1/4°W., 36 lks. healed double blaze.

Set - Referenced monument and reset 24" in the ground with 8" projecting above ground.

New BT - A fir, 19" bears S.39 1/2°W., 45 lks. mkd. T29S R8W S3 BT.

6/1/89

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
March 25, 1988  
C.S. 59/30

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
April 20, 1989  
C.S. 62/63

Wayne Rogers  
Bureau of Land  
Management  
June 1, 1989  
C.S. 63/87