

Douglas County Surveyor's Record of
Government Corners Renewed

T. 28 S. T. S. R. 9 W. R. W. W. M.

ROKE-CHARMAN CO., EUGENE, ORE. 97331

C.S. Lemonowsky
April 1953
For Coos
Bay Lumber
CS. 41/153

RE-RENEW CORNER NO. #2
Sec. Cor. to Secs. 12 & 13, T28-9W. & Secs. 7 & 18, T28-8W. #2
Set - Stake for this corner from a 60" Fir which bears N. 35° E. 14 lks.
dist., the only BT of the orig. four trees marked.
New BT: 60" Fir S. 27° 15' W. 43.40 ft. dist. for new BT for this corner.

Sec. Cor. to Secs. 12 & 13, T28-9W. & Secs. 7 & 18, T28-8W.
Found - 3x3x36" Stake at corner on shoulder of road & BT's as
recorded by Frear in 1953 except for the Orig. BT's.
which has been removed for road widening.

1953 BT's check for bearings & distance.

Set - Brass Cap 4" under surface mkd. County Surveyor's S 12 | S 7 T28S
Office R9W S 13 | S 18 R8W
1956 Coos Co. Doug. Co.

All trees in this area are to be removed for BPA Line.

I scribe near ground, stumps to remain:

- 6" R. Fir S. 83° E. 26.5 ft. mkd. T28S R8W S18 CS BT.
- 5" R. Fir N. 66° E. 90.0 ft. T28S R8W S7 CS BT (bark scribe)
- 6" R. Fir N. 54° W. 84.0 ft. T28S R9W S12 CS BT. (bark scribe)
- 6" R. Fir S. 41° W. 91.0 ft. T28S R9W S13 CS BT. (bark scribe)

Se.c. Cor. to Sections 19 & 30, T28-8W. & Secs. 24 & 25, T28-9W.

Found - Orig. 8", now 10" dead Yewood, N. 32° W. 26.4 ft., scribe marks vis.
Rotted stumps for S.W. & S.E. BT's. check for bear. & dist.
40" Fir N. 78° E. 20.4 ft. (record N. 78° W. 20.4') shows old face
near base. I do not open.

Set - Brass Cap at Cor. Mkd: County Surveyor's S 24 | S 19 T28S
Office, 1957 R9W S 25 | S 30 R8W

- New BT's: 48" Hemlock N. 85° W. 21.0 ft. mkd. T28S R9W S24 DCS BT.
- 12" Hemlock N. 45½° E. 39.1 ft. mkd. T28S R8W S19 DCS BT.
- 7" Hemlock S. 59° W. 9.8 ft. mkd. T28S R9W S25 DCS BT.
- 10" Hemlock S. 79° E. 17.1 ft. mkd. T28S R8W S30 DCS BT.

Sec. Cor. to Secs. 33 & 34, T28-9W. & Secs. 3 & 4, T29-9W.

Found - Orig. 18", now 20" Hemlock S. 59° W. 21.8 ft., prev. opened,
shows good scribing "1/4" S".

Orig. 24", now 30" Hemlock, S. 49° E. 17.2 ft., shows scar.
N.E. & N.W. BT's. not found.

Set - Brass Cap at Cor. Mkd: 1962 Coos Co. S 33 | S 34 T28S
Doug. Co. S 4 | S 3 T29S R9W

- New BT's: 46" Fir bears N. 76° W. 20.0 ft. bark scribed S33 T28S R9W CS BT.
- 7" Yewood bears N. 69° E. 33.6 ft. scribed S34 CS BT.

April 18, 1962

1/4 Cor. to Sec. 34, T28-9W. & Sec. 3, T29-9W.

Found - Stumps of Orig., now 30" Fir Stump N. 10° W. 19.1 ft., shows
good bark scribing "1/4". We nail yellow tag near base.

Water falls bears N. 55° E. 1220'+ or less. Corner is on top of spur.

Set - Brass Cap at Cor. Mkd: County Surveyor's 1/4 S 34 | T28S R9W
Office, 1963 S 3 | T 29S

- New BT; 62" Cedar bears S. 54° W. 169.6 ft. scribed 1/4 S 3 CS BT.
- No trees near to north.

June 20, 1963

Renew Township Corner: R9W S 36 | S 31 R8W T28S
S 1 | S 6 T29S

Found - 3/4" I. Pipe at Corner.

Orig. 15", now 24" Rotten stump, N. 86½° W. 23.8 ft., good
scribing on chip of old face. This corner renewed by

Coos Head Timber Co., Aug., 1956 per notes on yellow tag.

Orig. BT checks bearing & distance to 3/4" I.P.

Following BT's found scribed 1956:

- 7" R. Fir S. 8° W. 22.8 ft. scribed BT S1 T29S R9W
- 6" R. Fir N. 76½° E. 21.0 ft. scribed S31 R8W T28S
- 24" Cedar N. 3° E. 86.9 ft. scribed BT S31 T28S R8W

James W. Byron
Milo Godfrey - J. Fee
April 25, 1956
C. S. File No. 47/90

James W. Byron
Milo Godfrey - J. Fee
Aug. 16, 1957
C. S. File No. 49/12

James W. Byron, Deputy Col. Surv.
and Crew
C. S. File No. 49/100

James W. Byron, Deputy
M. Godfrey - J. Fee
Sept. 10, 1957
C. S. File No. 49/12

Sept. '68