

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 1 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

55

1/4 Corner to Sections 14 and 13

Found - 14X8X6 corner stone in place Mkd. 1/4 West face and two good bearing trees. 10' D. Fir, now 11" N 43 E 14.5 Ft. Shows good face
12 D. Fir, now 15, S 50W 11.2. Shows a good face.

Set - Brass cap at 1/4 Cor. from bearing and dist. from both bearing trees mkd:

County Surveyors T 29S RIW
Office, 1969 1/4 S14 | S13

Note: No new bearing objects needed. This cor. lies on steep east slope and a rock bluff bearing east 25'.

5-22-69

56

Section Corners 20, 21, 29, 28

Found - No trace of 18X12X10 corner stone, because the corner falls in an old skid road. Found two good bearing trees.

8" cedar, now 22', S 50W 47.5 ft. Shows good scribe of (T2, E.)
14" R Fir, now 32", N81W 53.5 Ft. Show, good face.
10" R Fir, now 28" stump, N 50°E, 151.4 Ft. Cut too low to show face or scribing. 24" R Fir, now 42" stump S 75E 112.2 Ft.. Shows scribe of a "W"

Set - Brass cap at sec. cor. from bearing and dist. from bearing trees

(Mkd.) County Surveyors T 29S RIW
Office, 1969

S20 | S21
S29 | S28

New B. T.:

6" D. Fir N 52 1/2 E. 23.2 ft. Scribed (T 29S R I W S 21 CSBT)

14" D. Fir S 55E 23.4 Ft. Scribed: (T29S RIW S28 CSBT)

Note: This Cor. lies in a skid Road on top a ridge with logged unit to the East.

5-21-69

57

1/4 Corner to Sections 18 and 19

Found - No trace of 20X15X10 corner stone and both BT's are cut because this corner lies in a logging unit.

40" R Fir, now 48" windfall stump, N38E 91.2 Ft.. Shows a face.

18" Cedar, now 28" stump, South 13.9 Ft. Opened and found scribe of a "B"

Set - Brass cap at 1/4 corner from bearing & dist. from both Bt's Mkd:

County Surveyors T29 RIW
Office, 1969 1/4 S 18
S 19

Note: 5' Metal fence post by B.C. New Bearing trees

6 Hemlock S 64 E 204.4 Ft. Scribed (1/4 S 19 CSBT)

22 Cedar S 34 E 223.9 Ft. Scribed (1/4 S 19 CS BT)

Note: Bearing objects out range in north. Plus this corner lies in a logged over unit 25' West of creek

5-21-69

58

1/4 Corner to Section 25 Only R. 2W T. 29-

Found - Brass cap in excellent condition and properly marked 1917, and 1 bearing tree.

24" D Fir, now 29", S 52°W 26.4 Ft. Shows good scar and is good for bearing and dist.

8" Chinquapin, now 9", N 28 1/2 W. 35.0 ft. Has rotten face and shows no trace of scribing, and is good for bearing and Dist.

Note: Place yellow tags on both bearing trees.

Found Brass Cap at bearing & Dist. from both bearing trees Mkd. by GLO 1917.

New Bearing tree: 6" D. Fir N 77W 16.4 Ft. Scribed 1/4 S 25 CsBt

Note: This 1/4 S 25 only lies north 33.7 Ft. From 1/4 S 30 only range line of R1, 2W T29S Plus these corners lie on steep West Side.

4-24-69

RE-REVIEWED, SEE CORNER NO. #142

JOHN M. POWELL
Frank Jones & W. Penley
April & May, 1969
C. S. File No. 54/82