

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 2 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 97101

James W. Byron, Deputy County Surveyor
Mike Darby and Bill Stoffel
December 1962 and January 1963
C. S. File No. 52/126

John M. Powell
Frank. Jones & Joe Brady
October 13, 1967
C. S. File No. 54/58

Corner to Sections 24 and 25 only T29-3W. (W. Bdy. T29-2W.) 16
Found - Stone at Corner & both BT's. as recorded.
Set - Brass Cap alongside Cor. Stone & Mkd: $\frac{S24}{S25}$ T29S
County Surveyor's Office, 1962 R3W R2W
Note - Both Corners, No. 15 & No. 16, on Steep South Slope.

Corner to Sections 30 and 31 only, T29-2W. 17
Found - Brass Cap at Corner & Both BT's., show scars.
New BT's: 13" Laurel bears N. 47° E. 29.9 ft. scribed S30 T29S R2W CS BT
12" R.Fir bears S.46°E. 34.0 ft. scribed S31 T29S R2W CS BT.

East $\frac{1}{4}$ Corner to Section 25 only, T29-3W. 18
Found - Brass Cap at Cor. & both BT's. N.W. BT., shows good scar.
S.W. BT., now down, shows scribing on stump section.
New BT's: 6" R.Fir bears N. 68° W. 18.0 ft. scribed $\frac{1}{4}$ S25 CS BT.
8" Chinquapin bears S.38°W. 4.4 ft. scribed $\frac{1}{4}$ S25 CS BT.

Corner to Sections 25 and 36 only, T29-3W. 19
Found - Both Bearing Trees. Orig. 16", now 30" Fir S.65°W. 26.0 ft.,
not 29.7 ft., shows good scar & bark scribing. N. W. BT.
shows good scar.
Corner Stone Not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{S25}{S36}$ T29S
Office, 1963 R3W R2W
No New Bearing Trees Scribed.

$\frac{1}{4}$ Corner to Sections 15 and 22. 20
Found - 1917 G.L.O. Brass Cap in good condition & properly marked.
18", now 20" Fir stump, S. 11 $\frac{1}{2}$ ° W. 30.4 ft. Open & find
partial "BT" scribe & reverse.
Stump only for N. E. BT.
New BT. Stumps: 40" D.Fir Stump S. 58° W. 22.5 ft. mkd. $\frac{1}{4}$ S22 CS BT.
8" Yew Snag N. 13° E. 26.1 ft. mkd. $\frac{1}{4}$ S15 CS BT.
Note - This corner lies in approx. middle of logged-off unit on S.W. slope.
(V. R. Tracy & Crew) June 28, 1967
C.S. File No. 54/58

MICROFILM TO HERE 10/67

Section Corner to Sections 8 - 9 - 16 - 17. 21
Found - 1917 G.L.O. Brass Cap at Section Corner properly marked.
40", now 45" D.Fir, N. 42° E. 39.6 ft., shows good scar.
36", now 40" D.Fir, N. 9 $\frac{1}{2}$ ° W. 27.1 ft., shows good scar.
7", now 11" Hemlock S.45°W. 38.3 ft., scribe marks visible.
No trace of S.E. BT.
New BT: 7" Hemlock S. 62 $\frac{1}{2}$ ° E. 17.6 ft. scribed T29S R2W S16 CS BT.
Note - This corner lies approx. 250.0 ft. W. of Deer Spring Road.

$\frac{1}{4}$ Corner to Sections 8 and 9. 22
Found - 1917 G.L.O. Brass Cap mkd., but out of ground.
36" D. Fir, now stump, N. 11 $\frac{1}{2}$ ° W. scribe visible " $\frac{1}{4}$ S8 BT).
No trace of N. E. BT.
Reset - Brass Cap at $\frac{1}{4}$ Corner.
New BT's: 16" D.Fir N. 48° W. 6.4 ft. mkd. $\frac{1}{4}$ S8 CS BT.
17" D.Fir S. 74 $\frac{1}{2}$ ° E. 35.6 ft. mkd. $\frac{1}{4}$ S9 CS BT.

$\frac{1}{4}$ Corner to Sections 9 and 16. 23
Found - 1917 G.L.O. Brass Cap properly marked but out of ground.
Reset - Brass Cap at $\frac{1}{4}$ corner which falls at edge of road.
Found - 12" Hemlock, now stump, S. 40° W. 33.0 ft., scribe visible " $\frac{1}{4}$ S16 BT".
No trace of N.W. BT, falls in Road R/W.
New BT's: 18" Hemlock S. 24° W. 48.0 ft. mkd. $\frac{1}{4}$ S16 CS BT.
24" D. Fir N. 84° W. 67.8 ft. mkd. $\frac{1}{4}$ S 9 CS BT.