

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

24

John M. Powell & Crew  
Jan. 15, 1968  
C.S. File No. 54/59

Township Corner, GLO Brass Cap: R T 29 S R  
Found as shown: 2 S 36 | S 31 1  
W S 1 | S 6 W  
T 30 S  
1917  
Found - Orig. 30" Pine, now down & burnt S 81° W 24.0 ft.  
Orig. 18" Oak, now rotted out, N 70° W 27.0 ft.  
Orig. 18" Oak, now stob, N 8° E 47.5 ft.  
Orig. 12" now 17" Oak, S 89° E. 118.8 ft., opened for scribe "BT".  
(Fell this tree as very rotten & would be a hazard)  
New BT's: 16" D. Fir N. 44° W. 26.8 ft. mkd. T29S R1W S36 CS BT.  
15" D. Fir N. 73° E. 17.5 ft. mkd. T29S R1W S31 CS BT.  
Reblzd. & Resc'd: 16" D. Fir S. 9° E. (Rec. S. 12° E.) 13.0 ft. mkd. T30SR1WS6CS BT.  
1904 BT's: 10" D. Fir S. 41° W. (Rec. S. 39° W.) 33.0 ft. mkd. T30SR2WS1CSBT.

25

Section Corner to Sections 3 and 4 only, T30-2W. (S. Boundary T29-2W)  
Found - Orig. 5" Cedar, now stob, S. 89° W. 32.3 ft.  
No trace of S.E. Bearing Tree.  
48", now 56" Corner Tree, shows good scars.  
Set - Brass Cap on S. Side of Corner Tree Mkd: T 29 S  
County Surveyor's Office, 1968 T 30 S R2W S 34 | S 3  
New BT's: 6" Cedar S. 82° E. 17.0 ft. mkd: T30S R2W S3 CS BT.  
8" Red Fir S. 64° W 16.2 ft. mkd: T30S R2W S4 CS BT.  
9" W. Fir N. 80° E. 7.3 ft. mkd: T29S R2W S34 CS BT.  
This corner lies 26.8 ft. East of Sec. Cor. to Secs. 33 & 34, T29-2.

26

Section Corner to Sections 33 and 34, T29-2W.  
Found - Stone, approx. 15x10x8, at section corner, no notches seen.  
12", now 18" Cedar, N. 30 1/2° W. 38.9 ft., scribe visible.  
14" Fir, now stump, N. 5° E. 69.3 ft., scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W S33 | S34  
Office, 1968 T30S S 4  
New BT: 6" D. Fir N. 24° E. 29.3 ft. mkd: T29S R2W S34 CS BT.  
7" D. Fir S. 13° W. 11.7 ft. mkd: T30S R2W S4 CS BT.  
This corner lies 26.8 ft. west of Cor. to Secs. 3 & 4 only, T30-2W.  
10/14/68

JOHN M. POWELL  
Frank Jones & W. Penley  
October & November, 1968  
C. S. File No. 54/73

27

1/4 Corner to Section 36 only.  
Found - GLO Brass Cap, properly mkd. in 1917.  
10", now 12" D. Fir, N. 45° E. 11.9 ft., shows scar, badly scared  
by logging.  
14", now 17" D. Fir, N. 37° W. 31.0 ft., shows good scar.  
New BT: 16" W. Fir N. 51° E. 23.1 ft. mkd: 1/4 S36 CSBT.  
This corner lies 25.7 ft. W. of 1/4 Cor. Sec. 1, T30-2W., see below.

RE-RENEWED, SEE CORNER NO. #121

28

1/4 Corner to Section 1, only, T30-2W.  
Found - Stone at 1/4 Cor. about size, no marks visible.  
8" D. Fir, now stump, S. 20° E. 30.4 ft., opened for scribe.  
No trace of S.W. Bearing Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W 1/4 S 1  
Office, 1968 T30S  
New BT's: 10" W. Fir S. 21° E. 23.7 ft. mkd: 1/4 S1 CSBT.  
9" W. Fir S. 24° W. 28.3 ft. mkd: 1/4 S1 CS BT.  
This corner lies 25.7 ft. east of 1/4 Corner Sec. 336 only, T29-2W.

Fd. 7/73 HANES  
FOR BLM - SEE  
S.I.S. FILE

29

1/4 Corner to Section 2 only, T30-2W.  
Found - 20" D. Fir, now stump, S. 84° E. 24.4 ft., opened for scribing.  
No trace of corner stone nor S.E. Bearing Tree.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S  
Office, 1968 T 30 S R2W 1/4 S 2  
New BT's: 10" Hemlock S. 22° E. 15.8 ft. mkd: 1/4 S2 CS BT.  
10" Hemlock S. 72° W. 48.4 ft. mkd: 1/4 S2 CS BT.  
This corner lies 39.1 ft. E. of 1/4 Cor. Sec. 35, T29-2W, see next page.

RE-RENEWED, SEE CORNER NO. #122