

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

30

1/4 Corner to Section 35 only, T29-2W.
Found - 15", now 22" D.Fir, N.56 1/2° E. 45.5 ft., shows good scar.
15", now 22" W.Fir, N.51° W. 38.3 ft., opened for scribing.
No trace of 1917 Brass Cap as corner falls in cut for old skid road
which comes directly down section line.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W 1/4 S 35
Office, 1968 T30S

All Bearing Trees in good condition & tagged.
This corner lies 39.1 ft. west of 1/4 corner Sec. 2 only.

31

Section Corner to Sections 35 and 36, T29-2W.
Found - Stone approx. size at corner, but no marks found.
30" D.Fir, now down, N.45 1/2° E. 12.5 ft., scribe visible. #111
No trace of N.W. BT.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W 1/4 S 35 | S 36
Office, 1968 T30S

New BT's: 24" D.Fir North 38.0 ft. mkd: T29SR2WS36 CS BT.
20" D.Fir N.10° W. 25.7 ft. mkd: T29SR2WS35 CS BT.
8" W.Fir S.24° W. 18.6 ft. mkd: T30SR2WS 2 CS BT.

32

Section Corner to Sections 1 and 2, T30-2W.
Found - Stone at corner approx. size & 5 grooves on west side.
5" W.Fir, now dead, S.11° E. 23.8ft., scribe visible.
15" D.Fir, now down, S.43° W. 56.1 ft., shows scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W 1/4 S 2 | S 1
Office, 1968 T30S

New BT's: 7" W.Fir S.12° W. 34.4 ft., T30SR2WS2 CS BT.
9" W.Fir S. 4° E. 43.0 ft. mkd: T30SR2WS1 CS BT.
15" D.Fir N.47° W. 14.7 ft. mkd: T29SR2WS26 CS BT.

33

1/4 Corner to Section 6 only, T30-2W.
Found - Stone at 1/4 corner, approx. size, mkd: "2" on top. #120
12" D.Fir, now rotten stump, S. 2° W. 13.2 ft., found scribing.
6", now 8" Laurel, S.40° W. (Red. S.40° E) 2.3 ft., rotten faces.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W 1/4 S 6
Office, 1968 T30S

New BT's: 5" D.Fir S.41° E. 17.4 ft. mkd: 1/4 S 6 CS BT.
30" D.Fir S.35° W. 18.9 ft. mkd: 1/4 S 6 CS BT.
This corner lies 100 ft. east of 1/4 corner Sec. 31, T29-2W., see below.

34

1/4 Corner to Section 31 only, T29-2W.
Found - GLO Brass Cap, properly marked in 1917.
30", now 38" D.Fir, N.32 1/2° W. 19.8 ft., shows good scar.
20" D.Fir, now down, N.8 1/2° E. 12.5 ft.

New BT: 20" D.Fir N.30° E. 25.1 ft. mkd: 1/4 S31 CS BT.

35

Section Corner to Sections 31 and 32 only, T29-2W.
Found - No trace of Corner Stone.
10", now 15" D.Fir, N.6 1/2° E. 13.9 ft., shows good scar.
20", now 25" D.Fir, N.38° W. 35.6 ft., scribe visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W S 31 | S 32
Office, 1968 T30S S 6

New BT: 11" D.Fir S.2° E. 18.8 ft. mkd: T30S R2W S 6 CS BT.
This corner lies 73.9 ft. west of Corner to Secs. 5 & 6, T30-2W, see below.

36

Section Corner to Sections 6 and 5 only, T30-2W.
Found - 24", now 26" D.Fir, S.27° E. 11.9 ft., shows good scar.
30", now 34" D.Fir, S.16° W. 30.4 ft.
Stone at Sec. Cor.(Set) approx. size, no marks found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W S 32
Office, 1968 T30S S 6 | S 5

New BT: 8" Cedar N.34° E. 16.1 ft. mkd: T29S R2W S32 CS BT.
This corner lies 73.9 ft. E. of Sec. Cor. 31,-32, T29-2, see above.

John M. Powell
Jack Heritage & W. Penley
November, 1968
C.S. File No. 54/73
Pd 7/73 HAWES
FOR ELM - SEE
G.I.S. FILE

RE-RENEWED, SEE CORNER NO. #111
RE-RENEWED, SEE CORNER NO. #120
RE-RENEWED, SEE CORNER NO. #119