

Douglas County Surveyor's Record of
Government Corners Renewed

29

T. S.

2

R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

80

Section Corner to Sections 6, 5, 7, and 8.

Found: 1917 GLO Brass Cap properly marked. This cap out of ground.
16" D. Fir, now 20", N. 41° E., 21.8 ft. Shows good scar.
8" D. Fir, now stob, S. 82° E., 31.0 ft. Scribe visible
T29S R2W S8.
10" D. Fir, now stob, S. 41½° W., 12.5 ft. (Rec. 9.9 ft.)
Scribe visible "R2"
10" D. Fir, now 12", N. 74° W., 9.9 ft. (Rec. 12.5 ft.)
Opened for scribe "W".
Set: Reset Orig. Brass Cap at Sec. Cor.
New BT's: 25" D. Fir, S. 74° W., 18.1 ft. Scribed T29S R2W S7 CS BT.
23" D. Fir, S 51° E., 36.2 ft. scribed T29S R2W S8 CS BT.

John M. Powell
J. Heritage
V. Perron
June 14, 1971
C. S. File 54/96

81

¼ Corner to Sections 5 and 8.

Found: 1917 GLO Brass Cap at ¼ cor. properly mkd.
10" D. Fir, now stump, S. 25½° W., 26.4 ft. opened for scribing
"¼"
18" D. Fir, now 24", N. 45° E., 21.1 ft. Shows good scar.
New BT's: 22" D. Fir, S. 84° W., 78.4 ft. scribed ¼ S8 CS BT.
Note: This cor. lies about 50 ft. north of Tater Hill Road.

6/14/71

JAN-1972

Section Corner, Sec. 31 only T28-2.

Found - 2" D. Fir, now 12", S. 8° W., 22.2 ft. shows scar.
1½" D. Fir, now 11", S. 55° E., 10.2 ft.
Also truck axle at ¼ Corner. Ren. No. 3.
Due to trees south of township line and not scribed, I scribe
New Bt's - 13" D. Fir, N. 46½° E., 29.6 ft. scribed ¼ S31 CS BT.
4" Cedar, N. 86° E., 2.9 ft. scribe ¼ S31 CS BT.

3/14/73

82

John M. Powell
J. Heritage
G. Commons
C. S. File 56/25
March 14, 1973

Section corner, Sections 5 & 6 only.

Found - 1" I. Pipe at corner. Ren. No. 1
3" D. Fir, now 7", S. 41° E., 19.0 ft. scribe visible "S5".
3" D. Fir, now 8", S. 1° W., 45.5 ft. shows scar.
NE and SE BT's other than the above, cut.
New BT - 7" D. Fir, North, 18.1 ft. scribed T28S R2W S31 CS BT.
All trees tagged.

3/14/73

83

¼ Corner, Section 6 only. (North)

Found - 1917 GLO Brass cap at ¼ Corner.
14" D. Fir, now stump, S. 14° E., 40.9 ft. shows good scar.
18" D. Fir, now stump, S. 80° W., 23.1 ft.
New BT's - 30" Laurel, S. 63° E., 39.2 ft. scribed ¼ S6 CS BT.
6" Live Oak, S. 65° W., 53.4 ft. scribed ¼ S6 CS BT.

84

Section Corner for Sec. 36, T28-3 and Sec. 31, T28-2 only.

Found - 6" D. Fir, now 8", N. 59° W., 21.7 ft. Shows good scar.
40" Cedar, now stump, S. 83° E., 11.9 ft.
7" Laurel, now 8", N. 25° E., 25.9 ft.
Also truck axle at sec. cor. Ren. No. 2
New BT - 24" D. Fir, S. 35° W., 78.6 ft. Scribed T29S R2W S6 CS BT.

85

John M. Powell
J. Heritage
G. Commons
C.S. File 56/25
March 14, 1973

¼ Corner for Sec. 17 and 18.

Found - 1917 US GLO Brass cap with iron pipe.
16" Rotten D. Fir stob, bears N. 82° E., 6.2 ft., scribing "¼ S17 BT"
visible. (rec. N. 81° E., 6.6 ft.)
Downed & shattered D. Fir, bears approx. N. 39° W, tagged & scribing
"¼ S18 BT" visible. (rec. N. 51° 30' W., 13.9 ft.)
New BT's - 30" D. Fir, bears N. 53° E., 22.3 ft. scribed ¼ S17 CS BT"
30" D. Fir, bears N. 24° W., 29.6 ft. scribed ¼ S18 CS BT.
Note - Record NW BT is out of position due to being knocked down by
blowdown. Brass cap is presently located underneath large
blown down tree.

86

Gary Langlitz
P. Earle
Jan. 15, 1974
C.S. 56/43

RECORDED - CORNER NO. #87
GOVT. COR. REF. OUT FOR RD. WORK - J. POWELL - 5/13 - 1/15/74

JAN '75