

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T.S. R2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21981

Gary L Langlettz  
Peter L Earle  
4/29/75  
C.S. 57/21

1/4 corner for Sec 17 and 18. 87  
Found - Brass cap out of ground and moved approx. 30 ft.  
downhill from its proper position by logging oper-  
ations. Ren# 86  
The remains of both original BT's have also been  
destroyed.  
The two additional BT's marked as noted in Ren#86  
are now both stumps. They are in the positions  
as noted in Ren.#86. However, only the scribing  
" CS BT" remains on the NW tree. The full scribe  
is visible on the NE BT.  
At the corner point, we reset the original monument.  
A 1" iron pipe with brass cap attached and marked  
properly, to which we add the markings: "CS 1975"  
We also place a steel fencepost with survey marker sign attached near the corner.

4/29/75

Gary L Langlitz  
V.A. Cangie  
6/25/75  
C.S. 57/30

1/4 corner for Sec. 22 and 27 88  
Found- 1" Iron Pipe, firmly set, extending 8" above ground, with  
brass cap attached, GLO properly marked.  
From which: An orig. 24" now 34" D Fir bears S 57 1/4°W., 11.9 ft.  
(Rec. S57 1/4°W., 16.5 ft.) with scribing "1/4" visible on  
a partially rotten unhealed blaze.  
and an orig. 20" now 29" D Fir bears N34 3/4°W., 77.9 ft., Alive  
and well-healed.  
We mark the following new bearing tree:  
A 9" D Fir bears S 74°E., 30.4 ft. scribed "1/4 S 27 CSBT"  
Compass Declination; 20° E.

Clell Goodwin  
Vic Cangie  
C.S. 57/36  
9/22/75

1/4 corner for Sec 27 & 34 89  
Found: A G.L.O. Brass cap on a 1"x30" iron pipe stamped properly, and an  
orig. 20" now 24" fir bearing N 46 1/2°W., 71.9ft.  
New: A 7" fir scribed "1/4 S 34 CS BT" in a double blaze bears S 25 1/2°W.,  
17.6 ft.  
Original SW BT, A 24" fir is blown down. Compass Declination 20° East. 9/75  
Section Corner to Sec. 28, 27, 33 & 34: 90  
Found. G.L.O. brass cap properly mkd on 1" x 30" I.P. (1917)  
From which: an orig. 24" now 30" fir bears S 19°E., 29.9ft. (call S 19°E., 27.7ft  
alive & well healed.  
An orig. 10" now 17" Fir bears S 46°W., 39.6ft alive & healed.  
An orig. 30" fir now rotted stump with no visible scribe bears N85°E., 7.9ft.  
No recognizable remains of original N.W. B.T.  
New: A 12" fir scribe "T29S R2W S28 CS BT" in a double blaze bears N43 1/2°W.,  
9.2ft.  
A 14" fir scribed "T29S R2W S27 CS BT in a double blaze bears N57°E., 22.9ft.  
Compass Declination 20° East 9/75

Section Corner to 27, 26, 34 & 35: 91  
Found- G.L.O. 1917 brass cap stamped properly, projecting 8" out of the ground  
and apparently undisturbed  
From which:  
an orig. 24" now 38" fir bears S 34°E., 30.4ft.  
an orig. 10" now 16" Cedar bears N 29°W., 65.4ft. (call N 29°W., 64.7ft)  
an orig. 24" fir now a rotted stump bears S 17°W., 40.8ft. (Call S 17°W.,  
40.3ft) No sign of orig. N.E. B.T. which has been removed by road  
construction  
New: A 13" fir scribed "T29S R2W S 34 CSBT" in a double blaze bears S 15 1/2°  
W., 27.5 ft.  
A 12" Cedar scribed "T 29S R2W S 26 CS BT" in a double blaze bears  
N 72 1/2°E., 21.1ft. Compass Declination 20° East 9/75

Section Corner to Section 21, 22, 28 & 27: 92  
Found: 1917 G.L.O. Brass cap properly mkd, Cap found to be leaning N.E.  
Using point in which pipe goes into ground.  
Orig. 16" now 17" fir bears N20°E., 43.6ft.  
Orig. 10" now 11" fir bears S 47 1/2°E., 3.9ft. (Rec. S52°E., 5.9ft. may have  
read 6 lks as 9 lks)  
Orig. 16" now 21" fir bears N 15°W., 25.7 ft.

(OVER)