

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 3 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

40

$\frac{1}{4}$  Section Corner to Sections 27 & 28.

Found - Orig. 18", now 36" R. Fir N.40°W. should be N.53°W., I  
open & find good scribing  $\frac{1}{4}$ " S".

Orig. 10", now 16" Down Fir Corner Tree, previously  
opened, shows good scribing  $\frac{1}{4}$ " S".

Orig. N.E. BT. shows good scar. I do not open.

Set Brass At Corner Tree Mkd: County Surveyor's Office, 1959,  
 $\frac{1}{4}$  S28/S27 T29S R3W.

New BT's: Rescribe Orig. N.32°E. 12.6 ft. 16" R. Fir  $\frac{1}{4}$  S27 CS BT.  
38" Cedar bears N.39°W. 32.7 ft. scribed  $\frac{1}{4}$  S28 CS BT.

RE-RENEWED, SEE CORNER NO. #134

James W. Hyron, Deputy  
Mlo Godfrey  
S. A. Blilow  
February 19, 1959  
C. S. File No. 49/47

41

Section Corner to Sections 21, 22, 27, & 28.

Found - All Four Orig. BT's.:

Orig. 36", now 44" Fir Snag N.5°E. 52.8 ft., shows good  
bark scribing.

Orig. 12", now 30" Laurel S.10°W. 29.0 ft., center rotted.

Orig. 10", now 18" Fir S.16°E. 16.5 ft., shows good scar,  
I do not open.

Orig. 6", now 18" Fir N. 13°W. 21.8 ft., shows good scar,  
I do not open.

Set Brass Cap at Corner Mkd:  $\frac{S21}{S28} | \frac{S22}{S27}$  T29S R3W County Surveyor's  
Office, 1959

New BT's: 20" R. Fir bears N.39°E. 28.9 ft. scribed S22 T29S R3W CS BT.  
6" R. Fir bears S.60°W. 55.2 ft. scribed S28 CS BT.

42

$\frac{1}{4}$  Section Corner to Sections 28 & 33.

Found - Orig. 6", now 6" Cedar Snag Corner Tree scribed  $\frac{1}{4}$ " S,  $\frac{1}{4}$ " S"

Orig. with  $\frac{1}{2}$ " Pipe at Base. - *Ren. No. 12*

Orig. 15", now 32" Fir Stump S.70°E. 8.0 ft., shows bark  
scribing & old scars.

Stump Hole checks bearing & distance for Orig. N.W. BT.

New BT's: 13" R. Fir bears S.32°W. 27.5 ft. scribed  $\frac{1}{4}$  S33 CS BT.

12" R. Fir bears N. 8°W. 53.7 ft. scribed  $\frac{1}{4}$  S28 CS BT.

43

$\frac{1}{4}$  Section Corner to Sections 25 & 36.

Add these two Bearing Trees to Corner, since we are logging  
both Original Bearing Trees as shown in Corner No. 37,  
previous page.

New BT's: 10" Fir bears N.72°W. 21.7 ft. dist. mkd.  $\frac{1}{4}$  S25 R3W B.T.

8" Fir bears S.13°E. 30.0 ft. dist. mkd.  $\frac{1}{4}$  S36 W.M.B.T.

44

Section Corner to Sections 25, 26, 35, & 36.

as determined by O.B.T's:

40" Fir N.75°E. 16.2 ft. O.B.T., fd. scribe.

30" Fir S.18°E. 44.8 ft. O.B.T.

18" Fir Snag S.43°W. 3.6 ft. O.B.T., fd. scribe.

12" Fir N.40°W. 7.0 ft. O.B.T.

At Corner Point found 12" Fir Snag scribed & Set 3" x 30" Iron Pipe  
from which:

12" Fir bears N.61°E. 18.5 ft. dist. mkd. S25 R3W B.T.

30" Fir bears N.81°E. 34.0 ft. dist. mkd. S25 T29S R3W BT.

12" Fir bears S.66°E. 36.8 ft. dist. mkd. S36 T29S B.T.

26" Fir bears S.41°W. 13.4 ft. dist. mkd. S35 T29S R3W BT.

Road bears North 75.0 ft.

RE-RENEWED, SEE CORNER NO. #118

John H. Markham, Jr.  
For Stomar Lumber Co.  
Wit. R. G. Boyd  
May 13, 1959  
C. S. File No. 42/315

45

$\frac{1}{4}$  Section Corner to Sections 19 & 30.

Set Iron Pipe.

No Trees Scribed (Old Burn)

RE-RENEWED, SEE CORNER NO. #131

For Hall &  
Potter

By E.S.

Woodford

April 1953

C.S. File 42/68 M 16 - 21