

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 3 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
Feb. 2, 1960
C. S. File No. 49/47

North $\frac{1}{4}$ Section Corner to Section 1. 46
Found - Both Original Bearing Trees:
Orig. 12", now 18" Fir S.52°E. 6.6 ft. I open & find
good scribing " $\frac{1}{4}$ S".
Orig. 12", now 16" Fir N.32°W. 6.6 ft., center rotted,
no scribing found.
Corner Stone Not Found -
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

T28S
N $\frac{1}{4}$ S 1 T29S R3W. - FOUND O.K. Dec. '66
New BT's: 24" R. Cedar bears S.43°E. 34.5 ft. scribed N $\frac{1}{4}$ S1 CS BT. VET.
5" R. Fir bears S.67°W. 15.0 ft. scribed N $\frac{1}{4}$ S1 CS BT.

North $\frac{1}{4}$ Section Corner to Section 2. 47
Found - Fir Stump, now 40", South 5.3 ft. with old bark scribe,
" $\frac{1}{4}$ S"-B" showing.
No trace of other B.T. found.

At Corner set Iron Pipe with Brass Cap Mkd: "County Surveyor's
Office, 1960 T28S R3W
N $\frac{1}{4}$ Cor. S2
T29S R3W
Blaze & Scribe New Trees: 34" I. Cedar S.63°E. 7.5 ft. (N $\frac{1}{4}$ S2 CS BT)
30" I. Cedar S. 2°W. 43.3 ft. (N $\frac{1}{4}$ S2 CS BT)

James W. Byron
Milo Godfrey
Clete Putnam
April 15, 1960
C.S. 49/47

Corner to Sections 18 and 19 only. 48
Found - Orig. 10", now mostly rotted Fir Stump N.10°E. 19.8 ft., I
open & find good scribing "B".
Orig. 24", now 40" Fir Snag, I open near base & find scribe
marks, S.80°E. 18.5 ft.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960
New BT's: 5" R. Fir bears N.76°E. 20.5 ft. scribed S18 CSBT.
6" Pine bears S.50 $\frac{1}{2}$ °E. 26.4 ft. scribed S19 CS BT. #136

$\frac{1}{4}$ Section Corner to Sections 17 and 20. 49
Found - 1 $\frac{1}{4}$ " Iron Shaft at corner & S. W. BT., exposed scribing
as recorded by B.B.I. - REN. 2/17
N. W. BT. not found.
New BT.: 16" Cedar bears N.61°E. 27.5 ft. scribed $\frac{1}{4}$ S17 CS BT.

July 1960

South $\frac{1}{4}$ Corner of Section 35. 50
Found - Orig. 6", now down 10" Laurel N.30°E. 33.0 ft. I open &
find good scribe marks " $\frac{1}{4}$ B". This BT. was found downhill
about 30.0 ft. We found matched stump section which
fixed location of BT.
Orig. S.E. BT. not found.
Set Brass Cap at Corner & alongside 14" R. Fir (East Side) Mkd:
County Surveyor's Office, 1960 South $\frac{1}{4}$ S35 T29S R3W.
New BT's: 10" R. Fir bears N.44 $\frac{1}{2}$ °E. 15.0 ft. scribed $\frac{1}{4}$ S35 CS BT.
11" R. Fir bears N.65°W. 5.8 ft. scribed $\frac{1}{4}$ S35 CS BT
Note-5/8" Rod Set by Bruce Shaner, National Plywood, for North
 $\frac{1}{4}$ S2 T30S R3W, bears N.87°W. 76.5 feet. See Map File M 17-51.

Section Corner to Sections 34 and 35 only. 51
Found - Both Orig. BT's. Orig. 24", now 40" Fir N.35°W. 46.2 ft,
shows good scar.
Orig. 14", now 20" Laurel N.81°E. 19.8 ft. (Record N.72°E.),
shows good scribing "S35".
Also find Stone at Corner, notches not found. T29S
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960 S34/S35 R3W
T30S
Rescribe, now 20" Laurel N.81°E. 20.4 ft. T29S R3W S35 CS BT.