

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

139

John M. Markham, Jr.
For: Stomar Lbr. Co.
April 22, 1958
C.S. File No. 42/345
42/345

West $\frac{1}{4}$ Corner to Section 31, as determined by Orig. BT's:
B. O. Stump Hole bears west 24.4 ft.
B. O. Stump Hole bears N. 3* W. 42.9 ft.
20" Fir bears S. 32* W. 16.0 ft., Rescribed " $\frac{1}{4}$ S36 BT".
At Corner Point set 2"x30" Truck Axle, from which:
50" Fir bears S.66*E. 4.0 ft. dist. bark scribed " $\frac{1}{4}$ S31 BT".
6" Maple bears S.33*E. 42.6 ft., mkd: " $\frac{1}{4}$ S31 BT".
10" Fir bears N. 11* E. 70.0 ft., mkd: " $\frac{1}{4}$ S31 BT".
Top and Road bears East 270.0 ft and South 390.0 ft.

April 22, 1958

140

Robert M. Thompson
Wit: L. Washburn, Jr. - H. Hubbard
For: Patrick Lumber Co.
Dec. 22, 1958
C. S. File No. 41/62

Section Corner to Sections 6 & 7, T29-4 & Secs. 1 & 12, T29-5W.
Found - 24" Stunted D. Fir which U.S. notes called, Redwood, S. 57 $\frac{1}{2}$ *W.
43.0 ft., scribed "5W S 1 (2)".
Other bearing trees burnt out.
To renew, Set 6x10x12 conglomerate stone.
Scribed New BT's: 40" D. Fir S.75*30'W. 46.0 ft.
14" I. Cedar N.23*40'W. 36.4 ft.
40" D. Fir N.88*40'E. 57.2 ft.
17" I. Cedar S.34*20'E. 21.2 ft. (Yellow Tag)
This corner falls 6 ft. east of Little Lick Ck. & about 120 ft.
east of old logging road.

June 5, 1958

141

$\frac{1}{4}$ Section Corner to Sections 6 and 7.
Found - 10" Fir S.60*W. 16.5 ft., now 26" stump, chopped open long
butt, I find "S" scribed.
Other BT's burnt out, stump hole evident.
To Renew, I set $\frac{1}{2}$ " I. Pipe:
Scribed New BT's: 20" Madrona S.40*20'E. 17.8 ft.
12" Madrona N. 5* E. 21.0 ft.

June 5, 1958

142

$\frac{1}{4}$ Corner to Section 6, T29-4 and Sec. 1, T29-5.
Being unable to find West $\frac{1}{4}$ corner Section 6 after diligent search,
I run blank west section line. Find total distance of 5180.0 ft.
At Midpoint on true line, I Set - $\frac{3}{4}$ " Iron Pipe.
Scribed: 15" D. Fir S. 51* E. 31.0 ft.
6" D. Fir S. 78* 30' W. 44.0 ft.

June 11, 1958

143

J. W. Byron
and
S. A. Bilow
C.S. File 49/67

$\frac{1}{4}$ Corner to Sections 20 and 21.
Found - 2" Iron Pipe at Corner and Both Bearing Trees., See Ren. #39. 460
I Blazed & Scribed: 14" Cedar S.30*W. 142.3 ft. " $\frac{1}{4}$ S20 CS BT".
April 24, 1959

144

Marvin C.
Ramsey
April, 1959
C. S. File
No. 51/19

Section Corner to Sections 33 and 34.
Monumented with an Iron Pipe 2" diam., 8" above the ground and 223
marked "RS298, from which the Orig. BT's: See Ren. #124 & #132.
30" D. Fir bears N. 32* E. 37 lks. dist.
26" D. Fir bears N. 60 $\frac{1}{2}$ * W. 11 lks. dist.

filed May 6, 1959

145

John H.
Markham
For Stomar Lbr.
12/2/59
C. S. File
No. 42/345

$\frac{1}{4}$ Section Corner to Sections 4 and 9.
At Mid-Point, Set $\frac{1}{2}$ " x 36" Iron Pipe, from which:
9" Fir S. 60* E. 12.0 ft., " $\frac{1}{4}$ S9 X BT.
10" Fir N. 10* E. 24.2 ft., " $\frac{1}{4}$ S4 B.T.
10" Laurel N. 39* W. 10.3 ft. " $\frac{1}{4}$ S T29S R4W B.T."
10" Laurel S. 6* W. 10.5 ft. " $\frac{1}{4}$ S9 T29S R4W B.T."
S. E. Corner 4 bears S. 81*35'E. 2090.0 ft. S.W. Corner 4 bears 206
N.81*35'W. 2090.0 ft. Corner lies on west nose of high ridge.

Dec. 2, 1959

James W. Byron
& Crew
8/17/61
C. S. File
No. 49/67

Sec. Cor. to Secs. 3 & 4, T29=4W. & Secs. 33 & 34, T28-4W. 2 B.T.s G. Lang
Found - $\frac{3}{4}$ " I.P. & Both BT's., as recorded in Ren. #5, T28-4W. 4193
S.E. BT., now down, shows serbe marks. S.W. BT. shows good scar. 7/73
Set - Brass Cap at Cor. Mkd: County Surveyor's S 33 | S 34 T28S R4W
Office, 1961 S 4 | S 3 T29S
New BT's: 20" R.Fir bears S.51 $\frac{1}{2}$ *E. 30.2 ft. mkd: T29S R4W S3 CS BT.
5" R.Fir bears S.82 $\frac{1}{2}$ *E. 24.4 ft. mkd: S 3 CS BT.
Note - See Sketch of location of old Board Fence & Corner in C.S. 49/67.

152