

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

229 # 251
 $\frac{1}{4}$ Corner to Sections 3 and 2.
 Found - Orig. 24", now 32" Fir N. 55° E. 12.1 ft., orig. bark scribe "S" in good condition & "BT" scribed in wood as recorded in Ren. #169.

Brass Cap bent over & buried out of position.
 No trace of new BT. recorded Ren. #169.

Set - New Brass Cap Mkd: County Surveyor's Office, 1965
 T29S $\frac{1}{4}$ S 3/S 2 R4W

New BT: 11" W. Fir N. 70° W. 44.5 ft. Mkd: $\frac{1}{4}$ S3 CS BT.

Note - Corner apparently destroyed by cat work. This corner located approximately 15.0 ft. E. of cat. road on edge of timber.

James W. Byron, Co. Surv.
 Vernon R. Eracy
 M. D. & J. B.
 May 1965
 C. S. File No. 52/126

May 7, 1965

230

Corner Sec. 1, T29S, R4W. & Sec. 6, T29-3W.

Found - Orig. 18", now 30" Fir S. 35° W. 22.4 ft., now down, shows good scar.

Orig. 20", now 38" Fir S. 30° E. 40.2 ft., Open & find good scribing "S".

Set - Brass Cap at Cor. Mkd: $\frac{S}{S} \frac{36}{17} \frac{S}{S} \frac{6}{6}$ T28S T29S County Surveyor's Office, 1958
 R4W R3W

New BT's: 20" Cedar S. 71° W. 55.2 ft. scribed S1 T29S R4W CS BT.

18" Cedar S. 30° E. 29.5 ft. scribed S6 T29S R3W CS BT.

James W. Byron, Deputy
 M. Godfrey & S. Bilow
 June 1958
 C.S. File No. 49/47

Center NE $\frac{1}{4}$ of Section 5. or
~~Center of Section 5. N.E. 1/16 Corner.~~

Set - 1" Iron Pipe for center of section.

New BT's: 16" Cedar S. 22° 16' E. 23.1 ft.

8" Cedar N. 29° 23' E. 36.8 ft.

Nov. 1946

231

Geo. J. Wenderoth
 For J. Day
 C.S. 53/93
 M. 28 - 78A

Center of Section 25.

SET - $\frac{3}{4}$ " x 36" Galv. Iron Pipe for Center $\frac{1}{4}$ Corner.

Blazed & Scribed BT's: 18" Fir N. 42° E. 57.4 ft.

15" Cedar S. 65° W. 78.2 ft.

Both BT's. Mkd: T29S R4W C $\frac{1}{2}$ S25 CS BT.

May 1949

232

Ben B. Irving
 Arthur R. Evans
 May 1949
 M 1 - 31

FOOK By R. Brown 1-95 M 121-38

Center of Section 24.

Set - 1" x 36" I. Pipe for center of Section.

New BT's: 24" Fir S. 88 $\frac{1}{2}$ ° W. 7 $\frac{1}{2}$ lks.

8" Fir N. 35 $\frac{3}{4}$ ° W. 20 lks.

24" Fir N. 38 $\frac{1}{2}$ ° E. 51 lks.

18" Cedar N. 80 $\frac{1}{2}$ ° E. 28 $\frac{1}{2}$ lks.

August 1918

233

Floyd Frear
 M. B. Germond,
 Co. Surv.
 Aug. 1918
 CS File Vol 3,
 Page 25
 M 1 - 33

Corner for Townships 29 and 30, Ranges 4 & 5 West.

All old BT's. standing & in good shape, as follows:

12" Cedar N. 75° E. 1.5 ft. - 15" Cedar N. 17° W. 12.0 ft.

16" Cedar S. 76° W. 23.0 ft. - 24" Cedar S. 66° E. 41.0 ft.

At corner point found wood post & Set - 1" x 30" Iron Pipe.

New BT: 48" Fir bears S. 80° E. 9.5 ft. Mkd: T30S R4W S6 BT.

South $\frac{1}{4}$ Corner Sec. 31 bears N. 76° 30' E. 700.0 ft.

234

John H. Markham, Jr.
 G. Vaughn,
 Wit.
 1951

235

Center of Section 5.

Set - 2" Iron Pipe for corner, from which

New BT's: 32" Fir N. 59° 17' E. 99.4 ft.

28" Cedar N. 72° 12' W. 109.9 ft.

G. J. Wenderoth
 For J. Day
 Nov. 1946
 M 28 - 78A