

Douglas County Surveyor's Record of
Government Corners Renewed

T 29 T. S. R 4 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

261

CONT - - - -

Found - A 3/4" iron rod inside a 2" iron pipe bears S.86°02'E., 14.9 ft.
Renewals 44 and 81A and 167
A 48" D. fir per map M25-61 bears N.18°49'E., 175.7 ft. This tree has a good scar and two BLM bearing tree tags. The tag dated 4-63 reads 1/4 corner S.15°W., 171.5 ft. A second tag dated 7/78 shows the corner to be S.18 1/4°W., 174. ft.
A 32" cedar bears S.80°48'E., 113.2 ft. This tree also has a good scar and is referenced on map M25-61. A BLM tag reads N.81 1/4°W 113.5 ft. to the 1/4 corner. The tag is dated 7/78.
An old vine covered fence running N-S is 15 feet east of the proportioned corner I accepted. About 8 ft. south of the same corner, there is a fence in fairly good repair which runs E-W.

I did not accept the 1/4 corner per Wood, Vol. 3 Pg. 234, because he failed to place the corner at the proportional distance as stated in his field notes. His overall distance between the section corners agrees with my distance within approx 1 foot, however the proportioned corner that he set is 15 feet in error.

6/83

1/4 Corner for Sections 20 and 29.

(Ren. #1)

262

Found - 1969 BLM iron post found out of the ground.
A maple, 21", bears N.15°E., 52 lks. dist., fragmentary scribe marks visible on partially healed blaze.
A maple, 17", bears S.45°E., 4 1/2 lks. dist., fragmentary scribe marks visible on partially healed blaze.
Set - BLM iron post reset at record bearing and distance from bearing trees marked in 1969.

(No new accessories marked.)

Note: See also data in C.S. file regarding County visit and conflicting information.

10/16/8

263

1/4 Corner for Sections 34 & 35.

Found - Brass Cap. Ren. # 115.
18" W. Fir N.46°W. 54.5 ft.
Rotted Stump approx. S.21°E. 93.0 ft.
New BT - 6" Fir N.24°E., 8.2 ft. - Scribed 1/4 S34 BT.

10-92

Center 1/4 Corner for Section 34.

264

Set - 5/8" x 30" I.R. with plastic cap marked "LANG SURVEYING".
7" Madrona N.60 1/2°E. 12.3 ft. Scribed "C 1/4 S34 BT"
6" Fir S. 25 1/2°E., 19.0 Ft. Scribed "C 1/4 S34 BT"
15" Madrona S.23 1/2°W., 36.5 ft. Scribed "C 1/4 S34 BT"
5" Madrona N.23°W. 28.7 ft. Scribed "C 1/4 S34 BT"

10-92

265

Corner to Sections 15,16,21 & 22. See Ren # 226

Found - 3 1/4" Brass Cap on 2 1/2" dia. iron post, from which:
7" Cedar BT, bearing N.71 3/4°E., 19.1 ft. destroyed and gone.
25" Cedar BT stump, scribes visible, bears S.26°E., 38.0 ft.
28" D.Fir BT, face overgrown, bears S.36 1/4°W., 70.0 ft.
55" D.Fir BT, Bearing N.21 1/4°W., 77.9 ft. now gone.

New Accessories -

10" Cedar BT, scribed "T29S R4W S15 BT" bears N.83°E., 31.5'
16" Cedar BT, scribed "T29S R4W S22 BT" bears S.64°E., 8.0'
8" Pine BT, scribed "T29S R4W S16 BT" bears N.30°W., 37.4'

Note - Corner located at newer fence corner, fence bears N. and E.

1/4 Cor. for Secs. 16|15. CONDITION REPORT ONLY See Ren. # 227

266

Found - 3 1/4" Brass Cap on a 2 1/2" iron pipe from which:
24" D.Fir BT, face overgrown, bears N.62°E., 66.7 ft.
24" Cedar BT, face overgrown, bears S.20°W., 100.9 ft.
(record 75.2 ft.)

Note - Located on newer North-South fence line.

William Ruppert
LS 866
For: Richard Schallich
May-June 1983
M 94 - 61
C.S. 58/270

James White
Wayne Rogers
Bureau of Land
Management
Oct. 16, 1984
C. S. 62/24

Gregory Lang
LS 2295
For: Silver Butte
Timber Co.
Oct. 1992
M 117-1

Bruce Shaner
For: Roseburg Forest Products
Aug. 1993
R.M. 3-79; C.S. 63/96; C.S. 63/153