

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T.29S.      T. S.      R.4W.      R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21981

269

13" dia., double trunked madrone double blazed & scribed "NW INT DLC 39 CS BT" on east trunk, root crown bears West 23.2 ft.  
4" dia., W.Fir double blazed & scribed "X BT" bears N4½°E., 48.1 ft.  
27" dia., J.Pine double blazed & scribed "NW INT DLC 39 CS BT" bears N.9°W., 30.8 ft.  
Corner lies at the intersection of old mostly down fences running north and west.

Gregory Lang  
L.S. #2295  
For: Silver Butte  
Timber Co.  
April 1993  
M 118-13

**Center 1/4 Corner Sec. 4**  
Set - 5/8"x30" Iron rod with cap marked "LANG SURVEYING"  
BTs - 7" Fir, bears S.20°E., 7.0, scribed "C½ S4 BT"  
9" Fir, bears S.51°W., 7.8', scribed "C½ S4 BT"  
11" Fir, bears N.46½°W., 49.7', scribed "C½ S4 BT"  
8" Fir, bears N.6°E., 37.5', scribed "C½ S4 BT"  
Found - ½" I. P. bears N 78°45'51"E, 2.50' (M 2-4) Ren 248

270

4/93

1/4 Cor. Secs. 14 & 23  
Found - SW BT, 22" W.Oak w/good scar. (REN # 82)  
SE BT, 15" W.Oak w/good scar. (REN #82)  
Old Fence post lying on ground w/ribbon approx. 15' Northerly of SW BT.  
Did not find Iron pipe.  
Set - 5/8" x 30" iron rod with 3/4" Brass Washer at record distances from BTs.  
AT survey basis of bearing trees are now S.47°W., 26.2' and S.71°30'E., 66.5'.  
Attached bearing tree tags w/record distance & bearing.  
Note - Fence corner w/fences running West, North, & South is 1' East and 2' South from corner. Corner is on South side of private road.

William Ruppert  
L.S. #866  
For: B. Westrup  
June 1994  
1994-0080 A&B

271

272

**NOT FOUND REPORT Center 1/4 Section 35**  
Found - Bent 1" I.P. out of ground in ditch of dirt road approx. 350 ft. down hill along a cat road from area of corner search. (source unknown)  
Accessories Found -  
-26" dia. 5 ft. high rotting D.Fir stump with a BLM location tag, dated 1956, tagged by Markham. Says 0 ft. to corner set by transit. J.Markham was on field crew, apparently worked for Stomar Lbr. Co. Field notes and survey RM 1-8 do not mention this tree. No recorded BT's are found for corner. See renewal #117

Douglas County  
Surveyor's Office  
Randall Smith  
Stephen Flause  
Mar. 8, 1995  
C.S. 64/58-6

**SEC. 26 SW COR** see renewal #209  
Mon. Fd. - 2½" dia. DCSSO Brass cap on a 1½" O.D. Iron pipe, protrudes 9" above ground.  
Accessories Fd. -  
A search for Orig. BT's made no oak's found  
10" now down and rotted 11" D.Fir, with illegible bark scribing found, bears S.37°E., 32'.  
8" now 13" dia., 3' rotted D.Fir stump, bark scribing visible "BT", bears S.15°W., 29.8'.  
14" now 16" dia. Cedar, with a partially healed single scribing visible "29S R4W S34 CS BT", bears S>5°W., 33.4'.  
9" now 12" dia. dead cedar, with a partially healed double blaze, scribing visible "3", bears S.32°W., 56.3'  
14" now 21" dia. Cedar, with a fully healed double blaze, bears S.20½°E., 103.2'.

273

Douglas County  
Surveyors Office  
Randall Smith  
Stephen Flause  
Apr. 11, 1995  
C.S. 64/63-6

(Cont. Next Page)