

Douglas County Surveyor's Record of  
Government Corners Renewed

29 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

N. E. Corner D. L. C. # 48. *See #84*

1 1/2" x 2 1/2" iron pipe set.

**RE-RENEWED, SEE CORNER NO. #84**

E.S. Woodford  
1953  
AUG 14, 1947  
M 21-16

N.W. Corner Cl. # 45.

Reset at record distance (1.42 chs) from 1/4 cor. secs 21-28, on section line between 21-28.

Set 3/4" iron rod.

Blazed and Scribed two B. T.s.

24" Oak (white) N 84° E., 83.0 feet.

20" Oak, W 8° E., 44.5 feet.

No suitable trees in claim.

**RE-RENEWED, SEE CORNER NO. #230**

1/4 section corner between 15 and 16.  
Determined by single proportional measurement.

At midpoint on section line set 1" X 30" iron pipe, from which

A 16" Fir bears S.51°W, 8.3 feet distant, Mkd 1/4 S 16 B. T.

A 18" Fir bears N.35°E., 15.1 feet distant, mkd 1/4 S 15 B. T.

Corner lies on N.E. slope approx. 400 feet East of Ridge.

Section corners lie N., 2214.3 feet and S., 2214.3 feet.

1/4 cor. between secs. 4 and 5.

Set by proportionate measurement. Set 1 1/4 inch iron pipe and 2 B. T.s.

24" W. O. S. 69 1/2° W., 57.7 feet.

12" W. O. S. 33 3/4° W., 67.9 feet

Position of corner determined by B. T.s. W. O. S. 70° W., 45 feet.

W. O. S. 28° W., 57.5 feet.

**RE-RENEWED, SEE CORNER NO. #201**

LATEX EMISSION COR. SEE FILE 9/227

NW corner D. L. C. # 47.

Old B. T. N.46°48'W., 42.1' dist. has been cut. Stump scribed B. T. visible - We did not look for other B.T. which was B. Oad S.25°E. 238.26 feet distant. *REN. No. 1*

Blazed and scribed two new B. T.s.

18 inch Oak mkd. C.L. # 47 N. W. C. S. B T.-N.17°W., 79.3 feet dist.

20 inch B. Oak; N.60°W., 74.0 ft. dist. Mkd. NW CL 47, CS BT.

Mag. Var. 21 1/2°.

*Fd. 3/4" I.P.  
By G. GARDNER  
Dec. 1951  
RM 3-52*

South 1/4 corner section 24.

Corner positively identified from stumps of old BTs.

which were - 12 inch cedar N.5°W., 87 lks. and - *REN. #42*

10 inch fir N74°E., 63 lks. Scribing still legible.

We set 3/4 inch iron rod and blazed and scribed two new trees.

10 inch red Fir N.85°W., 46.5 feet dist. mkd 1/4 Sec. 24, CS BT.

12 inch R. Fir N55°E., 40.0 feet dis. mkd 1/4 sec. 24, CS BT.

NW cor. D.L.C. # 50.

We found 1 1/2 inch iron pipe at corner, and stump of old BT. N57°W., 16 lks.

Old scribe visible. *REN. #41*

Blazed and scribed two new bearing trees.

10 inch R. Fir, S60°W., 23.1 feet dist. mkd. NW CL 50, CS B. T.

8 inch R. Fir, S20°W., 34.5 ft. dist. mkd. NW CL 50, CS B.T.

NE Cor. DLC No. 48.

Found 1 1/2 inch iron pipe.

Old B. T. in good condition. No other B.T. visible. Scribed and blazed 1 1/2 inch iron pipe at corner, CL 48, CS BT.

**RE-RENEWED, SEE CORNER NO. #203**

*For Paul Kutter*

77

78

79

80

81

82

83

84

Ben B. Irving  
1951  
1953  
C.B.  
FILE 53/94

John H. Markham  
Wife: Earl Stonerod  
October 9, 1953  
Work done for Earl  
Stonerod.  
Sur. file 41/198

Arthur R. Evans  
Aug. 11-13, 1953  
Sur. file  
no. 41/227.

James Byron - Ray Irving -  
Filed in sur. file # 45/231  
Dec. 11, 1953

Ben B. Irving  
Jim Byron  
Ray Irving  
File 45/234  
Page p.