

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section corner to secs. 1 & 2, T29S, R5W., and secs. 35 & 36, T28S, R5W.
Found - All of Coles BTs. The N. E. BT is a stump only & rotted face
well scribed. All other BTs down & rotted but some scribing visible.
All BTs check for bearing & distance.

Set an iron pipe with brass cap at corner mkd. $\frac{35}{2} | \frac{36}{1} \frac{T28S}{T29S}$ R5W County
Surveyor's Office, 1957.

Blaze and scribe:

- 4 inch Laurel, S.82°W., 57.4 feet, mkd. S 2 CS BT.
- 5 1/2 inch R. Fir, S.24°E., 72.2 feet, mkd. S 1 T29S R5W CS BT.
- 4 inch R. Fir, N.18 1/2°W., 22.0 feet mkd. S 35 CS BT.
- 4 inch Laurel, N.46°E., 25.1 feet, mkd. S 36 CS BT.

104

James W. Byron, Deputy County Surveyor
April - May, 1957.
C. S. File No. 47/180.

Township corner to secs. 31, 36, 1 and 6, Tps. 28 & 29, Rgs. 4 & 5 W.
Found 3 original BTs. I open NE BT and find good scribing. The NW
BT gone-stump hole only. I do not open SW or SE BTs-show old blazes and
all check for bearings and distances.

Note: Corner 10 feet west of N-S fence.

Set an iron pipe with brass cap mkd. $\frac{36}{R5W} | \frac{31}{T29S} \frac{T28S}{R4W}$ County Surveyors Office,
1957.

Blaze and scribe new trees:

- 20 inch R. Fir, N.82°W., 10.8 feet, mkd. T28S R5W S36 CS BT.
- 12 inch R. Fir, S.46°W., 54.2 feet, mkd. T29S R5W S 1 CS BT.
- 12 inch R. Fir, S.54°E., 50.4 feet, mkd. T29S R4W S 6 CS BT.
- Reblaze and rescribe orig. 16 inch B. O. (now 24 inches), N.31°E.,
25.1 feet, mkd. T28S R4W S 31 CS BT.

105

Sec. Cor. to Secs. 4 and 5, T29-5W. & Sec. 32 & 33, T28-5W.

Found - All 4 BT's. as recorded by Eppstein, 1926, See Book, 1, (Ren. #152)
Page 104. Distance to N.E. BT. should be 120.0 ft. and
Distance to S.E. BT. should be 148.8 ft. All BT's. show
good scars. I do not open.

Note 1/2 Corner is under East West Fence.

Set Brass Cap at Cor. Mkd: County Surveyor's $\frac{S32}{S5} | \frac{S33}{S4} \frac{T28S}{T29S}$ R5W
Office, 1961

No new BT's scribed.

106

1/2 Cornew to Sec. 3, T29-5W. & Sec. 34, T28-5W.

Found - 3" I. Pipe at Corner. - 18", now 36" W.Oak S. 36°W. 146.4 ft.,
not 446.4 ft. We open & find good scribing. - Ren. #35
Orig. S.W. BT., center rotted.

Note - Corner is in field. I set Wit. Cor. 10 ft. South & under E.W. Fence.

Set Brass Cap at Wit. Cor. Mkd: County Surveyor's $\frac{1}{4} \frac{S34}{S3} \frac{T28S}{T29S}$ R5W
Office, 1961 W.C.

New BT's: 7" R. Fir bears S.48°W. 137.0 ft. scribed 1/4 S 3 CS BT W.C.
14" W.Oak bears N.88°W. 236.3 ft. scribed W.C. 1/4 S34 CS BT.

107

Sec. Cor. Secs. 3 - 4, T29-5W. & Sec. 33 & 34, T28-5W.

Found - 3" I. P. at Corner. - 16", now 24" Fir Snag N.38°E. 6.7 ft.,
shows good scars. - 16", now 28" Fir N.40°W. 41.1 ft., shows
good scars. - 16", now 28" Fir N.40°W. 41.1 ft., now 24"
Fir Snag S.28 1/2°E. 20.0 ft.; shows scars. S.W. BT., now fence
corner & may die, in 1961 fire area. - Ren. #34

Set Brass Cap Mkd: County Surveyor's $\frac{S33}{S4} | \frac{S34}{S3} \frac{T28S}{T29S}$ R5W
Office, 1961

New BT's: 12" R. Fir bears S.78°W. 39.2 ft. scribed S 4 T29S R5W CS BT.
16" R. Fir bears N. 8°E. 57.3 ft. scribed S34 T28S R5W CS BT.
No live trees near to S.E.

108

Sec. Cor. to Secs. 5 - 6, T29-5W. & Sec. 31 & 32, T28-5W.

Found - 3" I. P. at Corner & N.E. and N.W. BT's, as recorded .
S.W. BT. is gone. - Ren. #35 IN T. 28-5

I scribe New BT: 11" Laurel bears S.44°E. 6.5 ft. scribed T29S R5W S 5 CS BT.

109

James W. Byron, Deputy County Surveyor
Dale McFarland
Jim Powell
September 1961 - C. S. File No. 49/64

RE-RENEWED

RE-RENEWED (DUP OF #200) #212

RE-RENEWED (DUP OF #200) #233

RE-RENEWED (DUP OF #200) #183