

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

CONT.

30" now 60" maple, Ren. #52 bears S.45°W., 153.1 ft.  
(rec. S.45°W., 151.1 ft.) with partial scribes  
"29 S32 CS" showing on previously opened blaze.  
A brass cap reference monument, mkd. as noted  
previously in this renewal bears S.35 1/2°E.,  
22.6 ft. (rec. S.40°E., 21.8 ft.)

No trace was found of a reference monument to the N.E. also  
set in 1957. The following bearing object is noted: The N.E.  
corner of a concrete foundation for a wood frame home bears  
S.22°W., 94.5 ft.

Gary Langlitz  
P. Earle  
C.S. 56/51  
4/26/74

Section Corner 31 & 32 T 28-R5 and Sec.6 & 5 T 29-R5

183

Found 3/4" X 28" IP at corner

From which: A madrone, the main trunk of which is 11" in dia. bears S 44°E.,  
6.5 ft. REN. #109

A 14" B.Oak bears N70°E., 10.0 ft. (call: N67 1/2°E., 9.6 Ft)

A 25" B.Oak bears N81 1/2 °W., 51.1 ft ( call: N81°W 49.5 ft)

\* Calls appear to have been to the scribed face.

Renewal: At the corner we set a 1" X 30" IP with brass cap stamped

|             |   |
|-------------|---|
| T 28 S      | R |
| S 31   S 32 | 5 |
| S 6   S 5   | W |
| T 29 S      |   |

DOUGLAS CO. SURVEYOR  
1975

JAN 75

Clell Goodwin  
Gary Langlitz  
Vic Cangie  
Lenora Ladig  
CS 57/39  
12/2/75

The S.W. quadrant is an open field with no trees nearby so we do not scribe  
a tree in Section 6

Corner Lies 1 mile more or less from Clark's Branch Rd. on Richardson Cr.Rd.  
corner lies 200' + north of the road in a fence corner. Fences run south,  
east and west. Compass declination 20° East 12/2/75

184

Sec. Cor. for 19 and 30; and Secs. 24 and 25 of T29-6

Found - 1969 County Surveyors Office Brass cap properly marked bears  
N.68°E., 17.4 ft. from orig. corner located from O.B.T.

From Brass Cap: Ren. #162

A 13" now 18" D. Fir bears S.40°W., 25.1 ft.

A 14" now 22" D. Fir bears N.43°W., 30.2 ft.

A 6" now 8" D. Fir bears S.56°E., 35.3 ft. (Rec. 25.2 ft.) BT  
tag said 35.2 ft.

All BT's had double well healed blazes.

From Apparent orig. corner location:

A D. Fir stump, 15" now 40" bears S.2°E., 137.3 ft. with prev.  
opened single blaze. Found scribing "2" S30 BT

Set - Reset Brass cap in orig. location stamped to now read

|                           |             |
|---------------------------|-------------|
| Douglas Surveyor's Office | T 29 S      |
| 1969                      | S 24   S 19 |
|                           | S 25   S 30 |
|                           | Reset       |
|                           | 1977        |

FD. 7/77 BLM ADMIN. SURVEY  
SEE GIS FILE

Drove a 5/8" Iron rod with alum cap at location where we removed brass cap.  
Alum Cap bears N.68°E., 17.4 ft. stamped "CS 1977". We used already scribed  
BT's which now face 5/8" I.R., as follows:

A 18" D. Fir bears S.0°30'W., 13.7 ft.

A 22" D. Fir bears N.9°W., 28.4 ft.

A 8" Twin trunked D. Fir bears S.75°E., 47.9 ft.

All BT's have double well healed blaze.

A wire fence running W & N has corner which bears N.15°E., 35.0 ft. dist.

6/14/77

185

South 1/16 Corner for Sec. 30 and Sec. 25 of T29-6.

Found - A 1" I.P. firmly set extending 14" above ground with 1969

County Surveyors brass cap properly marked. See M37-20

A 9" now 11" D. Fir alive with well healed double blaze bears  
S.83°E., 36.7 ft.

An 11" now 12" D. Fir alive with well healed double blaze, bears  
N.43°W., 10.5 ft. (Rec. per 1969 survey N.43°W., 11.2 ft.)

This 1969 corner location is now wrong due to the recent identification of  
the original corner common to Sections 19 and 30, T29S R5 W and Sections  
24 and 25, T29S R6W.

R Kimberling  
P. Earle  
June 14, 1977  
C.S. 59/34

Doug. Co. Surveyors Office

Doug. Co. Surveyors  
Office  
Gary L. Langlitz  
P. L. Earle, F. Sillagy  
Dec. 8, 1977  
C.S. 59/42