

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29

T. S.

R 5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

NOTE: ROTATION ERROR OF #° ON MAPS M 82 - 10 AND M 81 - 29 AND CORRESPONDING ROTATION OF BEARING TREE BEARINGS. 213

Section corner for Sections 5, 6, 7 and 8
 Found - Orig. BT, 18" B. Oak, N.33°W., 31.0 ft. Good scar.
 7" W. Oak, S.44 1/2°W., 18.8 ft. Good Scar.
 County brass cap was destroyed by clearing operation. Ren. #120
 Set - 1" x 36" Iron pipe with 2 1/2" brass cap at dist. and bearing
 from O.B.T. marked T29S R5W S6 S5 S8 S7 PLS 866 1980.
 New BO's - 5 ft. Steel fence post, S.23°12'E., 24.1 ft.
 5 ft. steel fence post, N.44°08'E., 26.0 ft.

William Ruppert
 For: Ron Kuehn
 October 1980
 M 84 - 58
 C.S. 58/143 (n)

(See notation re:
 bearings)

1/4 Corner for Sections 6 and 5. 214
 Found - Cain's BT, W. Oak, S.23 1/2°W. 67.98 ft. with scribing on
 rotten face. Ren. #23 See also #121.
 Set- 1" x 36" Iron pipe with 2 1/2" brass cap marked T29S R5W
 1/4 S6 S5 PLS 866-1980.
 New BT's- 7" W. Oak, bears S.37 1/2°W., 56.2 ft. scribed "1/4 S5 BT"
 5" W. Oak, bears S.56 1/4°W., 20.5 ft. "1/4 S6 BT".

1/4 Corner for Sec. 5; and Sec. 32 of T.28-5 215
 Found - 2 1/2" brass cap per M 82 - 10. Ren. #202
 8" W. Oak, S.77°W., 27.9 ft.
 8" W. Oak, N.21 3/4°E., 107.1 ft.

SE corner for DLC #48 216
 CONDITION REPORT ONLY
 (This information brought in by G. Grubb per his survey for V. Rice
 M 89-31 - Corner not of previous record - Engineer #3900 is Donald
 Martin.)
 Found - 2" brass cap on 1" I.P. stamped "SE Cor DLC 48 3900"
 31" fir stump bears N.35°W., 6.6 ft. scribing visible in
 chopped out face, "48..9s..W" still legible. Tree was 12"
 dia. when scribed.
 11" Madrona, new BT, bears N.60°E., 30.1 ft. scribing visible
 in open face "SE C DLC 48 T29S R5W BT"
 9" Fir bears N.39°W., 60.3 ft. BT tag reads "posted by D. Bentz
 & C. Wallace in 3-69".

George Grubb
 For: Victor Rice
 October, 1981
 M 89 - 31
 C.S. 58/229

Center 1/4 Corner of Sec. 23. 217
 Set - 2-1/2" x 31" I.P., 25" in the ground w/Brass Cap stamped:
 "T29S R5W C1/4 S23 1981 PLS 397"
 BTs - 14" Apple bears S.13°E., 212.2-ft., scribed "C1/4 S23 BT" (dble. face).
 32" W. Oak bears N.9-1/2°W., 386.8-ft., scribed "C1/4 S23 BT" on
 a double face. 12/81

George Grubb, PLS#397
 For: G. Thomasson
 December, 1981
 RM 3-52

1/4 Corner common to Sec. 1, and Sec. 36, of T.28-5. 218
 Set - 1" x 30" galv. I.P. w/ 2 1/2" B.C., mkd: T28S R5W 1/4 S36
 S1 T29S 1983 LS866.
 New BTs- 7" madrone bears northeasterly, 0.7-ft. (Both trees scribed:
 8" madrone bears N.41°15'W., 9.2-ft. "1/4 S36 BT")
 Note - Fnd. 25" black oak bears N.11°E., 69.1-ft. w/Oregon State Bd.
 of Forestry tag which reads "we chopped this tree 3-30-73
 approx. 1/4 cor. 45° S". I re-opened the tree & found no
 evidence of face or scribing.
 Note - New BT (0.7-ft. from cor.) has a tag from Douglas County
 Forestry Appraisal Depart. 11-29-54, stating that corner is
 approximately 1/4 chain northwest.
 Note - An east-west fence is approx. 10-ft. north of proport. cor.

William J. Ruppert
 LS#866
 For: Deam, Richard
 Jan.-Mar.1983
 M 93 - 68

1-3/83
219