

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

219

*FD. I. R.
7/91
W. Ruppert
M 112-32*

Section corner for Secs. 29, 28, 32 and 33.
 Found - 5/8" dia. I. Rod firmly set and buried 20 inches below surface. Ren. #182
 Not found - Original post, rifle barrel and angle iron from Renewals #6 and #52.
 Found - 12" now 16" maple with well healed blaze bears N.53°W., 165.7 ft. (Rec. N.52 1/4°W.)
 13" now 18" double trunk maple with well healed blaze bears S.78 1/2°W., 90.4 ft. (Rec. S.79 1/2°W.) to center of root crown.
 30" now 60" maple bears S.45°W., 153.1 ft. Scribing "S32 CS" visible on partially rotted blaze.
 The NE corner of house foundation bears S.21°W., 94.5 ft.
 Found disturbed 2" x 30" iron pipe with brass cap marked T29S R5W S28 RM 1957" bears N.60°E., 36.2 ft. (Rec. 37.2 ft.) (BLM) to base. We RESET monument at this position, firmly set flush with ground and add "DCSO RESET 1985" to cap. Set iron fence post alongside.
 Found disturbed 2" x 30" iron post with brass cap marked "T29S R5W S33 RM 1957" bears S.37°E., 21.94 ft. to base (Rec. S.35 1/2°E., 22.6 ft.) (BLM). We RESET monument at this position, firmly set flush with ground and add "DCSO RESET 1985" to cap. Set iron fence post alongside.
 Set - To facilitate location with electronic metal detector, we place misc. pieces of iron (bridge spikes and metal strap) above monument. These pieces of iron do not identify corner location to an accuracy closer than plus or minus one foot.
 Note - This corner if in area used occasionally for gardening and R.V. parking.

Douglas County
 Surveyors Office
 Larry E. Monrean
 Deputy
 R. W. Smith
 S. J. Flause
 July 30, 1985
 C.S. 62/28

7/30/85

220

Section corner for Secs. 30 and 31; and 25 & 36 of T.29-6
 Found - 1977 County brass cap with a 1" iron pipe along side of pipe with brass cap. Ren. #192
 38" W. fir stump which bears S.60°W., 11.2 ft. scribes visible.
 40" fir stump bearing S.73 1/4°E., 55.5 ft. scribes visible.
 34" fir stump bearing N.67 1/2°W., 42.2 ft. This stump cut too low for any scribing to remain.
 All other bearing trees were destroyed in logging. Also the 30" fir stump 64.2 ft. east is gone.
 New BTs - 10" W. fir bears N.67°E., 38.4 ft. marked T29S R5W S30 BT.
 6" fir bears N.52°W., 74.4 ft. marked T29S R6W S25 BT.

Burton W. Holt
 L.S. #418
 Sun Studs, Inc.
 Gary Angiolet.
 Aug. 7, 1985
 C.S. 63/8

8/7/85

221

Southwest corner for DLC #42
 Found - An original stone first noted in the orig. survey notes of DLC #43 and first described as a 12" x 16" stone, marked DLC 42 in the unrecorded Gray Acres Plat, C.S. 50/56, is now a broken but firmly set stone, marked with a 4 and a 2, partially broken off. Stone measures 8" x 8" x 14".
 A 3/4" iron pipe firmly set but leaning southwesterly bears North approx. 1.3 ft. (Rec. North 1.6 ft.) C.S. 50/56
 A 3/4" iron pipe firmly set but leaning south. At its plumb position, it bears North 110.2 ft. C.S. 50/56
 3/4" x 3/4" angle iron firmly set and protruding 6" from the ground bears West, 226.9 ft. (Rec. S.89°57'W., 227.2 ft.) M9-43
 A DCSO brass cap on an iron pipe set flush with ground bears South, 82.0 ft. Ren. #197 (Witness corner)
 New Accessories
 A 5/8" iron rod with a plastic cap marked LS 866 protrudes 5" above ground and bears N.46 1/2°W., 44.0 ft. M 99 - 10
 An unrecorded 3/4" iron pipe protruding 1 ft. above ground bears S.2 1/4°E., 38.6 ft..
 A 5" DBH O. Ash bark scribed SW DLC 42 CS BT, bears N.72 1/2°W., 18.0 ft. dist.

*FD Stone &
I.P. 7/91
W. Ruppert
M 112-32
FD Stone & IP
3/93 W. Ruppert
1993-0040*

Douglas County
 Surveyors Office
 Randall Smith and
 Stephen Flause
 Oct. 10, 1985
 C.S. 62/29

Note: On east edge of drainage ditch at intersection of ditches from east and southeast approx. 500 ft. west of the south end (point where road turns due east) of Weeks Road.

10/10/85