

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 6 R. W. W. M.

41

✓ CORNER TO SECTIONS 27, 28, 33 and 34.

I renewed this corner from 20 inch Cedar bearing tree which was standing with scribe marks plainly showing N.40°W., 37 lks. Maple down bearing scribe S.30°W., 13 lks. Maple decayed no scribe marks showing bears S.35°E., 33 lks. Cedar down N.50°13 lks. corner in creek on pile of logs. Marked new trees

A Fir 10" dia. S.40°W., 28 ft.

A Cedar 20" dia. N.38°E., 49.0 ft.

Face of Boulder 5 ft. x 5 ft. x 5 ft. S.24°E., 9.9 ft. marked S.34, C.S., B.O, Erected mound of rock 20 ft. North of corner.

J. W. Cole C.S.
March 7, 1924
Wit.
M. B. Hawkins
Doc Rice

42

✓ EXTERIOR "L" CORNER OF CLAIM # 45.

No evidence of this corner found. Set fir post 4" x 4" x 48" for corner scribed and a car axle with gear attached Cl.45 C.S. from which

A 16" Fir bears N.17°E., 49 lks. scribed Cl. 45 C.S. B. T.

This post was set at the intersection of a line south from the N.E. corner of the claim and a line east from the interior "L" corner as set by Kane in 1913.

Ben B. Irving, Deputy County Surveyor
January 26 and Feb. 1, 1929.
Witnesses: W. S. Grear, Chas. Lucas and Edward Evans

43

✓ 1/4 SECTION CORNER BETWEEN 15 and 21. SEE CORNER NO. 98
As described by Cole, one O.B.T. alive and in excellent condition. Cedar stake in fair condition. No B.T. in section 16. Drove car axle for corner and marked a new B.T. in REN. 33

A 6" Fir N.20°W., 18 lks. 1/4 S. 16 C.S. B.T.

44

✓ SECTION CORNER BETWEEN 16, 15, 21 and 22. SEE CORNER NO. 168
No evidence of corner post or B.T.s found after extensive search. Located corner at intersection of Blazed line east and north as being unquestionably the original lines. Drove a car axle for corner from which

A White Oak 12" dia. bears N.55°E., 22 lks. scribed T.29 S., R.6W., 15 C.S.B.T.

A Fir 15" dia. bears S.37 1/2°E., 64 lks. scribed T.29 S., R.6W., S.22 C.S.B.T.

A Fir 14" dia. bears S.10°E., 57 lks. scribed T.29S. R.6W., S. 21

A Fir 30" dia. bears N.37 1/2°W., 93 lks. scribed T.29S. R.6W., S.16.

45

✓ 1/4 SECTION CORNER BETWEEN 21 and 22. SEE CORNER NO. 47
Position identified by O.B.T. S.55°W., 5 lks. as described in original notes. B.T. now dead. Drove 3/4" x 54" Gal. Iron Pipe for corner and a 6" x 6" x 42" Cedar post scribed 1/4 S. C.S. on South face, S. 21 on West face and S. 22 on East face. Marked New B.T.s

A 14" Fir N. E., 14 lks. 1/4 S. 22 C.S. B.T.

A 15" Fir S. W., 53 lks. 1/4 S. 21 C.S. B.T.

46

✓ 1/4 SECTION CORNER BETWEEN 20 and 21. #271
Position identified from Fir post scribed 1/4 S. C.S. and a 12" White Oak N.30°W., 79 lks. mkd. 1/4 S. C.S. B.T.
A 12" Fir S.89°E., 43 lks. mkd. 1/4 S. C.S. B.T.
This corner was set by Frank Cain about 15 years ago according to Frank Royer a local resident who was present on both surveys. Could find no record of this corner in county records. Drove a car axle for corner and as Cains B.T.s were okay made no change.

Ben B. Irving D.C.S.
Jan. 30, 1929
Witnesses
Frank Royer
W. S. Grear
Chas. Lucas
J. H. Markham-Eng
Witnesses
Geo. & M. Vaughn
March 21, 1951

47

✓ 1/4 SECTION CORNER BETWEEN 21 and 22.
Completed notes.
16" Fir N 73° E, 9.5 ft. dist.
20" Fir S 62° W, 34.0 ft. dist.
At corner 7" x 7" cedar post and 3/4" iron pipe

45 + 47
CORNER NO. 214

RECORDED CORNER NO.