

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97190

*2/12/71 - SEARCHED FOR, NOT FOUND
C.S. FILE NO. 49/139 J.M.P.* **91**
 $\frac{1}{4}$ sec. corner 9 - 10.
 Determined by OBT. A 24" B.O. windfall bears S.65W., 587.0 ft. dist. O.B.T found scribe.
 At corner point set 1" x 30" iron pipe from which
 A 10" Maple bears N.23°W., 166.0 ft. dist. mkd. $\frac{1}{8}$ S 9, B. T. **217**
 S.E. corner of Cemetery bears S.82°W., 315.0 ft. dist.
 Centerline County Road bears West 150.0 ft.
 Corner lies in large field between Willis creek and Road.

John H. Markham Jr.
 Witness:
 Dennis Vaughn
 Dec. 6, 1953
 For Markham Bros.
 File 41/255

SEE CORNER NO. 95 92
 $\frac{1}{4}$ cor. between secs. 27-28.
 This corner renewed from orig. bearing trees, both of which were standing.
 Set an Oak post and a 1 inch iron pipe for the corner and marked new trees as follows:
 A Fir 12 inches in dia. N.77°45'E., 20 feet.
 A Fir 16 inches in dia. N.13°W., 42.2 feet.

J. W. Cole, Sur.
 Feb & March 1924
 For Rice Bros.

93
 Northwest corner of D. L. C. No. 46. (Gilliland d D. L. C.)
 Established this corner 27.5 chains W. of the NE. corner and 72 chs N. of SW. corner.
 Drove a $\frac{3}{4}$ inch iron pipe at corner and marked the following:
 16" W. O., S.30°45'W., 339.5 feet.
 12" W. O., S.19 $\frac{1}{2}$ °E., 447.3 feet.

Art Boyer
 December 30, 1954
 Witnesses:
 A. B. Rice
 A. E. Rice
 Hoy Rice
 Victor Rice
 C. S. File 41/276

94
 Southwest corner of D. L. C. No. 46. (Gilliland D.LC)
 Found stump and Blazed bark of Orig. B.T. Also post hole which is S.40°E., 89.8 feet from stump, and which matches fences to N. and E.
 Drove $\frac{3}{4}$ inch iron pipe at corner and marked the following 2 B. T.s:
 12" Oak grub, N.25°W., 40.5 feet.
 12" Maple, S.46 $\frac{1}{2}$ °E., 42.4 feet on 27° slope.

95
 $\frac{1}{4}$ corner secs. 27 and 28.
 Found both original BTs. The 30" Laurel is down and center is rotted. No scribes visible. Old blaze for BT faces o.k. Bearing is N.40°E., 115 lks. The 30" W. O., N.32°W., 31 lks. is standing but center is rotted. No scribing visible. *SEE REN. # 92*
 Set 1" pipe with brass cap from original BTs., mkd. County Surveyor's Office, 1954, $\frac{1}{8}$ S 28/27, T29S., R6W. *FD. 10/83 D. HOLT 95.35*
 Blazed and scribed:
 8" Cedar., S.45°W., 22.8 feet marked $\frac{1}{4}$ S28 CS BT.
 20" R. Fir., N.40°E., 15.4 feet marked $\frac{1}{4}$ S27 CS BT. (Bark scribed).

James W. Byron, party chief.
 Ray Irving
 John Fee

96
 Section corner to secs. 20, 21, 28 and 29.
 Found:
 1" iron pipe on E. W. fence line. checks bearing and distance to Laurel B. T. "36". Laurel in good condition. All other BTs in poor condition, but check for bearings and distances. *REN. No. 82 & 80*
 Blazed and scribed:
 14" R. Fir, S.89°W., 5.5 feet dist., marked S29 T29S, R6W., CS BT.
 10" R. Fir, S.38°E., 66.8 feet dist., marked S28 T29S, R6W CS BT.
 18" R. Fir, N.80°E., 100.0 feet dist., marked T 29 S, R6W., CS BT.

97
 Section corner to secs. 14, 15, 22, and 23.
 Found:
 1 inch iron pipe at corner. Also a 18" R. Fir Stump, scribed S14 BT., N.42°E., 26.5 feet dist. May have been scribed 25 years ago. *REN. #13*
 18" R. Fir, S.80°W., 30 feet has old blaze we did not cut out.
 30" R Fir, S.28°E., 20.6 feet has old blaze we did not cut out. **178**
 All trees are healthy and in good condition. *found 12-1975*

Renewal of corners for county
 by County Surveyor's Office.
 June 7 - 14, 1954.
 See County Surveyor's File No. 46/45.

98
 $\frac{1}{4}$ section corner of secs. 16 and 21.
 Found:
 Car axle and mound of stone. Also Cedar post scribed $\frac{1}{4}$ S 16. *REN #33 & 43*
 BT 6" Fir N.10°W., 12.0 feet, down and rotted but some scribing visible.
 Blazed and scribed:
 14" cedar, N.37°W., 20.8 feet dist., mkd. $\frac{1}{4}$ S16 CS BT.
 14" cedar, S.5°W., 9.8 feet dist., mkd. $\frac{1}{4}$ S 21 CS BT.