

Douglas County Surveyor's Record of
Government Corners Renewed

M.W.H.S. 29 T.S. 6 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$ Section Corner to Section 8 & 9. 134
Both original BTs. gone.
Corner position determined by the extension of the section line from
N.W. Corner Sec. 9 through interior L corner DLC 47 and half distance
between N.W. & S.W. Corner Sec. 9.
I blaze & scribe 4 ft. W.O. S. $54\frac{1}{2}^{\circ}$ E. 117.5 ft. $\frac{1}{4}$ S9 CS BT.
I blaze & scribe 10" W.O. N. 86° E. 194.0 ft. $\frac{1}{4}$ S9 CS BT.

Section Corner to Sections 8, 9, 16, & 17. 135
Found - $\frac{3}{4}$ " bolt only. No BTs.
Set 1" I.P. with brass cap marked 8 | 9 T29S R6W County Surveyor's
Office, 1957
Blazed & Scribed: 6" R. Fir N. $40\frac{1}{2}^{\circ}$ W. 23.4 ft. S8 T29S R6W CS BT.
9" R. Fir S. 22° W. 50.5 ft. S17 T29S R6W CS BT.
12" R. Fir S. 2° W. 31.7 ft. S17 T29S R6W CS BT.
15" R. Fir N. 72° E. 32.8 ft. S9 T29S R6W CS BT.
Note: See Sketch in File.

Renew S. W. Corner D.L.C. 47. 136
Found - Both BTs. as set by Cole, 1921. Check for bearing & distances.
S.E. BT. alive, center rotted, found C L scribe. -REN. NO. 111
The S. 79° E. BT. center rotted at old blaze but found BT scribe
at base of tree.
Looked for old plow frame at corner. Could not find, D. Rice
says he leveled field.
We also find original BT. recorded S. 5° E. 76.2 ft. to be south
76.2 ft. Center & all of Original blaze rotted. No Scribe.
I set 1" I. Pipe with Brass Cap marked S.W. Cor. D.L.C. 47, T29S, R6W
County Surveyor's Office.
New BTs: 24" W. O. N. 5° W. 33.8 ft. scribed S.W. Cor. DLC. 47 CS BT.
20" W. O. S. $85\frac{1}{2}^{\circ}$ W. 134.4 ft. scribed S.W. Cor. DLC. 47 CS BT.

Renew Int. L Corner D.L.C. 47. 137
Both BTs. as set by Boyer, Alive. -Ren #68
The N.W. BT. face is partly rotted.
I Scribe 8" W. O. N. 6° W. 78.9 ft. Int. L. CL CS BT.

Renew S. E. Corner D. L. C. 47. 138
We find the $1\frac{1}{2}$ " Pipe as shown on Page 4 of notes to be out of
position, as set by Cole in 1921 by traverse, also by topo, in relation
to Coles vertical angles North of corner. -REN No. 112
I leave $1\frac{1}{2}$ " Pipe at position tied in Page 4, and set 1" I.P. with
Brass Cap marked County Surveyor's Office, 1954 S.E. Cor. DLC 47 T29S R6W,
which is 145.8 ft. North & 13.8 ft. East of $1\frac{1}{2}$ " Pipe.
Blazed & Scribe 7" R. Fir N. 39° E. 167.8 ft. S.E. Cor. CL 47 CS BT.
Blazed & Scribe 8" Laurel S. 36° W. 54.7 ft. S.E. Cor. CL 47 CS BT.

Renew N. E. Corner D.L.C. 47. 139
Found - 4' W. O. shows old blaze, center rotted, no scribe.
Also find group of rocks under surface and E. W. Fence.
A.B. Rice states the W.O. is original BT., Also checks Coles
position by traverse. -REN No. 110
I set 1" I.P. with Brass Cap marked County Surveyor's Office, 1954,
N.E. Cor. DLC 47 T29S R6W.
Blaze & Scribe 18" B.O. N. 84° E. 24.6 ft. CL 47 N.E. Cor. CS BT.
Blaze & Scribe 18" B.O. N. $68\frac{1}{2}^{\circ}$ W. 26.8 ft. CL 47 N.E. Cor. CS BT.

$\frac{1}{4}$ Section Corner to Sections 4 & 5. 140
Found - 4"X4" Sq. Stake, See Page 17 of notes in file, at fence corner.
Set 1" I.P. with Brass Cap marked $\frac{1}{4}$ S $5\frac{1}{4}$ NW. T29S R6W County Surveyor's Off., 1954.
From Which: 24" R. Fir bears N. 24° E. 29.0 ft. Bark blazed $\frac{1}{4}$ S4 CS BT.
16" R. Fir bears N. $85\frac{1}{4}^{\circ}$ W. 24.5 ft. Bark blazed $\frac{1}{4}$ S5 CS BT.

James W. Byron, Deputy County Surveyor
R. Irving
J. Fee
Dec. 23, 1954 - Filed 12/10/57 - INCOMPLETE SURVEY
C. S. File No. 49/40

RE-RENEWED, SEE CORNER NO #258