

Douglas County Surveyor's Record of
Government Corners Renewed

T. 29 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy Co. Surveyor
Dale McFarland and John Powell
February 1962
C. S. File No. 49/139

C.S. File No. 49/64

C. S. File No. 49/139

SECS. 41/24
FOR EARLIER
BOYER CHANGE
REPORT
1/63
S.P.

March and April 1962 C.S. 49/139

Sec. Cor. 1 - 12, T29-6W. & Secs. 6 - 7, T29-5W. 156
Found - Orig. 8", now 14" B.Oak S.55°E. 13.9 ft., previously opened,
shows good reverse scribing on old chip "R".
Orig. 18", now 36" Laurel Snag N.87°E. 66.0 ft.
Orig. 12", now 20" W.Oak N.89°W. 23.1 ft.
Orig. S.W. BT. not found.
Set - Brass Cap at Cor. Mkd: Co. Surveyor's

S 1	S 6
S 12	S 7

 T29S
Office, 1962 R6W
New BT's: 8" W.Oak bears S.79°W. 52.0 ft. scribed S12 T29S R6W CS BT.
11" W.Oak bears N.58°E. 74.5 ft. scribed S 6 T29S R5W CS BT.
10" W.Oak bears S.69°E. 18.2 ft. scribed S 7 T29S R5W CS BT.

fd 8/30
M 110-60

Section Corner to Secs. 13 & 24, T29-6W. & Sec.s 18 & 19, T29-5W. 157
Found - Orig. 12", now 44" B.Oak opened years ago, center rotted,
S.85°W. 45.0 ft., not 56.1 ft.
Find 1" I.P. at corner. - Ren. # 84
Remains of N.E. & N.W. Orig. BT's., show axe work, check record.
Note - N.S. & Fence to West, Corner bears S.25°E. 4 ft.
New BT's: 40" B.Oak bears N.02°E. 72.8 ft. scribed S18 T29S R5W CS BT.
(This BT. previously bark scribed)
48" B.Oak bears N.82°W.75.0 ft. previously scribed.
44" B.Oak, O.B.T. S.85°W. 45.0 ft. We scribed CS BT.
(previously bark scribed)
W.Oak bears S.15°E. 134.4 ft. We scribe CS BT, prev.scribed.

RE-RENEWED, SEE CORNER NO # 239

$\frac{1}{4}$ Corner to Sections 29 and 30. 158
Found - Both Orig. BT's. Orig: 7", now 14" Laurel S.63°W. 16.5 ft. We
open & find good scribing "B". Orig. 12", Now 20" Laurel N.77°E.
17.8 ft., shows good scars.
Note - Corner lies in center of Log. Road. We drive $\frac{3}{4}$ " I. Rod at corner
& flush with road surface.
New BT: 14" R.Fir bears N.71°W. 26.4 ft. scribed $\frac{1}{4}$ S30 CS BT.

Fd ok
3/87
B. Holt
M 104-3

$\frac{1}{4}$ Corner to Section 30 and 31. 159
Found - Both Orig. BT's., now snags. We open, now 22" Fir Snag S.20°W.
21.1 ft. & find good scribing "BT". We do not find Corner Stone.
Set - Brass Cap at Cor. Mkd: County Surveyor's

$\frac{1}{4}$ S30	T29S R6W
S31	

Office, 1962
New BT: 4" Laurel bears S.17°E. 31.3 ft. scribed $\frac{1}{4}$ S31 CS BT.
8" Laurel N.26°E. 103.0 ft. scribed $\frac{1}{4}$ S30 CS BT.

$\frac{1}{4}$ Corner to Sections 20 and 29. 160
Found - 1 $\frac{1}{2}$ " I. Pipe & Both BT's. (as recorded by Cole. Each BT., now
Stump. N.W. BT. shows good bark scribing "BT". See Cor. #39
New BT's: 28" Laurel bears S.16°E. 41.0 ft. scribed $\frac{1}{4}$ S29 CS BT. Fnd. O.K. by
20" R.Fir bears S.79°W. 26.2 ft. scribed $\frac{1}{4}$ S29 CS BT. Rbt. DEAN
JAN. 1962 M 09-71

$\frac{1}{4}$ Corner to Sections 19 and 30. 161
Found - Stone, broken in several pieces; with scribed Fir guard stake at cor.
N. E. Madrone has been cut down, fd. scribing on same "1 $\frac{1}{2}$ ". - Ren #59
S. E. Madrone still standing, but rotted out on S. Side.
Set - Brass Cap at Cor. Mkd: County Surveyor's

$\frac{1}{4}$ S19	T29S R6W
S30	

Office, 1962
New BT's: 12" Fir S.30°W. 49.0 ft. mkd: $\frac{1}{4}$ S30 CS BT. FD OK PER JOHN STONE
16" Laurel N.80°E. 50.5 ft. Mkd: $\frac{1}{4}$ S19 CS BT. 12/89 M 101-73

$\frac{1}{4}$ Corner to Sec. 30, T29-6W. & Sec. 25, T29-7W. 162
Found - Stone at Cor. & in place as recorded except We do find + on top
& $\frac{1}{2}$ Mkd. on East Face, not West face.
Both BT's. as recorded by B.B.I., now stumps, down & out of place. REN. #191
Set - Brass Cap alongside corner stone & Mkd: County Surveyor's Office, 1962

$\frac{1}{4}$ R7W	S25/S30	R6W	T29S
-------------------	---------	-----	------

New BT's: 21" R.Fir bears N.49°E. 71.5 ft. scribed $\frac{1}{4}$ S30 CS BT.
8" R.Fir bears N.29°W. 116.1 ft. scribed $\frac{1}{4}$ S25 CS BT.