

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 29 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21887

J.M. Powell  
& Crew  
C.S. File  
No.  
49/139

1/4 Corner to Sections 11 and 14. 213  
Found - No trace of 1" Iron Pipe due to new Yew Wood Corner Post at  
fence corner which falls directly at corner point, See Ren. #16.  
8", now 10" W. Oak, S. 23° E. 12.8 ft., shows good scar.  
8", now 10" W. Oak N. 35 3/4° W. 27.1 ft., shows good scar.  
Set - Brass Cap on South Side of Fence Post Mkd: T 29 S R 6 W  
County Surveyor's Office 1/4 S 11  
1971 S 14

This corner falls at fence corner, fences running E-W-N.  
Bearing Trees O. K. and Tagged. 2/8/71

J. M. Powell  
& Crew  
C.S. File  
No.  
49/139

1/4 Corner to Sections 21 and 22. 214  
Found - Old Scribed Post, scribed "1/4 S 21 SCS", See Ren. #47.  
16", now 16" D. Fir, N. 73° E. 9.5 ft., shows good scar.  
20", now 22" D. Fir, S. 62° W. 34.0 ft., shows good scar.  
After good search with metal finder, did not find Iron Pipe. #245  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 6 W  
Office, 1971 1/4 S 21 | S 22

Bearing Trees O. K. and Tagged. 2/12/71

J. M. Powell  
& Crew  
C.S. File  
No. 49/139

SE Corner of DLC #45 215  
Found - 14" Maple now 20", S, 20 W. 5.3 ft., Scribe visible  
"45 29S., R6W". Rotten face. See Ren. #7.  
16" Maple, now 22", N. 72 W., 47.5 ft. Shows scar.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 29 S R 6 W  
Office, 1971 S.E.  
DLC 45

New BT: 10" Cedar S. 7 W., 58.6 ft. Scribed "S.E. DLC 45 CS BT"  
Note: This cor. falls approx. 70.0 ft. West of Willis Creek. 4/19/71

Mr. Victor  
McLind  
C.S File  
No. 55/196  
M. 42 - 22

S. W. Corner D. L. C. No. 45 216  
Found - 48" Fir on ground with blaze and "X" as per Cain Renewal, 1915.  
Established corner N 70° E, 11 links (7.3 ft) from hole in ground  
where fir stood. See Ren. #8.  
Set - 5/8" iron rod at corner.  
New BT's - 13" D. Fir, N 76° E, 15.2 ft.  
9" D. Fir, S 23° W, 25.6 ft.  
Both BT's scribed "C45 BT".

Note: The West line of DLC 45, as controlled by this corner, fits closely  
an old fence running North from S. line of Sec. 21. Position  
of corner falls within 3 ft. of position calculated using  
Proportioned distances and rotated bearings. 4/1/71

Victor M. McLind  
Willis Ck. Prop.  
July, 1971 M 42 - 33

1/4 Corner between Sections 9 and 10. 217  
Found - Remains of 24" B. Oak & Stump Hole S. 65° W. 587.0 ft.  
10", now 22" Maple, with scar, N. 23° W. 166.0 ft. See Ren. #91.  
Set - 5/8" Iron Rod buried 1.0 ft. deep in open field.  
Centerline of County Road No. 88 bears West 150 feet.

Section Corner to Sections 9 - 10 - 15 - 16. 218  
No evidence of corner found. I renewed corner by double prop.  
measurement from corners shown.  
Set - 5/8" Iron Rod in Mound of Stone. #275  
Blazed & Scribed New Bearing Trees, as follows:  
12" Alder scribed "T29S R6W S10 BT" bears N. 48° E. 158.1 ft.  
10" B. Oak scribed "T29S R6W S 9 BT" bears N. 74° W. 157.2 ft.  
26" B Oak scribed "T29S R6W S15 BT" bears S. 42° E. 255.0 ft.

1/4 Corner to Sections 15 and 16. 219  
No evidence of corner found. FD OK PER DEBROOT  
FEB. 1987, M 103-47  
Set - 5/8" Iron Rod and blazed & scribed BT's., as follows:  
12" D. Fir scribed "T29S R6W 1/4 S16 BT" bears S. 5° W. 27.5 ft.  
12" Maple scribed "T29S R6W 1/4 S15 BT" bears S. 87° E. 46.5 ft.