

Douglas County Surveyor's Record of
Government Corners Renewed

29 T. S. 6 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 21881

Doug. Co.
Surveyors Off.
Gary Langlitz
Peter Earle
Feb. 20, 21,
1974
C.S. 56/43

CC corner, Secs. 31 and 31 only.
Found corner in good condition. Ren. #119
I Do Not Renew

*Amud. CC.
SEE CORNER REPORT
H. JOHNSTONE
C.S. 63/104*

225

Corner lies in bottom of draw, course west, approx. 200' south of a fairly new logging road.

2/20/74

226

Section cor. for 5 and 4 only, T.30-6.
Found - 1958 Cadastral brass cap properly mkd., laying on the ground.
I reset - Same brass cap in its original position, from which:
44" D.Fir, bears S.66°E., 28.4 ft. with a burned blaze, previously opened.
36" D.Fir snag, bears S.7°W., 16.5 ft. with a burned blaze previously opened.
18" now 20" red cedar, bears S.16½°E., 71.3 ft. scribing T30S R6W S4 BT plainly visible.
43" D.Fir, now a stump, bears S.39½°W., 62.0 ft.
New BT - 12" Grand Fir, bears N.48°W., 35.2 ft. scribed T29S R6W S32 CS BT.

Note - Upon resetting brass cap, I find a 1½" truck axle with 8" diameter wheel bolt flange attached, driven flush with the ground, bearing north 0.8 ft. from the corner point.
Corner lies approx. 80 ft. west of a dirt road.

Don E. Garrett
for Jimmie L.
Johnson
March 1974
M 53 - 13A&B

1/4 Corner for Sec. 1 and Sec. 36, T.28-6
Set - 1" Iron pipe.
BT's - 9" W.oak, bears S.13°45'W., 26.0 ft. scribed 1/4 S1 BT
9" W.Oak, bears N.17°E., 26.2 ft. scribed 1/4 S36 BT.

227

228

Center 1/4 Corner for Sec. 1
Set - 1" Iron pipe.

March 1974

M. Lenora Ladig
Clell G Goodwin
Gary L Langlitz
A Vic. Cangie
10/21/75
CS57/36

1/4 corner to Sec. 5 & 6 Ren. # 196
Found- Iron pipe 3ft. long, 1 1/2" in diam. 28" in the ground. Marked: R S404
From Which: an Orig. 12" now 24" B.Oak bears N 30°W., 47.5 ft.
An orig. 18" now 20: fir bears N 62°E, 62.7 ft.
New: 10" fir bears S65°W., 78.3 ft. Scribed 1/4 S 6 CSBT in double blaze.
Compass declination 20°E. 10/21/75

229

230

1/4 Corner for Secs. 32 and 33.
Found - A 30" Fir stump with illegible bark scribing bearing N.37°W., 34.3 ft.
A 47" Fir stump uprooted and tree removed. Stump shows visible "BT" and other illegible scribing on unhealed blaze. Also find old "BT" tag nailed on stump. Stump bears S.32°E., 25.1 ft.
A 28" x 2 1/2" I.P. with brass cap stamped properly. It was laying on top of ground over corner point. (disturbed by logging).
Set - At corner point we replace found 1958 brass cap and stamp "CS 1976" on brass cap.
New BT's-A 12" D.Fir, bears S.25°E., 147.8 ft. marked "1/4 S33 CS BT" in a double blaze.
An 8" D.Fir, bears S.87°W., 104.2 ft. marked "1/4 S32 CS BT" in a double blaze.

11/10/76

231

1/4 Corner for Secs. 33 and 34.
Found - The remains of an orig. 30" now 42" Fir now windfall, with scribing "S" visible on unhealed rotted face, bears N.30°W., 11.2 ft.
1958 BLM BT, a 45" Fir, now a stump, with bark scribing "1/4 S34 BT" visible. Bears S.53°E., 46.2 ft.
1958 BLM BT, a 37" Fir, now a windfall, with scribing "1/4 S33 BT" visible., bears S.57°W., 33.7 ft.
There is no evidence remaining of the orig. NE Chinquapin BT or the 1958 BLM Brass Cap.

Set - At the corner point as determined at record bearing and distance from above described trees WE SET a 1" x 30" I.P. 26" in the ground on a steep North slope along the West edge of a cat trail, with Brass Cap attached marked: Douglas Co. Surveyor T29S R6W 1976 S33/S34

1/4

Gary L. Langlitz, Doug. Co. Surveyors Office
A.V. Cangie
M. Tompkins
Witness: R. Mosher, BLM
Nov. 10, 1976
C.S. 59/26