

Douglas County Surveyor's Record of  
Government Corners Renewed

T 29

T. S. R 6

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE., 91881

237

South 1/16 for Sec. 25 and Sec. 30 of T29-5

Found - A 1" I.P. firmly set extending 14" above ground with brass cap attached marked: County Surveyors Office T29S S1/16 R6W S25 S30 R5W 1969. Ren. See M37-20.

A 9" now 11" D. Fir, alive with well healed double blaze bears S.83°E., 36.7 ft.

An 11" now 12" D. Fir alive with well healed double blaze, bears N.43°W., 10.5 ft. (Rec. per 1969 survey N.43°W., 11.2 ft.)

This 1969 corner location is now wrong due to the recent identification of the orig. corner common to sections 19 and 30, T29S R5W and Sections 24 and 25 T29S R6W. We therefore RESET this corner by survey at it's proper proportionate location as follows:

We remove the 1969 monument and set it at the true corner point, extending 6" above ground. We add the markings "Reset 1977" to the brass cap.

At the 1969 corner location, we set a 5/8" x 30" I. Rod, with alum. cap attached marked: "Douglas Co. Surveyor 1977".

The 1969 bearing trees are now located as follows:

An 11" D. Fir, condition noted above, bears S.87°E., 40.7 ft.

A 12" D. Fir condition noted above, bears N.21 1/2°W., 9.7 ft.

A 5/8" Iron rod with alum. cap attached, marked as noted above bears N.73°E., 3.89 ft.

A N-S fence bears East approx. 13.5 ft.

12/8/77

238

1/4 Corner Sec. 25 and Sec. 30 of T29-5

Found - A 1969 County Surveyors brass cap properly marked, extending 12" above ground on a 1" I.P. Ren. #206

A 22" now 24" D. Fir alive with well healed double blaze bears S.84°E., 5.5 ft. (Rec. per 1969 survey M37-20, S.99°E., 5.5 ft.)

A 12" now 14" D. Fir alive with well healed double blaze bears N.83°W., 32.9 ft.

We find no trace of the original corner.

This 1969 corner location is now wrong due to the recent recovery of the original corner common to Sections 19 and 30, T29S, R5W, and Sections 24 and 25, T29S R6W. We therefore RESET this corner at it's proper proportionate location by survey as follows:

We remove the 1969 monument and set it at the true corner point, extending 4" above ground. We add the markings "Reset 1977" to the brass cap.

At the 1969 corner location, we set a 5/8" x 30" I. Rod with alum. cap attached marked "Douglas Co. Surveyor 1977".

The 1969 bearing trees are now located from the 1977 corner as follows:

A 24" D. Fir condition noted above bears N.82 1/2°E., 12.8 ft.

A 14" D. Fir condition noted above bears N.77°W., 26.4 ft.

A 5/8" Iron rod with alum. cap attached marked as noted above bears N.74°E., 7.09 ft.

A N-S fence bears East approx. 22 ft. A small creek, course N.40°E., bears South, approx. 35 ft.

12/8/77

239

Section Corner for 13 and 24; and Secs. 18 & 19 of T29-5

Found - A 1" x 27" Iron pipe. Ren. #157 and M 37 - 20

A 12" now 44" B. Oak bears S.85°W., 46.1 ft. (Rec. 56.1 ft.) with a chopped open blaze, 12" center rotted away and another well healed double blaze at the left side of chopping.

A 40" B. Oak bears N.0 1/2°E., 72.8 ft. with scribe marks visible in an almost healed double blaze.

A 48" B. Oak bears N.82°W., 75.0 ft. with a well healed blaze.

A 24" W. Oak bears S.15°E., 134.4 ft. with a well healed blaze.

Set - A 1" x 36" Ironpipe with brass cap set 6" above ground marked: "Douglas County Surveyor" 1977

R	T 29 S	R
6	S 13 S 18	5
W	S 24 S 19	W

I set the I.P. at the N. edge of the brass cap

No new accessories. Corner is at S.W. edge of a 7 ft. high fencepost, 8 ft. N.W. of a fence corner to the west and N-S.

12/14/77

Douglas County Surveyors Office

Gary L. Langlitz

Peter L. Earle

Frank Silagy

Dec. 8, 1977

C.S. 59/42

R. B. Kimberling, Doug. Co.

Surveyors Office

F. C. Silagy

December 14, 1977

C.S. 59/42