

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 29 T. S. R 6 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE., 91881

R. B. Kimberling
F. C. Silagy
Doug. County Surveyors Office
December 12, 1977
C.S. 59/42

244

Section Corner for Secs. 25 and 36; and Secs. 30 & 31 of T29-5
 Found - A 3/4" x 34" Galv. I.P. 25" in the ground. Ren. #183 5/77
 A 10" now 38" W. Fir bears S.60°W., 11.2 ft. with visible
 scribing "S31--S in opened blaze. (OBT).
 A 36" now 40" D. Fir bears S.73 1/4°E., 55.5 ft. (Rec. 54.1 ft.)
 with visible bark scribing "T29S R5W S31 CS" and carved "K"
 on NW face.
 A 36" now 34" D. Fir bears N.67 1/2°W., 42.2 ft. with visible
 bark scribing "T29S R6W S25 CS BT"
 A 6" now 8" W. Fir bears N.7°E., 15.5 ft. with a well healed
 double blaze.
 A 9" now 14" W. Fir bears S.78 1/2°E. (Rec. S.81°E.) 26.2 ft. with
 a well healed double blaze.
 Set - A 1" x 36" I.P. with brass cap set 5" above ground and marked:
 "Douglas County Surveyor"
 R T 29 S Set 3/4" x 34" I.P. at
 6 S 25 S 30 north edge of brass cap
 W S 36 S 31 5
 1977 W 24" in the ground.

No new accessories. Corner is south 1.2 ft. of an E-W fence, due west 64.2' of a 30" Fir stump which is a fence corner, fence to north and E-W and the SW cor. of clearcut unit.

12/12/77

245

1/4 Corner for Secs. 21 and 22.
 Found - a 1" I.P. with a 1971 County Brass cap set 14" above ground
 properly marked. Ren. #214
 A 6" x 6" Cedar post is laying alongside brass cap with visible
 scribing "S C S" on one face.
 A 14" now 15" Fir bears N.76°E., 9.8 ft. (Rec. N.73°, 9.5 ft.)
 with a well healed double blaze.
 A 15" now 24" Fir stump is partly uprooted, orig. position approx.
 S.62°W., 34.0 ft. with visible reverse scribing "S21 CS" looking
 back from rotted center of stump.
 New BT - A 18" D. Fir bears S.3°W., 16.2 ft. with scribed "1/4 S21 CS BT"
 in double blaze.
 Corner is 35 ft. north of BLM road.

1/4/78

246

1/4 Corner for Sec. 27 only. East boundary.
 Found - 1958 Cadastral Brass cap and I.P.
 38" Fir, S.30°W., 28.4 ft. See Renewals #78 and 208
 50" Fir, S.10°W., 17.2 ft.
 14" Maple N.53°W., 53.2 ft.

No new monument or accessories.
 Corner is 119.72 ft. , N.1°02'24" E. of 1/4 cor. sec. 26 only.

247

1/4 Corner for Sec. 26 only. West boundary.
 At midpoint SET - 5/8" x 30" Iron rodd and alum. cap.
 BT's - 8" Yew N.86°E., 28.5 ft.
 10" Cedar, S.7°W., 21.8 ft.
 Corner is 119.72 ft. south of 1/4 corner for sec. 27. bearing N.1°02'24"E.

248

1/4 Corner for sections 34 and 35.
 At midpoint SET - 5/8" x 30" Iron rod and alum. cap.
 BT's - 18" Fir, S.43°W., 57.6 ft. See Ren. #122 and 1961 BLM
 12" Fir N.54°E., 153.8 f. Renewal pg. 12842
 Iron rod at improperly set 1/4 corner bears N.6 1/2°W., 30.1 ft.

249

Center 1/4 Corner for Sec. 25.
 Found - 3/4" I.P. Not of record
 8" Cedar, S.55°E., 16.9 ft.
 6" Cedar, S.88°W., 12.0 ft. SEE 1977 BLM Admin. Survey
IN GIS FILE
 No new monument or accessories.

1/4 Corner for

R. B. Kimberling
F. C. Silagy
Doug. Co. Surveyors
Office
Jan. 4, 1978
C.S. 59/46

Howard Johnstone
For: Roseburg Lumber Company
April 1978
R M 3 - 12

RE-RENEWED SEE CORNER NO. #257